

Ziegelei 1 D-72336 Balingen E-Mail: info@kern-sohn.com Phone: +49-[0]7433-9933-0 Fax: +49-[0]7433-9933-149 Internet: www.kern-sohn.com

Operating and Installation Instructions Display device

KERN KFT-TM

Version 1.0 09/2016 GB



KFT-TM -BA-e-1610



KERN KFT-TM

Version 1.0 09/2016 Operating and Installation Instructions Display device

Contents

| 1 | TECHNICAL DATA |
|---|--|
| 2 | DECLARATION OF CONFORMITY5 |
| 3 | APPLIANCE OVERVIEW |
| 3.1 | Keyboard overview |
| 3.2 | Display overview (start screen "Weighing mode")9 |
| 4 | BASIC INFORMATION (GENERAL) 10 |
| 4.1 | Proper use 10 |
| 4.2 | Improper Use 10 |
| 4.3 | Warranty10 |
| 4.4 | Monitoring of Test Resources11 |
| 5 | BASIC SAFETY PRECAUTIONS 11 |
| | |
| 5.1 | Pay attention to the instructions in the Operation Manual11 |
| 5.1 5.2 | Pay attention to the instructions in the Operation Manual |
| - | |
| 5.2 | Personnel training |
| 5.2 6 | Personnel training |
| 5.2 6 6.1 | Personnel training 11 TRANSPORT AND STORAGE 11 Testing upon acceptance 11 |
| 5.2 6 6.1 6.2 | Personnel training 11 TRANSPORT AND STORAGE 11 Testing upon acceptance 11 Packaging / return transport 11 |
| 5.266.16.27 | Personnel training 11 TRANSPORT AND STORAGE 11 Testing upon acceptance 11 Packaging / return transport 11 UNPACKING, SETUP AND COMMISSIONING 12 |
| 5.2 6 6.1 6.2 7 7.1 | Personnel training 11 TRANSPORT AND STORAGE 11 Testing upon acceptance 11 Packaging / return transport 11 UNPACKING, SETUP AND COMMISSIONING 12 Installation Site, Location of Use 12 |
| 5.2 6 6.1 6.2 7 7.1 7.2 | Personnel training 11 TRANSPORT AND STORAGE 11 Testing upon acceptance 11 Packaging / return transport 11 UNPACKING, SETUP AND COMMISSIONING 12 Installation Site, Location of Use 12 Unpacking, inspection and placing 12 |

| 7.6 | Commissioning | |
|--------------|--|----|
| - | | |
| 7.6. 7.6. | | |
| | | |
| 7.7 F | Peripheral equipment | 16 |
| | Adjustment | |
| | ustment with external weight | |
| 7.8. | | |
| 8 E | BASIC OPERATION <weighing></weighing> | 19 |
| 8.1 V | Weighing | 19 |
| 8.1. | .1 Simple weighing | 19 |
| 8.2 \$ | Set to zero/return to zero | 20 |
| 83 / | Weighing with tare | 21 |
| 8.3 | | |
| 8.3 | | |
| 8.3 | | |
| | | |
| 9 3 | SETUP MENU | 23 |
| 9.1 (| Call up menu and change settings | 23 |
| 9.2 0 | Overview <technical setup=""></technical> | 24 |
| 9.3 (| Overview <operator setup=""></operator> | 27 |
| 9.4 C | Description of individual functions | |
| 9.4. | | |
| 9.4. | .2 Serial interface RS 232 | 28 |
| 10 | APPLICATION SETTINGS | 31 |
| 10.1 | Parts counting | 30 |
| 10.1 | | |
| 10. | - 1 | |
| 10. | | |
| | | |
| 10.2 | Tolerance weighing | |
| 10.2 | 0 0 11 | |
| 10.2 | | |
| 10.2 | 2.3 Save/retrieve articles in the database | 49 |
| 10.3 | Formulation | |
| 10.3 | 3.1 Creating a recipe in the database | 51 |
| 10.4 | TAKE OFF | |
| 10.4 | | |
| 10.4 | | |
| 10.5 | Fill to target | 60 |
| 10.6 | Classification | 62 |
| 40 - | Tatalian | |
| 10.7 | Totalization | |

| 11 | SERVICING, MAINTENANCE, DISPOSAL | 68 |
|------|--|----|
| 12 | TROUBLESHOOTING / ERROR MESSAGES | 69 |
| 13 | INSTALLING DISPLAY UNIT / WEIGHING BRIDGE | 70 |
| 13.1 | TECHNICAL DATA | 70 |
| 13.2 | WEIGHING SYSTEM DESIGN | 70 |
| 13.3 | How to connect the platform | 71 |
| □ D | isconnect the display unit from the power supply | 71 |
| | older the individual leads of the load cell cable onto the circuit board. Anzeigegerät urieren | 71 |
| 13.4 | Configure display unit | 71 |

1 Technical data

| KERN | KFT-TM |
|------------------------------------|---|
| Display | 6 - digit |
| Resolution (non verified) | 30.000 |
| Weighing ranges | 2 |
| Divisions | 1,2,5,10n |
| Weighing Units | g, kg, lb, oz |
| Functions | Stückzählen, Toleranzwägen, Take off, Rezeptieren, Fill to Target, Klassifizierung, Summieren, |
| Display | LCD Touch, with back lighting |
| DMS weighing cells | 80-1200 Ω. Max. 8 item per 350 Ω; Sensitivity 2-3 mV/V |
| Range calibration | We recommend ≥ 50 % max. |
| Electric Supply | Input voltage 110 V – 230 V AC |
| Electric Supply | Power pack secondary voltage 12V, 2500mA |
| Housing | 252 x 152 x 134 mm |
| Operating temperature | -10°C – 40°C |
| Weight kg (net) | 1 kg |
| Rechargeable battery | Operating time (with back lighting) 7 h |
| (optional) | Charge time 12 h |
| Interface | 2 x RS 232 2 x USB Ethernet |
| Support base incl. wall bracket | Standard |
| User language selectable | German, English, French, Italian, Spanish |

2 Declaration of conformity

The current EC/EU Conformity declaration can be found online in:



3 Appliance overview



| Pos. | Designation | Pos. | Designation |
|------|--------------|------|-------------------------------------|
| 1 | Touch screen | 3 | Status display |
| 2 | Keyboard | 4 | Rechargeable battery status display |

Position of battery compartment:



Connections / interfaces:



| Pos. | Designation | Pos. | Designation |
|------|--------------------------|------|----------------------------------|
| 5 | Connector for AC adapter | 8 | Input connection load cell cable |
| 6 | Serial interfaces RS 232 | 9 | USB connections |
| 7 | Ethernet | | |

3.1 Keyboard overview



| Button | Name | Explanation |
|-----------|-----------------|---|
| ON OFF | ON/OFF | Switch machine on/off |
| | Home | Back to start screen |
| F | Function key | Invoke the menu <operator setup="" technical=""></operator> |
| TARE | Taring | Tare balance |
| →0← | Zeroing | Set balance to zero |



Do not operate touch screen with pointed or sharp objects!

This could damage the touch screen.

3.2 Display overview (start screen "Weighing mode")



Pos. Designation

- 1 Date/time
- 2 Maximum load
- 3 Readability
- 4 Stability display
- 5 Indicator "zero display"
- 6 Weight unit
- 7 Settings
- 8 Output data via interface, e.g. to a printer
- 9 Switching Off
- 10 Application selection (adjustable, see chap. 9.3)
- 11 Currently available buttons (zero, tare, PRE-tare)
- 12 Capacity display
- 13 Weight value
- 14 Back to start screen

4 Basic Information (General)

4.1 Proper use

The balance you purchased is intended to determine the weighing value of material to be weighed. It is intended to be used as a "non-automatic balance", i.e. the material to be weighed is manually and carefully placed in the centre of the weighing pan. As soon as a stable weighing value is reached the weighing value can be read.

4.2 Improper Use

Do not use balance for dynamic add-on weighing procedures, if small amounts of goods to be weighed are removed or added. The "stability compensation" installed in the balance may result in displaying an incorrect measuring value! (Example: Slowly draining fluids from a container on the balance.)

Do not leave permanent load on the weighing pan. This may damage the measuring system.

Impacts and overloading exceeding the stated maximum load (max) of the balance, minus a possibly existing tare load, must be strictly avoided. Balance may be damage by this.

Never operate balance in explosive environment. The serial version is not explosion protected.

The structure of the balance may not be modified. This may lead to incorrect weighing results, safety-related faults and destruction of the balance.

The balance may only be used according to the described conditions. Other areas of use must be released by KERN in writing.

4.3 Warranty

Warranty claims shall be voided in case

- Our conditions in the operation manual are ignored
- The appliance is used outside the described uses
- The appliance is modified or opened
- Mechanical damage or damage by media, liquids, natural wear and tear
- The appliance is improperly set up or incorrectly electrically connected
- The measuring system is overloaded

English

4.4 Monitoring of Test Resources

In the framework of quality assurance the measuring-related properties of the balance and, if applicable, the testing weight, must be checked regularly. The responsible user must define a suitable interval as well as type and scope of this test. Information is available on KERN's home page (<u>www.kern-sohn.com</u> with regard to the monitoring of balance test substances and the test weights required for this. In KERN's accredited DKD calibration laboratory test weights and balances may be calibrated (return to the national standard) fast and at moderate cost.

5 Basic Safety Precautions

5.1 Pay attention to the instructions in the Operation Manual



⇒ Carefully read this operation manual before setup and commissioning, even if you are already familiar with KERN balances.

5.2 Personnel training

The weighing balance may only be operated and maintained by trained staff.

6 Transport and storage

6.1 Testing upon acceptance

When receiving the appliance, please check packaging immediately, and the appliance itself when unpacking for possible visible damage.

6.2 Packaging / return transport



- ⇒ Keep all parts of the original packaging for a possibly required return.
- \Rightarrow Only use original packaging for returning.
- ⇒ Prior to dispatch disconnect all cables and remove loose/mobile parts.
- ⇒ Reattach possibly supplied transport securing devices.
- Secure all parts such as the glass wind screen, the weighing pan, power unit etc. against shifting and damage.

7 Unpacking, Setup and Commissioning

7.1 Installation Site, Location of Use

The balances are designed in a way that reliable weighing results are achieved in common conditions of use.

You will work accurately and fast, if you select the right location for your balance.

Therefore, observe the following for the installation site:

- Place the balance on a firm, level surface;
- Avoid extreme heat as well as temperature fluctuation caused by installing next to a radiator or in the direct sunlight;
- Protect the balance against direct draughts due to open windows and doors;
- Avoid jarring during weighing;
- Protect the balance against high humidity, vapours and dust;
- Do not expose the device to extreme dampness for longer periods of time. Nonpermitted condensation (condensation of air humidity on the appliance) may occur if a cold appliance is taken to a considerably warmer environment. In this case, acclimatize the disconnected appliance for ca. 2 hours at room temperature.
- Avoid static charge of goods to be weighed or weighing container.

If electro-magnetic fields or static charge occur, or if the power supply is unstable major deviations on the display (incorrect weighing results) are possible. In that case, the location must be changed.

7.2 Unpacking, inspection and placing

Remove device and accessories carefully from packaging, remove packaging material and place device at the planned work place. Verify that there has been no damage and that all packing items are present.

Scope of delivery / serial accessories:

- Display device, see chap. 2
- Mains adapter
- Support base incl. wall bracket
- Operating manual
- ⇒ Place weighing pan on the rubber elements

7.3 Placing

Mount the display unit in a way that facilitates operation and where it is easy to see.



Usage with support base (KFB-TAM only)

Usage with wall mount (KFB-TAM only)



7.4 Mains connection



Select a country-specific power plug and insert it in the power unit.

Check, whether the voltage acceptance on the scales is set correctly. Do not connect the scales to the power grid unless the information on the scales (sticker) matches the local mains voltage.

Only use KERN original mains adapter. Using other makes requires consent by KERN.



Important:

- Before starting your weighing balance, check the mains cable for damage.
- > Ensure that the power unit does not come into contact with liquids.
- > Ensure access to power plug at all times.

7.5 Rechargeable battery operation

Before the first use, the battery should be charged by connecting it to the mains power supply for at least 12 hours.

The LED display informs you during loading about the loading status of the rechargeable battery.

- red: Charging storage battery
- green: Rechargeable battery completely reloaded

7.6 Commissioning

In order to obtain exact results with the electronic balances, your balance

must have reached the operating temperature (see warming up time chap. 1). During this warming up time the balance must be connected to the power supply (mains, accumulator or battery).

The accuracy of the balance depends on the local acceleration of gravity. Strictly observe hints in chapter Adjustment.

7.6.1 Switch on balance

- ⇒ Press ON/OFF key until you hear an acoustic signal. The status indicator lights up.
- \Rightarrow Wait until the start screen appears.



The first time you switch the balance on, "Weighing" will appear as the start screen. When you switch on next time, the start-up screen will appear with the last application used prior to switching off.

7.6.2 Switch off balance


➡ To turn off the display, press the **ON/OFF**-key shortly. During this process the weighing balance will be moving into ready mode. The status indicator stays on.

The weighing balance will be ready for operation immediately after activation without requiring any time to warm up.

- Press the ON / OFF key to switch off the balance. The status indicator goes off.
 or
- A Switch off balance> The status indicator goes off.

7.6.3 Selecting user language

The display is set to English upon delivery. For other languages, see chap. 9.3 <Operator setup → Display → language>.



7.7 Peripheral equipment

Before connecting or disconnecting of additional devices (printer, PC) to the data interface, always disconnect the balance from the power supply.

With your balance, only use accessories and printers by KERN, as they are ideally tuned to your balance.

7.8 Adjustment

As the acceleration value due to gravity is not the same at every location on earth, each balance must be coordinated - in compliance with the underlying physical weighing principle - to the existing acceleration due to gravity at its place of location (only if the balance has not already been adjusted to the location in the factory). This adjustment process must be carried out for the first commissioning, after each change of location as well as in case of fluctuating environment temperature. To receive accurate measuring values it is also recommended to adjust the balance periodically in weighing operation.

Adjustment with external weight

- Prepare adjustment weight, see chap. 1.
 - The adjustment weight you use is dependent on the capacity of the balance. Perform adjustment as close as possible to the maximum load. Info about test weights can be found on the Internet at: <u>http://www.kern-sohn.com</u>
 - Observe stable environmental conditions. A warming up time (see chapter 1) is required for stabilization.

Procedure:


- ⇒ Call up <Technical setup>, see chap. 9
- \Rightarrow Select <Adjustment> and follow the instructions on the display.



Unload the balance. Ensure that there are no objects on the weighing pan. Tap <Continue>.



Place the adjustment weight at the centre of the weighing pan. Tap <Continue>.




7.8.1 Adjustment using gravitational constant

The balance can be adjusted to the installation location via the gravitational constant. Further adjustment with an external weight is then no longer required after setting up on site.

Procedure:


- ⇔ Open <Techncial setup>, see chap. 9
- Select <Weighing ➡ gravitational constant>. ⇔



L

field.






in the display. \Rightarrow Back to the weighing mode press \square or repeatedly tap

8 Basic operation <Weighing>


The sequence of a simple weighing process is described in the chapter on Weighing below. Apart from the work steps described there (simple weighing, reset to zero, taring) the weighing balance offers additional options for adapting the "Weighing" application to your requirements. For the settings available see chap. 9.2

8.1 Weighing

The start screen <Weighing> appears automatically when you first switch on. If the balance was already turned on, the application, in which the balance was last used appears.



8.1.1 Simple weighing



Depending on the setting in <Technical setup
Autoprint activated/deactivated> the weighing value can be output either automatically by connecting an optional printer or

after tapping

Print example (KERN YKB-01N, Settings <Printing format> see chap. 9.4.2

| Short print format without date/time | Short print format date/time | Long print format with date/time | | | |
|--------------------------------------|------------------------------|----------------------------------|--------------------------|--|-------|
| N: 5.000kg | 01.09.21016 N: 5.000kg | 10:57 | 01.09. N: T: N: | 21016 5.000kg 0.396kg 5.396kg | 10:57 |

All weighing data are saved automatically after pressing the PRINT key. These data records can be exported by the operator to a USB storage device, see chap. 9.2<Weighing data>.

The database allows for up to 1000 weighing results to be saved. When the capacity of the memory is exhausted, data records will be overwritten in turn, starting with the first data record.

8.2 Set to zero/return to zero

In order to obtain optimal weighing results, reset to zero the balance before weighing.

- ⇒ Unload the balance
- ⇒ The zero display appears, depending on the setting in the menu either

automatically or after pressing $\downarrow^{\rightarrow 0}$

Settings:

Automatic return to zero

You can compensate for drift behaviour of the balance with this setting.

Under <Technical setup → Weighing → Automatic Zero reset> the function can be deactivated or its limit can be determined. To open setup menu, see chap. 9



• Zeroing range

| Autom. | The set value is automatically reset to zero on switching on. |
|----------------------|--|
| Zeroing range | Possible settings 0 (deactivated), 2, 3, 4, 10, 20, 100%. |
| Manual Zero range | After pressing $\xrightarrow{\bullet 0+}$ the balance admits the zero setting to the set value. Possible settings 0 (deactivated), 2, 3, 4, 10, 20, 100%. |

⇒ The values can be set under <Technical setup ⇒ Weighing ⇒ Automatic/manual zero set range>. To open setup menu, see chap. 9

| Weighing | Weighing | | |
|---------------------------|----------------------------|--------------------------|---|
| Adjustment | Balance Type | Single-range balan | - |
| Screen Password | Partition | 2 | - |
| Serial interfa | Maximum load | 30 kg | |
| Date/time | Constant of gravitation | 9.80761 m/s ² | |
| Network | Autom. Zero return | Disabled | - |
| Database Weighing data | Autom./manual zero setting | 10% | - |
| Autoprint | Unit | kg | - |
| | Display speed | nor | - |
| | Decimal Positions | 0.00 | - |

8.3 Weighing with tare

8.3.1 Taring

1

The dead weight of any weighing container may be tared away by pressing a button, so that the following weighing procedures show the net weight of the goods to be weighed.


- \Rightarrow Put empty weighing container on the weighing pan.
- ⇒ Wait until the stabilisation indicator (►→) is displayed, then press or tap

tare / of in the display. The zero display appears. The weight of the container is now internally saved.

- ⇒ When the balance is unloaded the saved taring value is displayed with negative sign.
 - ➡ To delete the stored tare value, remove load from weighing pan and press TARE.
 - ⇒ The taring process can be repeated any number of times, e.g. when adding several components for a mixture (adding). The limit is reached when the taring range capacity (see type plate) is full.

8.3.2 Tare specification (PRE-TARE)

If the container weight is known, the tare weight can be entered numerically.



 \Rightarrow To delete the saved tare value, enter the value zero in step 2.

8.3.3 Weighing with capacity display

The capacity display moves from the left to the right and proceeds equally to the weight loaded onto the weighing balance. The full range can be achieved at maximum load.



9 Setup menu


You can set the balance according to your requirements using the menu. Here, you can change the settings of the balance and activate the functions.

9.1 Call up menu and change settings


Call up menu:

Press F or tap in the display to go to the menu selection. The menu has two levels:

- <Technical setup> Password protected
- <Operator setup> Accessible without password
- ⇒ Select Setup menu
 - <Technical setup>



<Operator setup>



| 2 | Functions Display News Autoprint Information | ✓ Parts counting ✓ Tolerance weighing ✓ Recipe mode ✓ Take off ✓ Target parts counting ✓ Classification ✓ Totalization | |
|---|--|--|--|
| | | 5 | |

The available settings will be shown

 \Rightarrow The available settings will be shown.

Change settings:

Tap on settings and make the desired changes or follow the display instructions.

Accept input with . The display returns to the previous screen.

9.2 Overview <Technical setup>

Menu <Weighing>

| Menu item | Description |
|----------------------------|---|
| Balance Type | Select single range / multiple interval / multiple range balance |
| Partition | Readability "d" |
| Maximum load | Upper limit of the weighing range "Max" |
| Constant of gravitation | Adjustment using gravitational constant, see chap. 7.8.1 |
| Autom. Zero return | see chap. 8.2. |
| Auto/man. Zeroing range | see chap. 8.2. |
| Unit | Select weighing unit |
| Display speed | This setting is used to define how quickly the weighing balance considers a measured value as stable for release. |
| Decimal Positions | Select number of decimal places |

Menu <Adjustment>

| Menu item | Description |
|------------|--|
| Adjustment | Adjustment with external weight, see chap. 0 |

Menu <Screen>

| Menu item | Description |
|-----------|-------------------------------------|
| Screen | Adjust touch screen, see chap.9.4.1 |

Menu <**Password**>

| Menu item | Description |
|-----------|--|
| Password | Change password for technical setup menu |

Menu <Serial interface>

| Menu item | Description |
|------------------|---|
| Serial interface | Activate/deactivate interface, see chap. 9.4.2 Set communication parameters, see chap. 9.4.2 |

Menu<Date/time>

| Menu item | Description |
|-----------|----------------------|
| Date/time | How to set date/time |

Menu <Network>

| Menu item | Description |
|-----------|---|
| network | Display IP address (only if balance is logged on to network) |

Menu <Database>

| Menu item | Description |
|-----------|--|
| Database | Export/import/delete database, which was populated using |
| | the control buttons |

Menu < Weighing data>

| Menu item | Description |
|---------------|---|
| Weighing data | All weighing data are saved automatically after pressing the PRINT key. |
| | The data can be exported or deleted with this function. Our optional software KERN SET 1.0 is available for viewing the data. |

Menu <Autoprint>

| Menu item | Description |
|-----------|---|
| Autoprint | Activate/deactivate automatic print function.Define output interval. |

English

9.3 Overview <Operator setup>

Menu <Functions>

| Menu item | Description |
|-----------|---|
| Functions | All functions with a tick will be shown in the applications menu. |

Menu <**Display**>

| Menu item | Description |
|-----------|--|
| Display | Set Operator language, see chap. 7.6.3Set screen brightness |

Menu <**Messages**>

| Menu item | Description |
|-----------|---|
| News | Each time a key is pressed, you will hear a short confirmation beep. This function can be activated/deactivated with a tick |

Menu <Autoprint>

| Menu item | Description | | |
|-----------|---|--|--|
| Autoprint | Application-specific settings for the automatic printing function. These menu items are only available when <autoprint> is activated.</autoprint> | | |


Menu <Information>

| Menu item | Description |
|-------------|-----------------|
| Information | Show IP address |


9.4 Description of individual functions

9.4.1 Set touch screen orientation

If the orientation of the touch-sensitive area does not match the positions of the control buttons on the display, it can be corrected by this function.



Tap **<Technical setup → Screen →** Adjustment start>.



Use a pen to touch the centre of the cross as accurately as possible.

Repeat this process for all the points.

- Be careful not to touch other areas of the display during adjustment.
 - Do not touch the display with your hand.
 - Adjustment cannot be exited.


9.4.2 Serial interface RS 232

Weighing data can be exchanged with peripheral devices (printer or PC) via the interface.

The following conditions must be met to provide successful communication between the weighing balance and an external device.

- Disconnect balance from the power supply and connect to the device interface with a suitable cable. Faultless operation requires an adequate KERN interface cable.
- The communication parameters of the RS 232 interface (baud rate, bits and parity) and the external device must be the same.

1



Weighing Serial interface 3 Adjustment Com₂ Screen Deactivated V Print Ask Password Baud rate 9600 Serial interfa. 600 Date/time Data bits 1200 Network Stop bits 2400 Database 4800 Parity Weighing data 9600 Print format Autoprint 19200 Print date and time 38400 115200 5 Appy ⇒ Select interface parameters by tapping on the pull-down menu. ⇒ Select print format <short> or <long> (Printout examples see chap. 8.1.1) ⇒ Select print date/time.

Serial interface Weighing 4 Adjustment Com2 Screen Deactivated V Print Ask Password Serial interfa... Baud rate 9600 Date/time Data bits 8 • Network Stop bits 1 -Database Disabled Parity • Weighing data Print format Autoprint Long • Print date and time 5 Accept settings using control button Apply


Selection <Ask>

KCP (core communication protocol) contains the commands that are used to control the KERN GAT balance via the interface.

The following commands are supported:

- I0 Send all implemented commands
- I1 KCP status and version
- I2 Balance data
- I3 Software version
- I5 Query SW ID number
- S Send stable value
- SI Send value immediately
- SIR Send value immediately and repeat
- Z Zeroing
- ZI Immediate zero reset
- @ Cancel (reset)
- D Display
- DW Display weight value
- K Buttons: Set configuration
- SR Send weight value for weight change
- T Taring
- MM Enter the tare value (pretare)
- TAC Delete tare
- TI Tare now
- Finish commands with CR/LF character.
 Consult the KCP manual for more inform
 - Consult the KCP manual for more information, available on our KERN website (www.kern-sohn.com).

Pin connection:



Pin 2 input Pin 3 output Pin 5 signal earth

10 Application settings

All factory-set applications are shown in the applications menu. By tapping on a pictogram, the corresponding application window will be displayed.



However, the number of available applications can be adapted operator-specifically via <Operator setup ➡ Functions>.

| 1 | Functions Display News Autoprint Information | Functions Parts counting Tolerance weighing Recipe mode Take off Target parts counting Classification Totalization | 2 | 11:11:47 19:09:2016 ■ START | Max = 30kg 0.000 | d=2g | , , |
|---|--|---|---|---|---------------------|------|-----|
| | ⇒ Call up <operator setup="" ⇒<br="">Functions>, see chap. 9.3</operator> ⇒ Select desired applications. | | | Only those applications confirmed with will be shown in the applications selection. | | | |


10.1 Parts counting

"Parts counting" application allows you to count items with roughly the same item weight. Before the balance can count parts, it must know the average part weight (i.e. reference). The balance determines the total weight and divides it by the number of parts (the so-called reference quantity). Based on the calculated reference item weight, counting will follow next.


As a rule:

The higher the reference quantity the higher the counting exactness.


Open application:



10.1.1 Simple item counting Identify reference item weight:




Selection operator-defined reference item quantity






The balance determines the weight of the reference item.

Remove reference weight. The balance is now in parts counting mode counting all units on the weighing pan.







Carry out parts counting

After determining the reference, load the parts to be counted. The item number is calculated and displayed.



Enter known reference single weight as numeric value


35


Return to weighing mode:



10.1.2 Retrieve/save counting article/reference item weight from/to database


10.1.2.1 Creating a data record





The saved data record is displayed in the list.

10.1.2.2 Edit data record



10.1.2.3 Data record deletion


1

| 07:36:56 20.09.2016 | Max = 30kg EMORY | d = 2g | |
|---------------------|---------------------|--------|---|
| PCS : Product 123 | LINOKI | | - |
| | | | _ |
| | | | ī |
| | | | |
| | | | |
| | | | |



Confirm the query, the data record will be deleted

10.1.2.4 Retrieve data record/perform item count



Load the items to be counted, the number of items will be calculated and displayed.

| | | 0 |
|------------------|-------|----------------|
| | | Upcs |
| Total weight | 0.0 | 000 kg |
| Reference weight | 0.525 | kg/pcs |
| Reference name | Produ | uct 123 |
| | | |
| TARE / | 0. |) - ≣ + |

I


The counting procedure can be started now.

10.1.3 Fill to target

This function facilitates counting to a nominal value.

With the additional input of a ± tolerance, you can set the accuracy with which a count is performed (only supported for databases, see chap. 10.1.3.2).

The following description assumes that the reference for the item counting was already determined (see chap. 10.1.1 "Determine reference").



10.1.3.1 Count in to a nominal value

Place weighed load on the balance and start counting. The capacity indicator facilitates weighing to the nominal value.

m

Sample display

| 07:45:44 20.09.2016 | ling | | м | ax = 30k | g | d = 2 | g | |
|---------------------|--------------------|-----|---------|----------|------|--------------|--------|---|
| | | | | | 2 | 24 | qty | м |
| | get part erence | | House . | | 24/2 | 25 qty | 1 / | |
| | abase i | | | | | Target | | ۵ |
| AUTO | | TA | RE / | +0+ | | • - | • | 2 |
| E Men | 5× Ref | 10× | 20× | n× M | Ref | →• Tarpet | â | 1 |



State

Number of items below the specified nominal value/tolerance

Nominal value reached and within the tolerance specified

| 7:45:56 20.09.2016 START ++ CHECK WEIGHIN | | x = 30kg | d = 2g | |
|--|-------------------|----------|-------------------|---|
| | | 2 | 26 _{qty} | - |
| | | - | qty | |
| Targe | et parts quantity | 26/2 | 25 qty 🕕 | |
| Refer | ence weight | 0.100 | kg/qty | |
| Data | base name | New | Target | 1 |
| + AUTO | TARE / | •0• | → - 🖬 🗧 | 4 |
| | | | | 1 |

Number of items exceeds the specified nominal value/tolerance

10.1.3.2 Save/retrieve the articles in the database

Create data record:



The following data can be saved for the data record:

- Name
- Known container weight
- Barcode
- Reference weight
- > Target value
- > Tolerance

Enter data as described in chap. 10.1.2.1 beschrieben eingeben

- Retrieve, delete or edit data record, see chap. 10.1.2
- Return to weighing mode, see chap. 10.1


1

10.2 Tolerance weighing

With this application, you can check whether a weight value is within the specified tolerance limits. In addition weighing in can be to a specified nominal value/± tolerance [%].


Above or below the limit value is displayed with the indicators <->, <**OK**> or < + >. The colour of the back light changes depending on loaded weight.

Open application:



10.2.1 Tolerance weighing after setting an upper and lower limit value

A low and a high weight value must be entered. These weights and all weights that fall within this range are considered within the tolerance.



KFT-TM-BA-e-1610

| 9:08:07 20:09:2016 | Max = 30kg d = 2g | |
|--|---------------------|----|
| START V TOLERANCE WEIGHING | 4.890 kg | м |
| | OK + | |
| | | \$ |
| TARE | />0< → -董 < | 4 |
| B | â | |
| | | _ |
| START V TOLERANCE WEIGHING Current weight | 4.990 kg | м |
| 4.900kg | 5.100kg | ۵ |
| TARE | />0< → -≣ < | 4 |
| B | ā | |
| 9.08.42 20.09.2016 START V TOLERANCE WEIGHING | Max = 30kg d = 2g | |
| Current weight | 5.110 kg | 1 |
| | 0K + | |
| 4.900kg | 5.100kg | ð |
| | | - |
| TARE | />0≤ → -重 < | |
| TARE | />0+ → - ≣ + | |

State

Weighed load too light


Weighed load within set tolerance


Weighed load too heavy

- The limit values will be saved until new values are defined
- To delete the limits tap on
 - Return to weighing mode, see chap. 10.1

10.2.2 Weighing in to target weight/± tolerance

The target weight and a lower and upper tolerance [%] must be entered.






- The target weight and the tolerances are saved until new values are calculated.
- Tap in to delete the values.

1

• Return to weighing mode, see chap. 10.1



Weighed load too light

Weighed load within set tolerance

Weighed load too heavy

- The limit values will be saved until new values are defined
- To delete the limit values s tap on
 - Return to weighing mode, see chap. 10.1

1

10.2.3 Save/retrieve articles in the database

Max = 30kg 09:06:14 20:09:2016 Max = 30kg d = 2g 09:33:59 20.09.2016 d = 2g 1 2 START V TOLERANCE WEIGHING START V TOLERANCE WEIGHING B MEMORY 0.000 kg . */ Current weight + 0 + 1 â ,o \$ TARE / + O + > =**≣** ∢ **B** B 而 5 目 1 Create a new data record with Tap on the symbol 09:34:08 20.09:2016 Max = 30kg d = 2g 09:34:13 20.09.2016 Max = 30kg d = 2g 3 4 START V TOLERANCE WEIGHING HMEMORY * NEW START V TOLERANCE WEIGHING B MEMORY * NEW TOL TOL **New Tolerance New Tolerance** 0.000 kg 0.000 kg Pretare value Pretare value 00000000000000 0000000000000 Barcode Barcode Target weighing (tolerance in %) Target weighing (tolerance in %) Lower limit value 0.000 kg Target weight 0.000 kg 0.000 kg '-' Deviation 0.00 % Upper limit value '+' Deviation 0.00 % 5 Select tolerance type: "Tolerance weighing after setting an "Weighing in to target weight/± upper and lower limit value!". tolerance" ⇒ Enter data as described in chap. 10.1.2.1

Create data record:

- Retrieve, delete or edit data record, see chap. 10.1.2
- Return to weighing mode, see chap. 10.1

1


10.3 Formulation


Complete recipes with all components and the corresponding parameters (e.g. description, tare weight, tolerances) can be saved in the database. When working through these recipes from the database, the balance will guide you step by step through the process of components weighing in.

The practical recalculation function automatically detects in case of an overbalanced component the new nominal weights of the other components.


The information column at the left edge of the display keeps you informed about the components already weighed in.

Open application:






10.3.1 Creating a recipe in the database



- Edit data record or delete, see chap. 10.1.2
 - Return to weighing mode, see chap. 10.1

1



10.3.1.1 Process recipe from the database

The capacity indicator facilitates weighing to the nominal value:




Weight of the component is below the desired weight/tolerance



Weight has reached the nominal weight and lies within the tolerances



Weight of the component is over the nominal weight/tolerance





The balance is ready to weigh the second component.

Further components can be weighed as described for the first component.



After weighing the last component, the total weight and individual weights of the components can be printed out by connecting an optional printer (depending on the setting in the menu either automatically or after

pressing

Finish recipe with



Confirm query.

A new recipe can be started (see step 1).

7

Recalculation function:



If a nominal weight is exceeded, press and the nominal weights of the other components are calculated proportionally to the exceeded weight value.

| | ٨ | | 07 | | 0 | |
|---|--------|----------|---------|------|----------------|---|
| | A | | 0.7 | U | Ukg | |
| | Total | weight | 1 | 0.70 | 0 kg | |
| A | Targe | t weight | | 0.70 | 00 kg | |
| | Pudd | ing | | | Milk | 1 |
| | Next + | TA | RE /+0+ | |) - ≣ < | |
| | A+ | B | 0 | nx | 亩 | |

10.3.1.2 Log recipe


Printout example (KERN YKB-01N):

| Product: Mi?Ho 14.09.2016 08 | |
|--|---------|
| Milch. 0.250kg Nominal Mass: Difference: | 0.250kg |
| Honig. 0.070kg Nominal Mass: Difference: | 0.070kg |
| Benzoe Oel. O. Nominal Mass: Difference: | 0.001kg |
| Mandeloel. 0.3 Nominal Mass: Difference: | 0.330kg |
| C: 0.642kg | |


10.4 TAKE OFF

With this function you can weigh defined portions of the large container. With the additional input of a \pm tolerance, you can set the accuracy with which the portions are to be weighed (only supported for databases, see chap. 10.4.2).

Open application:



10.4.1 Weighing using the quick keys



English




Printout example (KERN YKB-01N):

| Product: T01 N: 4.100kg 11:02 15/09/16 15.09.2016 10:38 |
|---|
| Product: T01 N: -0.200kg 11:03 15/09/16 15.09.2016 10:38 |
| Product: T01 N: -0.200kg 11:03 15/09/16 15.09.2016 10:38 |

10.4.2 Save articles in the database

Create data record:



| Barco | de | | 00 | 000000 | ТКО | Product 33 |
|-------------------|-------------------|-------------|--------|---------|---|--------------|
| | | hen removir | ng | 0 | Pretare value | 0.000 |
| Tolera | ance | | | | Barcode | 00000000000 |
| 1 | - | 1 | T | | Target weight when removin Tolerance | g 0.250 5 |
| | 1 | 2 | 3 | Ē, | Tolerance | 5 |
| | 4 | 5 | 6 | 5 | | |
| | 7 | 8 | 9 | | | |
| | | 0 | • | J | | |
| 10:07:40 20.09.20 | 16 | | and ac | ccept v | J Save data record with | J |
| Enter ± t | 16 E OFF 🔡 MEM | | | | ±# | J |
| 10:07:40 20.09.20 | 16 E OFF 🔡 MEM | | | | ±.47 47 | J |
| 10:07:40 20.09.20 | 16 E OFF 🔡 MEM | | | | ±.// // 面 | J |
| 10:07:40 20.09.20 | 16 E OFF 🔡 MEM | | | | ±.47 47 | J |
| 10:07:40 20.09.20 | 16 E OFF 🔡 MEM | | | | ±.// // 面 | J |
| 10:07:40 20.09.20 | 16 E OFF 🔡 MEM | | | | ±.// // 面 | J |

- Retrieve, delete or edit data record, see chap. 10.1.2
- Return to weighing mode, see chap. 10.1
- Note:

1

Due to the drift of the balance, for a continuous load, the display value can change slowly over time.

10.5 Fill to target


This function facilitates counting to a nominal value.

With the additional input of a \pm tolerance, you can set the accuracy with which a count is performed (only supported for databases, see chap. 10.1.3.2).

08:21:27 29.07.2016 Max = 30kg d = 2g 10:13:00 20.09.2016 Max = 30kg d = 2g 1 2 START START -- CHECK WEIGHING --**0.000**_{kg} + 0 + + 0 + qty Target parts quantity Reference weight 0.000 kg/qty 0 ¢ AUTO 8 ۵, TARE />04 TARE />04 > - 🖬 🛪 > - i -B Å -**√**+ Å t →• _ill Σ 0 5× 10× 20× n× 1 ++ m The application-specific settings are displayed. Either tap the symbol in the applications menu. Retrieve/save counting **B** Mem article/reference item weight or from/to the database, see chap. 10.1.2 call up the function via the "Item counting" application, see chap. 10.1.3 Determine reference single 20× 5× 10× weight by weighing Number of reference items selectable (5, 10, 20)Determine reference item n× weight by weighing Number of reference items is operator defined Enter known reference item Ref weight as a numerical value Determine target parts -++ quantity Delete target number and 面 reference weight


⇒ Open application

- ⇒ Calculate reference item weight, see chap. 10.1.1
- ⇒ Set target item / weighing on a nominal value



⇒ Save/invoke articles in the database, see. chap. 10.1.3.2

⇒ Printout example (KERN YKB-01N)




10.6 Classification


This application can be used to classify identical objects in specified classes in accordance with their mass.


The info column to the left of the display tells you which class is currently loaded.

Open application:




Create article in the database:






English



- Edit data record or delete, see. chap. 10.1.2
 - Return to weighing mode, see chap. 10.1

1

Classify article:





The balance is ready for classification.


If required load the weighing containers corresponding to the pretare value.

Printout example (KERN YKB-01N):

| | 15.09.2016 | 9:29 |
|----|-----------------------------|------|
| | Untere klasse N: 0.990kg | 2 |
| | 15.09.2016 | 9:29 |
| | Mittlere Klas N: 1.390kg | se |
| J. | 15.09.2016 | 9:29 |
| | Mittlere Klas N: 1.890kg | sse |
| | 15.09.2016 | 9:30 |
| | Oberste Klass N: 2.190kg | 5e |

10.7 Totalization

With this application the individual weighing values are added into the summation memory by pressing a button and edited, when an optional printer is connected.



Open application:





Remove the weighed good. More weighed goods can only be added when the display \leq zero.

| 3 | 10.39.52 20.09.2016 START + ADDING UP 2.000kg | 10:40:54 20:09:2016 Max = 30kg d = 2g ■ START + ADDING UP 0.0000 kg |
|---|---|--|
| | Total weight 1.000 kg | Total weight 3.000 kg |
| | AUTO TARE />0 · → - ▲ · ▲ H H H Man | AUTO TARE ← TARE />0 ← → - ■ ← ■ ■ ← ■ |
| | Place good to be weighed B. Wait for stability display, then press . The weight value will be saved and printed if an optional printer is connected. | Remove the weighed good. More weighed goods can only be added when the display ≤ zero. |

- \Rightarrow Add more weighed goods as described before. Please note that the balance must be unloaded between the individual weighing procedures.
- \Rightarrow Tap the \square symbol to finish. The application switches back to the initial state.

| 16.09.201 | 6 09:39 | |
|---------------------|-----------------|--|
| No. 1 | | |
| N: 1.000k | g | |
| C: 1.000k | 9 | |
| NI- 73 | | |
| No. 2 | | |
| N: 2.000k | PT-270(41) | |
| C: 3.000k | g | |
| No. 3 | | |
| N: 1.500k | g | |
| C: 4.500k | | |
| | Name of the sec | |
| < <<<<<<< | | |
| C: 4.500k | a | |

Printout example (KERN YKB-01N):

- Create, edit, retrieve, or delete articles in the database, see chap. 10.1.2
- Return to weighing mode, see chap. 10.1

1

11 Servicing, maintenance, disposal



Before any maintenance, cleaning and repair work disconnect the appliance from the operating voltage.

11.1 Cleaning

Please do not use aggressive cleaning agents (solvents or similar agents), but a cloth dampened with mild soap suds. Ensure that no liquid penetrates into the device. Polish with a dry soft cloth.

Loose residue sample/powder can be removed carefully with a brush or manual vacuum cleaner.

Spilled weighing goods must be removed immediately.

11.2 Servicing, maintenance

- ⇒ The appliance may only be opened by trained service technicians who are authorized by KERN.
- ⇒ Before opening, disconnect from power supply.

11.3 Disposal

Disposal of packaging and appliance must be carried out by operator according to valid national or regional law of the location where the appliance is used.

12 Troubleshooting / error messages

Possible causes of errors:

In case of an error in the program process, briefly turn off the balance and disconnect from power supply. The weighing process must then restart from the beginning.

Help:

Fault

Possible cause

The displayed weight does not glow.

- The balance is not switched on.
- The mains supply connection has been interrupted (mains cable not plugged in/faulty).
- Power supply interrupted.

The displayed weight is permanently changing

- Draught/air movement
- Table/floor vibrations
- Weighing pan has contact with other objects.
- Electromagnetic fields / static charging (choose different location/switch off interfering device if possible)

The weighing result is obviously incorrect

- The display of the balance is not at zero
- Adjustment is no longer correct.
- The balance is on an uneven surface.
- Great fluctuations in temperature.
- Warm-up time was ignored.
- Electromagnetic fields / static charging (choose different location/switch off interfering device if possible)

No data transfer between printer and balance.

• Communication settings are wrong.

13 Installing display unit / weighing bridge



Installation / configuration of a weighing system must be carried out by a well acquainted specialist with the workings of weighing balances.

13.1 Technical data

| Supply voltage: | 12 V / 2500 mA |
|----------------------|---|
| Max. signal voltage | 0-10 mV |
| Zeroing range | 0-2 mV |
| Sensitivity | 2-3 mV/V |
| Resistance parameter | 80 - 1200 Ω, Max. 8 Stück à 350 Ω Lastzelle |

13.2 Weighing system design

The display unit is suitable for connection to any analogue platform in compliance with the required specifications.

The following data must be established before selecting a weighing cell:

• Weighing balance capacity

This usually corresponds to the heaviest load to be weighed.

Preload

This corresponds to the total weight of all parts that are to be placed on the weighing cell such as upper part of platform, weighing pan etc.

• Total zero setting range

This is composed of the start-up zero setting range $(\pm 2\%)$ and the zero setting range available to the user via the ZERO-key (2%). The total zero setting range equals therefore 4 % of the scale's capacity.

The addition of weighing scales capacity, preload and the total zero setting range give the required capacity for the weighing cell. To avoid overloading of the weighing cell, include an additional safety margin.

• Smallest desired display division

13.4 Configure display unit

⇔

⇒

13.3 How to connect the platform

Anzeigegerät konfigurieren

Disconnect the display unit from the power supply.

| 1 08:21: STA | 17 29.07.2016 XT | Max = 30kg | d = 20 | - 0 - | 2 | | - ¢¢ ≔ | × | |
|-----------------|-------------------------------|-----------------------------------|----------------------|---------|---|--|--|--|---------|
| Pre go | ess F or tap | o 🏝 👬 | Σ the disp | blay to | | • | | - | ۲ d. |
| 3 | 1 2 4 5 7 8 0 | sword **** 3 6 9 œ | Cancel | t | 4 | Weighing Adjustment Screen Password Serial interfa Date/time Network Database Weighing data Autoprint | Weighing Balance Type Partition Maximum load Constant of gravitation Autom. Zero return Autom./manual zero setting Unit Display speed Decimal Positions | Single-range ball 2 30 kg 9.80761 m/s ² Disabled 10% | |
| | er the standa our personal | • | | | | The ava see cha | ilable settings v p. 9.2 | vill be sh | own, |

Solder the individual leads of the load cell cable onto the circuit board.

 \Rightarrow Adjustment is required after entering configuration data, see chap. 7.8.