Moisture Analyzer

INSTRUCTION MANUAL

MX-50

MF-50



WM: PD4000477A

This manual and Marks

All safety messages are identified by the following, "WARNING" or "CAUTION", of ANSI Z535.4 (American National Standard Institute: Product Safety Signs and Labels). The meanings are as follows:

Z!\SWARNING	A potentially hazardous situation which, if not avoided, could result in death or serious injury.
A CAUTION	A potentially hazardous situation which, if not avoided, may result in minor or moderate injury.



This is a hazard alert mark.



This mark is the IEC417 mark for "Caution. Hot surface". Do not touch parts affixed with this mark without adequate protection.



This mark informs you about the operation of the product.

- This manual is subject to change without notice at any time to improve the product.
- Product specifications are subject to change without any obligation on the part of the manufacturer.
- Under the copyright laws, the instruction manual and the software (program) described in it are copyrighted, with all rights reserved.
 The software may be installed in a computer and may not be installed into other coumputers without the prior written consent of A&D Company. Copying includes translation into another language, reproduction, conversion, photocopy and offer or loan to another person.
- The purchaser may make one copy of the software for backup purposes.
 The manual and the software may not be copied, in whole or part, except as described above.
- Windows is a registered tradmark of the Microsoft Corporation.

*

Contents

1.	•	Safety and Compliance	3
2	•	Precautions	5
	2.1.	Installing the Instrument	
	2.2.	During Use	
	2.3.	After Use and Maintaining the Instrument	
3.	•	Outline and Features	8
4.		Packing List and Names of each part	10
	4.1.	Display and Keys	12
5.		Preparations (Installation, Initialization, Motion Check)	14
	5.1.	Installing the Instrument	
	5.2.	Setting the Clock and Calendar (Initialization)	
	5.2.1		
	5.3.	Proper Operation for Precision Measurement	
	5.3.1		
	5.3.2		
6.		Measurement Procedure	17
	6.1.	Simple Operation	
	6.1.1		
	6.1.2		
	6.2.	Program Number	
	6.2.1		
	6.2.2		
7.		Measurement Programs	21
	7.1.	List of Measurement Programs	
	7.1.1		
	7.1.2		
	7.1.3		
	7.1.4	. Analyzing Mode of the Timer Mode	.23
	7.1.5.		.23
	7.2.	Procedures to Store a Measurement Program	24
	7.2.1		
	7.2.2		
	7.2.3		
8.		Check Function	36
	8.1.	Self-Check Function (Motion Check)	

8.1.1	Operation	36
8.2.	Test Sample (Sodium Tartrate Dihydrate)	37
9.	Connecting to a Printer	38
10.	Connecting to a Computer	39
10.1.	RS-232C Serial Interface	40
10.2.	Output Format	41
10.3.	Command	42
11.	Data Memory Function	43
11.1	.1. Preparation	43
11.1	.2. Output All Data at One Time	44
11.1	.3. Delete All Data at One Time	44
12.	Calibration	45
12.1.	Identification Number (ID No.)	45
12.1	.1. Setting the ID Number	45
12.2.	Calibration of the Weighting Sensor	46
12.2	.1. Operation	46
12.3.	Calibration of Drying Temperature for MX-50	48
12.3	.1. Operation	48
13.	Function Table	50
13.1	.1. Operation	51
14.	Maintenance	52
14.1.	Cleaning the Heater Unit	52
14.2.	Replacement of the Halogen Lamp	53
14.3.	Factory Settings	54
14.3	.1. Operation	54
14.4.	Troubleshooting	55
14.5.	Error Message	56
15.	Specifications	57
15.1.	Dimensions	58
15.2.	Accessories and Peripheral Equipment	58
16.	Index	59



1. Safety and Compliance

MWARNING

- Do not use a sample which could make a dangerous chemical reaction and cause an explosion or poisonous gas, when a sample is dried.
- Keep flammables away from the analyzer.
 Parts of the analyzer become very hot. Materials placed near it might catch fire.
- □ Do not use the analyzer in ambient ignitable gas. It may cause explosion and fire.
- Use a power source (voltage, frequency, outlet type) adapted to the specification of the analyzer. If excessive voltage is used, the analyzer may overheat and be damage or cause a fire.
- Turn off the power switch and remove the power cord from the power outlet, when replacing the halogen lamp. Touching an electrode of the halogen lamp connector carelessly, it may cause to receive an electric shock.
- Do not disassemble the analyzer. It may cause an error, damage, receiving an electric shock or fire. If the analyzer needs service or repair, contact the local A&D dealer.
- Avoid getting the analyzer wet. The instrument is not a water-resistant structure. If there is leakage of liquid into the analyzer, it may cause damage to the instrument or receiving electric shock.
- Do not look at the active halogen lamp to protect your eyes from damage.
- Do not drop, hit or crack the glassware included the halogen lamp, to avoid an injury.
- □ When the halogen lamp is used beyond 5000 hours, we recommend replacing the lamp with a new one to avoid trouble.
- □ When discarding halogen lamp, do not break it to avoid scattering glass and injury.

ACAUTION

- Do not touch the heater cover, the halogen lamp, glass-housing, pan handle, sample pan and sample without adequate protection, it could cause a burn or scald. Parts of the analyzer are very hot when a measurement finishes. For operation, use the specified grips of the heater cover and pan handle. Use the standard accessory tools.
- □ Do not touch parts affixed with the ▲ mark, because they may get very hot and dangerous.
- When the analyzer is used in a room where hot air does not diffuse, the drying temperature may unexpectedly overheat. In this case, adjust the drying temperature or move the instrument to a place with adequate ventilation.
- Avoid leaving the analyzer in direct sunlight, as that could cause discoloration of the case or a malfunction.

Compliance with FCC Rules

Please note that this equipment generates, uses and can radiate radio frequency energy. This equipment has been tested and has been found to comply with the limits of a Class A computing device pursuant to Subpart J of Part 15 of FCC rules. These rules are designed to provide reasonable protection against interference when this equipment is operated in a commercial environment. If this unit is operated in a residential area, it may cause some interference and under these circumstances the user would be required to take, at his own expense, whatever measures are necessary to eliminate the interference.

(FCC = Federal Communications Commission in the U.S.A.)

Compliance with Council Directives

This device features radio interference suppression and safety regulation in compliance with the following Council Directives

Council directive 89/336/EEC

EN61326

EMC directive

Council directive 73/23/EEC

EN61010-1

Low voltage directive



2. Precautions

X

2.1. Installing the Instrument

--- Caution for Measurement Safety ---

- Do not install the analyzer in a dangerous place.
- Maintain the following ambient condition to operate the analyzer.
 5°C to 40°C (41°F to 104°F), 85%RH or less (no condensation)
- Keep flammables away from the analyzer.
- Do not put anything on the heater cover.
- Do not install the analyzer in a small airtight room. If the analyzer is used in an airtight room, hot air does not diffuse, the sample may unexpectedly overheat. In this case, the safety circuit of the halogen lamp activates. Move the instrument to a place with adequate ventilation or adjust the drying temperature.
- There is the voltage label on the back panel of the analyzer.
 Confirm that voltage, frequency and outlet type is correct for your local voltage.
- Confirm that the rated voltage of the halogen lamp is correct for your power supply voltage. (Refer to 14.4.Troubleshooting)

Voltage Label	Power Supply Voltage	The Rated Voltage of Halogen Lamp
100 - 120 V	AC 100 V to AC 120 V	AC 120 V
200 - 240 V	AC 200V to AC 240 V	AC 240 V

- Ground the analyzer using the ground terminal of the power cord.
- Do not change the setting of the I/II switch on the rear of the analyzer. If the incorrect setting is used, it may damage the instrument or cause a fire.

--- Caution for Precision Measurement---

Confirm the following condition, because the weighing sensor (S.H.S.) is very sensitive.


- The weighing surface should be solid and free from vibration, drafts and as level as possible.
- □ Install the analyzer in a stable place avoiding vibration and shock.
- Install the analyzer where it not affected by heaters or air conditioners.
- Ensure a stable power source.
- □ Keep the analyzer away from equipment that generates magnetic fields.
- Discharge static electricity.




--- Caution for Measurement Safety ---

Operate the analyzer using the following procedure.

- Put the sample pan in the correct position.
- Handle the grip of the heater cover to open and close it.
- Use the pan handle to move the sample pan.
- Do not touch hot parts around the grass-housing, when the cover is opened.
- The glass-housing is very hot. It may cause a burn, if touched.
- ☐ The sample pan and pan handle is very hot, when finishing measurement. Allow them cool down.
- Use the tweezers or spoon to move the sample.





Grip of heater


Grip of pan handle

cover

Grips and Hot Parts.

u Hot parts are as follows:

Use the following grips to operate the analyzer.



Do Not Measure a Dangerous Sample.

- Do not use an explosive, flammable or noxious substance as a sample.
 Do not use a sample that makes a dangerous substance by drying it.
 Do not use unknown substances.
- □ When a sample surface becomes dry first and the inner pressure increases, the sample may explode. Do not use such a sample.
- Turn off the power switch if a sample catches fire.
- □ The case of the analyzer is made of a flame-retardant substance (UL94V0).

Do Not Put any Flammable Matter Around the Analyzer.

- During and after measurement, parts of the analyzer become very hot. Do not put flammable matter near the analyzer.
- Do not put any thing on the heater cover.

Caution for Heating (Drying).

- When the drying temperature is set to 200°C and measurement is started, the thermostat of the halogen lamp may work after 30 minutes. When the halogen lamp has cooled down, the next measurement can be started. If necessary, change the drying time and temperature.
- When a measurement is started and the time passes one hour, the maximum temperature is automatically regulated to 160°C for safety.


Operation to Stop Measurement


During measurement, the STOP key is always effective. If there is an error or danger, press the STOP key.




2.3. After Use and Maintaining the Instrument

- Put dust cover on the analyzer after it is cool.
- Clean the glass-housing carefully.
- Clean fingerprints from the halogen lamp to keep its life. Refer to "14.2.Replacement of the Halogen Lamp".
- Avoid mehcanical shock to the analyzer.
- Do not disassemble the analyzer.
- Protect the analyzer from excessive dust.
- Use the packing box (special container) to move the analyzer.
- Clean the analyzer with a lint free cloth that is moistened with warm water and a mild detergent.
- Do not use organic solvents to clean the analyzer.
- Do not disassemble or remodel the analyzer.









3. Outline and Features

- □ The moisture analyzer is built using a super hybrid sensor (S.H.S.) adopted in an analytical balance. Therefore, the result is more precise and gets greater repeatability.
- An analyzer using the S.H.S. has high sensitivity, needs only a sample quantity of a few grams, and the measurement time becomes shorter.
- □ A 400W halogen lamp is used as the heating source and the temperature on the sample pan can reach 200°C within two minutes.
- □ The **standard mode** can obtain the moisture content with settings of the drying temperature and accuracy.
- □ There are three user mode that can set the measurement parameters.

Automatic mode..... When the change of moisture content per one minute is less than the preset termination value, the measurement is automatically stopped and the result is obtained.


Timer mode...........The sample is dried for a preset time and the result is obtained. **Manual mode**..........This mode can stop the measurement by key operation and the result is decided.

□ There are three drying programs which control the temperature profile.

Standard drying..... Maintains a constant drying temperautre.

Lamp drying......Increases the drying temperature gently.

Step drying......Uses multiple steps of the drying temperature.



□ The analyzer can store and recall proper individual settings for each sample using a program number (PROG No.).

Maximum number

MX-50

20 sets

MF-50

10 sets

□ The data memory function can store results and output them at one time.

Maximum number

MX-50

results of 100

MF-50

results of 50

- □ The software "WinCT-Moisture", the standard accessory of the MX-50, has a function that can make a graph of the change of moisture content, etc. in realtime.
- □ The software "WinCT", the standard accessory of the MF-50, is communication software for tarnsmitting data to a computer using Microsoft Windows.
- □ The analyzer is equipped with a serial interface as standard. It can be connected to a printer or computer.
- The analyzer can calibrate the weighing sensor (Use special mass.) and drying temperature (Use temperature calibrator for MX-50). The analyzer can output the data required at GLP, GMP and ISO at the end of the calibration.
- The analyzer has a self check function that can detect a function errors.

- □ The analyzer displays the current change of moisture content per one minute [%/ min] in realtime. It can be used for the reference to find the analyzing mode.
- □ The sample pans included in the standard accessory can be used repeatedly.
- A test sample, the standard accessory, is included to check the moisture accuracy.
- A reference card is built into the analyzer.


Principle and Use

The moisture analyzer, is based on the principle of thermogravimetric analysis, dries a sample using a halogen lamp and obtains the moisture content in % and other results by the difference between the wet weight and dry weight.




4. Packing List and Names of each part

- Keep the packing box to move the analyzer.
- Packing list as follows:




Standard Accessories



Caution Please confirm that the instrument is correct for your local voltage, receptacle type and power cord.

X

4.1. Display and Keys



	Name	State	Meaning			
1	Time	Preset time. Process	time			
2 Temperature of		During gram display Set temperature of sample pan				
	sample pan	During measurement	Current temperature of sample pan			
	PROG: Program No.	During gram display	Program number of measurement program			
. 3	MEM: Data No.	Storing data	Data number of data memory function			
	Mode	During setting	Symbol of mode	(5Ed, U-A, U-E, etc .)		
4	Accuracy	Accuracy indicator of	measurement			
		Indicator of heater co		Irying process		
	Operation indicator	Lights when heater	cover is closed			
_		Blinks during measu	ırement.			
5	1 1111	Disappears when no	ot measuring			
	—	Sample mark: Lights	when the sample	is 0.1 g or more.		
		Sample needs at leas	st 0.1 g or more to	start measurement.		
		Reference of sample				
	Level indicator	Proper sample quantity range				
6						
			· .			
- 	Target quantity	During gram display	Target quantity	of sample [g]		
7	Drying rate	During measurement	Current drying r	ate [%/min.]		
	·	It means Change of moisture content per one minute [%/min.]				
	Measurement unit					
	% MOIST	Moisture content	<u>W-D</u> x100	•		
	/W	is based on W	<u> </u>			
	% MOIST	Moisture content (Atro)	VI00	W: Wet sample mass		
	/D	is based on D	D			
8	% MOIST	Dry content	$\frac{D}{W}$ x100	D: Dried sample mass		
	D/W		W	•		
	% MOIST W/D	Ratio	<u>₩</u> x100	14 14 14 14 14 14 14 14 14 14 14 14 14 1		
	VV/D	_	U	<u> </u>		
	g	Gram value				
	\/oluo	During gram display	Sample qua	ntity [g]		
9 Value		During measurement	Current moi	sture content [%]		

	Name	State	Meaning
	Drying programs		
10	Standard drying	Maintains a constant	Drying temperauter
	∇	drying temperautre.	brying temperaturer
	Lamp drying	Increases the drying	
	▼ ▽ .	temperature gently.	Drying temperauter
	Step drying	Uses multiple steps of	
	V V	the drying temperature.	Drying temperauter

Display Samples for Mode

Mode	Symbols (during settings)	Gram display (after settings and before measurement)				
Standard mode	SEd	Target quantity				
Automatic mode	U-A	Preset termination value of analyzing mode				
Timer mode	U-E	"10.5 - 5.000 g Preset time				
Manual mode	U-ñ	"105 % 5.000 g				

Key Operation and Key Functions

Keys		Function and action
PROGRAM		Stores or recalls measurement program with the program number during the gram display. Selects a temperature program while the drying
SELECT >		temperature is selected.
	SELECT	Selects item in the measurement program.
●,●	↓ , ↑	Changes value of item in the measurement program.
ENTER	ENTER	Stores current condition in the measurement program number. Output data at measurement.
START	Start prepared measurement	
STOP	STOP	Stop current measurement
RESET	RESET	Sets the display to zero in the unit of gram. Cancel key.



5. Preparations (Installation, Initialization, Motion Check)

5.1. Installing the Instrument

- 1. Select the place to install the analyzer. Refer "2.1.Installing the Instrument".
- 2. Level the analyzer by adjusting the leveling feet and confirm it using the bubble spirit level.
- 3. Read the power supply voltage label on the back of the heater cover.


Confirm that voltage, frequency and outlet type is correct for your local voltage.

Confirm that the rated voltage of the halogen lamp is correct to your power supply voltage.

Voltage Label	Power Supply Voltage	The Rated Voltage of the Halogen Lamp	
100 - 120 V	AC 100 V to AC 120 V	AC 120 V	
200 - 240 V	AC 200V to AC 240 V	AC 240 V	

- 4. Confirm that the power switch is "OFF" position.
- 5. Connect the power cord. Ground the analyzer with the earth terminal on the power cord.
- 6. Align the guide hole of the breeze break ring to the guide on body.
- Install the pan support.
 Align together Δ signs on the pan support and body.
- 8. Put the sample pan on the pan handle.

And hook the pan handle on the notch in the rim of the breeze break ring.



5.2. Setting the Clock and Calendar (Initialization)

Adjust the built-in clock and calendar before use.

5.2.1. Operation

- 1. Turn on the analyzer. The gram unit (of weighing mode) is displayed.
- 2. Press and hold the SELECT key to display [[Rdd].
- 3. Press the ENTER key to display the calendar. Example: 15th April, 2002
- 4. To skip the calendar settings.

Press the | or | key to proceed step 5.

To adjust the calendar settings.

Press SELECT key. Adjust the calendar using the following keys.

SELECT key..... Selects a figure.

 $\cup{!}$, $\cup{!}$ key Selects a value for the figure.

ENTER key Stores the current date and

proceeds to step 5.

RESET key Cancels the adjustment and

proceeds to step 5.

Symbols and arrangement of the calendar

ਪੁੰਜਰYear, month, day

ndy Month, day, year

dกับ Day, month, year The arrangement of the calendar is used for the report

of GLP, GMP and ISO.

- 5. Time is displayed.
- 6. To finish the adjustment.

Press the RESET key to proceed step 7.

To adjust the clock.

Press the SELECT key. Adjust the clock using the following keys.

SELECT key..... Selects a figure.


🗓, 🚹 key Selects a value for the figure. ENTER key Stores time and proceeds to

step 7.


RESET key Cancels the adjustment and

proceeds to step 7.

7. When finishing the adjustment, dP is displayed. Press the RESET key to return to the weighing mode.



0.000a





5.3. Proper Operation for Precision Measurement

5.3.1. Operation of the sample


Use a proper sample quantity. If the sample quantity is small, precise results may not be possible. If the sample quantity is too much, the measurement time becomes long. If the measurement is repeated, maintain the same sample quantity.



- Crush grain samples to a small, uniform powder for a quick drying process.
- Spread the sample as evenly as possible.
- The analyzer is designed to measure the moisture content of the sample by its weight change. If the sample includes volatile matter, it may vaporize during drying causing a measurement error.
- □ When measuring a liquid or liquid state sample that may make a film on the surface, we recommend you use a glass fiber sheet (accessory, AX-MX-32).

5.3.2. Operation of the analyzer

- Press the RESET key to display the zero value before each measurement.
- Check that the displayed sample weight is stable before measurement. Press the START key to start a measurement.
- Select the proper analyzing mode to finish a measurement. Use the change of moisture content per one minute [%/min] that is displayed during measurement as a reference value.



- The analyzer needs a pre-heating process before measurement. When measuring samples repeatedly or continuously, the first result is always different from the other results.
- The pre-heating process is as follows: Put a sample pan, instead of a sample, on the pan. Press the START key to heat it. The analyzer temperature becomes equilibrium.
- Use a sample on the sample pan that has cooled to room temperature. When a sample is put on a hot sample pan, the moisture content is diffused before measurement, and precise results are not possible. We recommend you use multiple sample pans.
- Do not pile up sample pans during a measurement.



6. Measurement Procedure

6.1. Simple Operation

The standard mode can obtain the moisture content with settings of ACCURACY and drying program (temperature profile, drying temperature).

6.1.1. ACCURACY

ACCURACY of measurement can be set either HI, MID. or LO.

Sample and termination values of the analyzing mode are automatically selected by ACCURACY.

Analyzing mode is the program to finish the measurement when a change of moisture content per one minute (drying rate) becomes smaller than a preset termination value. The settings are as follows: Specify an ACCURACY.

ACCURACY	Use	Sample quantity	Preset Termination value of Analyzing mode	
	· · · · · · · · · · · · · · · · · · ·	quartity	MX-50	MF-50
	Precise result	10 g	0.02 %/min	0.05 %/min
MID	↑ ↓	5 g	0.05 %/min	0.10 %/min
LO	Quick measurement	1 g	0.10 %/min	0.50 %/min

Drying rate: Change of moisture content per one minute [%/min]

6.1.2. Operation

This operation explanation uses the following example: Refer to "7.Selection of Measurement Method" for detail.


Input Parameters

Stored Parameters (Facrtry Settings for the MX-50)

 Turn on the analyzer.
 The gram unit (of weighing mode) is displayed.

Enter the Standard Mode

2. Press the SELECT key to select item and press the J or key to select 5td.




Select ACCURACY

- 3. Press the SELECT key to select ACCURACY.

 When ACCURACY is selected, HI, MID. or LO blinks.
- 4. Press the □ or ↑ key to select either □ of ACCURACY.
 - Set Drying Temperature at the Sample Pan
- 5. Press the **SELECT** key to select the drying temperature.
- 6. Press the ↓ or ↑ key to set 130 °C.
 - Store Parameters and Finish the Operation
- 7. Press the **ENTER** key to store the parameters. The weighing mode is automatically displayed.

Put Sample on the Pan

- 8. Put the breeze break ring, pan support, pan handle and sample pan in order. (With no sample.)
- Close the heater cover.
- 10. When displaying a stable value, Press the RESET key. Avoid mechanical vibration, breeze and environmental noise during measurement. If it deviates from zero display, press the RESET key.



0.000

11. Open the heater cover. Put in a sample using the level indicator.



Range of proper sample

Sample needs more than 0.1 g. Significant sample is indicated segment.

Caution

The sample needs to be more than 0.1 g. Spread the sample evenly.

12. If the h key is pressed during gram display, measurement unit and minimum scale value are displayed.

Start the Measurement

- 13. Close the heater cover. Press the START key after a stable value is displayed.
- 14. If the SELECT key is pressed during measurement, measurement is stopped.

Finish the Measurement

- 15. When the change of moisture content per one minute (drying rate) reaches the preset termination value, the measurement is completed and the buzzer beeps.
- 16. Open the heater cover and remove the sample using the pan handle.
- 17. Press the following key to return to gram display.

ENTER key Outputs (Prints) result.

SELECT key.... Returns to the weighing mode.


RESET key..... Returns to the weighing mode and

displays zero.

18. If the same condition is used, proceed to step 8. If changing the condition, proceed to step 3.

Sample pan can be washed and reused.

There is the Reference card on the bottom of the analyzer.



" 130 %

0.000

From last page

Good

1.023

No good

130 %



6.2. Program Number

The measurement conditions of all program numbers are set to the standard mode at the factory. The analyzer can store and recall proper individual settings for each sample with the program number (PROG No.).


Maximum number

MX-50 20 sets MF-50 10 sets

The same measurement program is stored in all program numbers with factory settings.

Mode.....Standard mode

Drying programStandard drying



PROG

0.000

If the data memory function is active, the data memory number (MEM) is Caution displayed, in place of the program number (PROG).


6.2.1. Storing a Measurement Program to a Program Number

Displaying or recalling a PROG number, a measurement program can be renewed.

- 1. Press and hold the PROGRAM key in gram display.
- 3. Press the ENTER key to use the selected number.
- 4. Press the SELECT key to edit the parameters.
- 5. Edit parameters of a measurement program. Refer to "7.Selection of Measurement Method"
- 6. Press the following key to return to the gram display.

ENTER key Stores parameters to the selected number. RESET key..... Cancels the operation and returns to the

weighing mode.




0.000a

PROG ∂ 0.000a

6.2.2. Recalling a Measurement Program with a Program Number

Stored measurement programs can be recalled with a program number.

- 1. Press and hold the PROGRAM key in the gram display.
- 2. Press the □ or ↑ key to select a program number
- Press the ENTER key to use the selected number.





7. Measurement Programs

7.1. List of Measurement Programs


There are the standard mode and three user modes in the measurement program.

		Measurement Programs				
			Շ		Drying Program	
Mode and Display				Analyzing Mode to Finish Measurement	Temperature Profile	Drying Temperature
Stand	dard Mode Std	selected is less tha	by AC an pre	condition is automatically CURACY. When drying rate set termination value, is completed automatically.	Ohana la al	
	Automatic Mode U-R		ineric	When drying rate is less than preset termination value, measurement is completed automatically.	Standard drying, Lamp drying,	50°C to
User Mode	Timer Mode U-Ł	0.1g to 50g	_	Sample is dried for a preset time. 1 min. to 480min.	Step drying	200°C
	Manual Mode ⊔-ñ			Measurement is completed by the STOP key. Max. 480min.		

Drying rate: Change of moisture content per one minute [%/min]

7.1.1. Drying Program

Temperature Profile




Temperature2 can be set higher than temperature1" in step drying.


How to Select a Temperature Profile

Press the SELECT key during the gram display.

Press the PROGRAM key. Symbols of temperature profile are displayed in order.

Display examples during settings





Drying Temperature at the Sample Pan

Drying temperature range......50°C to 200°C, 1°C interval.

When a measurement is started and one hour passes, the maximum temperature is automatically regulated to 160°C for safety.

7.1.2. ACCURACY of the Standard Mode

ACCURACY of measurement can be set to either HI, MID. or LO.

Sample and final change of moisture content per one minute are automatically set by ACCURACY.

Analyzing mode is that measurement is completed when a change of moisture content per one minute (drying rate) becomes smaller than a preset termination value.

The settings are as follows: Specify an ACCURACY.

ACCURACY	Use	Sample quantity	Preset Termination value of Analyzing mode	
		quaritity	MX-50	MF-50
H	Precise result	10 g	0.02 %/min	0.05 %/min
MID	↑ ↓	5 g	0.05 %/min	0.10 %/min
LO	Quick measurement	1 g	0.10 %/min	0.50 %/min

Drying rate: Change of moisture content per one minute [%/min]

7.1.3. Analyzing Mode of the Automatic Mode

When the change of moisture content per one minute is less than the preset value, the measurement is automatically completed.

Preset Termination value	Range		
to complete masurement	MX-50	MF-50	
2.00 %/min	A	A	
1.00_%/min			
0.50 %/min			
0.20 %/min		Available range	
0.10 %/min	Available range	(Factory setting)	
0.05 %/min	(Factory setting)		
0.02 %/min		V	
0.01 %/min		Unavailable item	
0.005 %/min			

7.1.4. Analyzing Mode of the Timer Mode

Sample is dried for a preset measurement time.

Drying Time

1 minute to 480 minutes.

Setting interval:

1 minute during 1 minute to 60 minutes.

5 minutes during 60 minutes to 480 minutes.

Factory setting:

10 minutes.

7.1.5. Measurement Unit

Display Data	Formula	Unit
Moisture content is based on wet sample mass *1	W-D W x 100	% MOIST /W
Moisture content (Atro) is based on dried sample mass	W-D x 100	% MOIST /D
Dry content	X 100	% RATIO D/W
Ratio *2	W x 100	% RATIO W/D
Gram value		g

W: Wet sample mass

D: Dried sample mass


*1: Factory settings

*2: When result reaches to 999%, measurement is stopped.

7.2. Procedures to Store a Measurement Program

7.2.1. Standard Drying

	This explanation uses the following parameters.	
	Drying temperature	Drying temperature Time
	Standard Mode, Automatic Mode, Manual Mode	Timer Mode
	Common Items Program number	Standard drying 🗢 🗢 160°C Moisture content MOIST MOIST
	Minimum scale value of gram display	Approximately 5 g
	Items for Standard Mode Mode	MID.
	Items for Automatic Mode Mode Analyzing mode to finish measurement	
	Items for Timer Mode Mode Analyzing mode to finish measurement	
	Items for Manual Mode Mode	Manual mode (Symbol: [ปี-กิ])
Proce	dure	
1.	Display the gram unit (of the weighing mode).	PROG / 0.000g
2.	Select a Program Number to Edit the Measur Press the PROGRAM key and press the J or key to select a program number.	rement Program
3.	Press the ENTER key to use the number.	Program number
4.	The analyzer displays End and returns to the weighing mode.	PROG ?
Cautio	on If the data memory function is active, the memory number (MEM) is displayed in pl program number (PROG).	



5. Select a mode symbol with the SELECT key and the or key.

If standard mode is used, select 5£d.

If automatic mode is used, select U-R.

If timer mode is used, select U-E.

If manual mode is used, select U-r.

Set ACCURACY for the Standard Mode

6. Select ACCURACY with the SELECT key. Select MID. with the ↓ or ↑ key. When ACCURACY is selected, HI, MID. or LO blinks.

Set the Drying Program

7. Select drying temperature with the SELECT key. Select standard drying of the drying program with the PROGRAM key.

Set the Drying Temperature

8. Set 160°C with the IJ or ↑ key.

Set the Preset Termination Value for Automatic Mode

9. Select the preset termination value with the SELECT key.
Select 0.05 [%/min] with the II or 11 key.

Set the Drying Time for the Timer Mode


10. Select time with the SELECT key. Select 10.0 [min] with the or 1 key.

Set the Measurement Unit

11. Select a measurement unit with the SELECT key. Select a moisture content (based on a wet sample) with the [] or [] key.


Set the Minimum Scale Value of the % Display

12. Select % display with the SELECT key. Select 0.01 [%] with the J or 1 key.



Set the Minimum Scale Value of the Gram Display

13. Select gram display with the SELECT key. Select 0.001 [g] with the ↓ or ∱ key.



Store the Parameters and Finish the Operation
14. Press the ENTER key to store the new parameters for the measurement program to program number 2. Pressing the key, the weighing mode is automatically displayed. When PROG 2 is recalled, the settings can be used.


To cancel the new parameters and return to the weighing mode, press the RESET key.

Standard Mode, Automatic Mode or Manual Mode

Refer to page 29 for Timer Mode

MOIST

This explanation uses the following parameters.



Common Items

Lamp time......5.0 minutes

Minimum scale value during measurement . 0.01 % Minimum scale value of gram display 0.001 g

Sample quantity...... Approximately 5 g

Data memory function...... Not used

Items for Standard Mode

Analyzing mode to finish measurement........... Automatic setting by ACCURACY

Items for Automatic Mode

Analyzing mode to finish measurement.......... 0.05 %/min

Items for Manual Mode

Procedure


1. Display gram unit (of the weighing mode).


Select a Program Number to Edit the Measurement Program

2. Press the PROGRAM key and press the or

tey to select a program number.


- 3. Press the ENTER key to use the number.
- 4. The analyzer displays Fnd and returns to the weighing mode.






0.000a

PROG /



Store Parameters and Finish the Operation

14. Press the ENTER key to store the new parameters of the measurement program to program number 3. Pressing the key, the weighing mode is automatically displayed.




When PROG 3 is recalled, the settings can be used.

To cancel the new parameters and return to the weighing mode, press the RESET key.

Timer Mode

Refer to page 27 for Standard Mode, Automatic Mode or Manual Mode

This explanation uses the following parameters.



Common Items

Program number......4 (PROG 4)

Drying program Temperature profile.....Lamp drying ▼▼

Drying time 10.0 minutes

Measurement unit...... Moisture content

Minimum scale value during measurement . 0.01 %

Minimum scale value of gram display 0.001 g

Sample quantity...... Approximately 5 g

Data memory function...... Not used

Procedure


1. Display gram unit (of the weighing mode).

Select a Program Number to Edit the Measurement Program

 Press the PROGRAM key and press the ↓ or ↑ key to select a program number.

- 3. Press the ENTER key to use the number.
- 4. The analyzer displays *End* and returns to the weighing mode.


Caution If the data memory function is active, the data memory number (MEM) is displayed in place of the program number (PROG).



0.000a

PROG /


MOIST



Standard Mode, Automatic Mode or Manual Mode

Refer to page 33 for Timer Mode

This explanation uses the following parameters.



Common Items

Program number...... 5 (PROG 5) Temperature profile Step drying ▼▼ Drying program

> Drying temperature 1...... 160°C Drying temperature 2...... 120°C

Time 5.0 minutes

MOIST Measurement Unit...... Moisture content

Minimum scale value during measurement . 0.01 % Minimum scale value of gram display 0.001 g

Sample quantity...... Approximately 5 q

Data memory function...... Not used

Items for Standard Mode

ACCURACY......MID.

Analyzing mode to finish measurement...... Automatic setting by ACCURACY

Items for Automatic Mode

Analyzing mode to finish measurement.......... 0.05 %/min

Items for Manual Mode

Procedure

- 1. Display gram unit (of the weighing mode).
- Select a Program Number to Edit the Measurement Program 2. Press the PROGRAM key and press the $\c U$ or
- h key to select a program number.
- 3. Press the ENTER key to use the number.
- 4. The analyzer displays Fnd and returns to the weighing mode.

Caution If the data memory function is active, the data memory number (MEM) is displayed in place of the program number (PROG).

PROG /

0.000a

Select a Mode

5. Select a mode symbol with the SELECT key and the ☐ or ☐ key.
If standard mode is used, select ☐ SEd ☐.
If automatic mode is used, select ☐ U-R ☐.
If manual mode is used, select ☐ U-R ☐.

Set ACCURACY for the Standard Mode

6. Select ACCURACY with the SELECT key. Select MID. with the ↓ or ↑ key. When ACCURACY is selected, HI, MID. or LO blinks.

Set the Drying Program

7. Select drying temperature 1 with the SELECT key. Select step drying ▼ ▼ of the drying program with the PROGRAM key.

Set Drying Temperature 1

8. Set 160°C to drying temperature 1 with the [] or [] key.

Set the Time

9. Select time with the SELECT key. Set 5.0 minutes with the □ or ↑ key.

Set Drying Temperature 2


10. Select drying Temperature 2 with the SELECT key.
Set 120°C with the ↓ or ↑ key.

Set the Preset Termination Value for Automatic Mode

11. Select a preset termination value with the SELECT key. Select 0.05 [%/min] with the [] or [] key.


Set Measurement Unit

12. Select measurement unit with the SELECT key. Select moisture content (based on a wet sample) with the or key.



Set the Minimum Scale Value of the % Display

13. Select the % display with the SELECT key. Select 0.01 [%] with the ↓ or ↑ key.



160°C

Gram display of

weighing mode

0.000a

MOIST

Set the Minimum Scale Value of the Gram Display

14. Select the gram display with the SELECT key. Select 0.001 [g] with the ↓ or ↑ key.

Minimum scale value of gram display

Store the Parameters and Finish the Operation

15. Press the ENTER key to store the new parameters of the measurement program to program number 3. Pressing the key, the weighing mode is automatically displayed. When PROG 3 is recalled, the settings can be used.


To cancel new parameters and return to weighing mode,

o cancel new parameters and return to weighing mode press the RESET key.

Timer Mode

Refer to page 31 for Standard Mode, Automatic Mode or Manual Mode

This explanation uses the following parameters.



Common Items

Program number...... 6 (PROG 6)

Mode......Timer mode (Symbol: U-E)

Drying program Temperature profile...... Step drying ▼▼

Drying temperature 1....... 160°C
Drying temperature 2....... 120°C

Time 1 5.0 minutes

Time 2......10.0 minutes

Measurement unit...... Moisture content

Minimum scale value during measurement . 0.01 % Minimum scale value of the gram display 0.001 g


Sample quantity..... Approximately 5 g

Data memory function...... Not used

Procedure

- 1. Display gram unit (of the weighing mode).
 - Select a Program Number to Edit the Measurement Program
- 2. Press the PROGRAM key and press the solution or leave to select a program number.
- 3. Press the ENTER key to use the number.
- 4. The analyzer displays *End* and returns to the weighing mode.

Caution If the data memory function is active, the data memory number (MEM) is displayed in place of the program number (PROG).




0.000a

PROG /

Select a Mode

- 5. Select the symbol <u>U-t</u> of the timer mode with the <u>SELECT</u> key and the <u>U</u> or <u>1</u> key.
 - Set the Drying Program
- 6. Select drying temperature with the SELECT key. Select step drying ▼ ▼ of the drying program with the PROGRAM key.
- Set Drying Temperature 1 7. Set 160°C with the ☐ or ↑ key.
- Set the Time 1
- 8. Select time 1 with the SELECT key. Set 5.0 minutes with the 1 or 1 key.
 - Set Drying Temperature 2
- 9. Select Drying Temperature 2 with the SELECT key. Set 120°C with the ↓ or ↑ key.
 - Set the Time 2
- 10. Select time 2 with the SELECT key. Set 10.0 minutes with the we key.



Mode

Set the Measurement Unit

11. Select measurement unit with the SELECT key. Select the moisture content (based on wet sample) with the 🗓 or 🕅 key.

Measurement unit


Measurement unit

SELECT

SELECT


Set the Minimum Scale Value of the % Display

12. Select the % display with the SELECT key. Select 0.01 [%] with the or key.




Set the Minimum Scale Value of the Gram Display

13. Select the gram display with the SELECT key. Select 0.001 [g] with the or key.



Store the Parameters and Finish the Operation

14. Press the ENTER key to store the new parameters of measurement program to program number 6. Pressing the key, the weighing mode is automatically displayed.
When PROG 6 is recalled, the settings can be used.



To cancel the new parameters and return to the weighing mode, press the RESET key.



8. Check Function

8.1. Self-Check Function (Motion Check)

Use the self-check function to check whether there is an error or inaccurate result. During the check, the heater is turned on and the temperature sensor is checked.

Caution

Do not put flammable matter near the analyzer. Do not put anything on the heater cover.

8.1.1. Operation

- 1. Display the gram unit (of the weighing mode).
- 2. Press and hold the PROGRAM key to display [H]
- 3. Put the breeze break ring, pan support, pan handle and sample pan in order. (Do not put a sample on the pan.)

Close the heater cover.

Press the **ENTER** to start the check.

If [[Lo5E]] is displayed, the heater cover is ont closed. When it is closed, check is started."


4. Check needs approximately one minute.

Good result... Displays [IH PRSS], sounds buzzer and returns to weighing mode automatically.

Error.....The buzzer sounds and an error.

Code is displayed.

Error O Ht Err Refer to 14.5. Error Message for details.



0000g



8.2. Test Sample (Sodium Tartrate Dihydrate)

---Test sample (Sodium tartrate dihydrate, Na2C4H4O6 · 2H2O)---

Sodium tartrate dihydrate is the standard accessory to check the accuracy of measurement for the analyzer.

As an ideal substance on theory, sodium tartrate dihydrate includes a moisture content of 15.66% in the molecule. But the moisture content may change due to conditions of storage.

The moisture content of 15.0 to 16.0% is obtained by the method below. (Unit % is based on wet sample)

Sodium tartrate is contained in food (example : wine). If it may irritate the eyes and nose, wash it by with water.

The test sample can not be used repeatedly. Dispose of it as flammable matter.

Caution A hot sample pan may make error. Allow the pan to cool before the next test.

Measurement

1. Enter the following parameters.

2. Pre-heating process.


Put a sample pan, instead of a sample, on the pan. Press the START key to heat it. The analyzer temperature becomes equilibrium.

- 3. Press the RESET key to make zero display. Spread the sample as evenly as possible.
- Press the START key to start the measurement.
 The result is displayed after 8 minutes normally.
 If the results is between 15.0 to 16.0%, the analyzer works properly.
- 5. Press the following key to complete the measurement.

ENTER key Outputs (Prints) the results.

SELECT key Returns to the weighing mode.

RESET key Returns to the weighing mode and displays zero.





9. Connecting to a Printer

The analyzer can be connected to a compact thermal dot-matrix printer (AD-8121) using the RS-232C interface. The results and record adapted to GLP, GMP and ISO can be printed.

GLP: Good Laboratory Practice,

GMP: Good Manufacture Practice,

ISO: International Organization for Standardization

□ The statistical calculation data of the result and the graph data of the change of moisture content per one minute can be printed using the function of the AD-8121.


Use the AD-8121 accessory cable to connect them.

Setting List

Use	Ana	ılyzer sett	AD-8121 settings	
Ose	PrE	5-d	inFo	
Statistical calculation	0, 1	0	0, 1	MODE 1
Trace d of change of moisture content per one minute	2	0	0, 1	MODE 2 Interval printing
Data for GLP, GMP and ISO	0, 1, 2	0	1	MODE 3 Dump printing

Refer to "13. Function Table" to detail of settings.

Read the instruction manual of the printer.




Compact thermal dot-matrix printer (AD-8121)



10. Connecting to a Computer

- □ The analyzer can be connected to personal computer using the RS-232C interface.
- The analyzer is DCE (Data Communication Equipment).
 Use a straight-through type cable.

The MX-50 has the following standard accessory cable for RS-232C. If it is necessary to connect a cable to the MF-50, purchase the cable of accessory AX-MX-40. If purchasing the RS-232C cable on the market, check the interface connections and type.



- The MX-50 has the standard accessory software "WinCT-Moisture" for windows. It has the function to make graphs of the change of moisture content, etc. in realtime. Refer to "Readme.txt" of each language on the CD-ROM for the details.
- The MF-50 has the standard accessory software "WinCT" for windows. It can transmit data to a computer, can be used to monitor data and to check the measurement condition.

10.1. RS-232C Serial Interface

RS-232C Serial Interface

□ Transmission system

EIA RS-232C

□ Transmission form

Asynchronous, bi-directional, half duplex

Data format

Baud rate 2400bps

Data bits

7bits

Parity

EVEN 1bit

Stop bit Code

ASCII

Data bits

Start bit

Terminator

CR LF (CR: 0Dh, LF: 0Ah)

Bit format


RS-232C

-5 V to -15 V

0 +5 V to +15 V Stop bit

- Parity bit

Pin Connections



	MX-50 and	MF-50 (DCE)	Comp	uter (DTE)
Pin No.	Signal Name *2	Description	Direction	Signal Name
1	FG	Frame ground	•	FG
2	RXD	Receive data	-	TXD
3	TXD	Transmit data	→	RXD
4	RTS	Ready to send *3	J	RTS
5	CTS	Clear to send *3	→	CTS
6	DSR	Data set ready	→	DSR
7	SG	Signal ground		SG
16, 18, 19, 21, 23	Internal use		Do not co	nnect *1
Other	Not used			

^{*1:} Normal DOS/V cables do not use these terminals.

^{*2:} Signal names of the analyzer side are the same as the DTE side with TXD and RXD reversed.

^{*3:} RTS and CTS control are not used. RTS output is HI always.

10.2. Output Format

In Cas	se of Format omitted Temperature Data (Function Table 5-d 🗓)
	The format consists of fifteen characters except the terminator.
u	A polarity sign is placed before the data with the leading zeros. If the data is zero, the plus sign is used.
0	The unit is or
	Sign of ASCII code
	© 0Dh Carriage return
	Use OAh Line feed
	20h Space
-	Sample Mass Format (Gram Display)
	ST, +0001. 234gc_F
	Header Mass data Unit Terminator
	Trade data Sim formilator
	Positive Overload Format (Too heavy weighing, E display)
	OL, +999999E+1968-
	Header Polarity Overload Terminator
	Negative Overload Format (Too light weighing, FE display)
	OL, -999999E+19c _R -F
	Header Polarity Overload Terminator
	Moisture Content (during weighing or after weighing)
	ST, +00012. 34%CRLF
	Header Moisture content Unit Terminator
In Cas	se of Format included Temperature Data (Function Table 5-d /)
	The first 3 figures are the temperature data.
	The format consists of nineteen characters except the terminator.
	160, ST, +00012. 34%CRLF
	Header Moisture content Unit Terminator
	160°C at sample pan



10.3. Command

The analyzer can be controlled by the following commands from the computer. Add a terminator (ODh. OAh) to each command.

Command	Description
Q	Outputs the current data.
SIR	Outputs data continuously
С	Stops data output by SIR command.
QM	Outputs the data during measurement.
START	Same as the START key
STOP	Same as the STOP key
RESET	Same as the RESET key
ENTER	Same as the ENTER key
SELECT	Same as the SELECT key
DOWN	Same as the ↓ key
UP	Same as the ↑ key
PROGRAM	Same as the PROGRAM key



11. Data Memory Function

- The data memory function automatically stores each result when finishing a measurement. The maximum number of memory is 100 data sets in the MX-50, 50 data sets in the MF-50.
- The function can output the stored data to a printer at one time or to a computer, using the standard accessory CD-ROM, at one time.
- The function can delete the stored data at one time.
- □ The function can select either storing each result or not at dRER of the function table.


 Data is stored at each measurement

 Data is not stored

 □ dRER □
 □
- □ When using the function, MEM is displayed.
- When displaying Full, the function can not store the next data. The function can store new data after deleting the stored data.

Caution


- □ When pressing the STOP key during a measurement except manual mode, the result is not stored.
- ullet Set dRtR / before measurement, if it is necessary to store each result with data memory function.





11.1.1. Preparation

This example selects "store result" at dRER of the function table.


- 1. Display the gram unit (of the weighing mode).
- 2. Press and hold the SELECT key to enter the function table.
- 3. Press the SELECT key to display drief.
- 3. Press the SELECT key several times and press the or have to display delete.
















11.1.2. Output All Data at One Time



11.1.3. Delete All Data at One Time





12. Calibration

- The moisture content is calculated with a ratio of wet weight and dried weight. Therefore, the absolute value of weighing does not influence the calculation of the moisture content, but it is necessary to get precise weighing for GLP, GMP and ISO. Use a 20g mass or a 50g mass to calibrate the weighing sensor.
- When calibrating the weighing sensor, you can output the calibration report adapted to GLP, GMP and ISO.
- □ There is a certified temperature calibrator (accessory AX-MX-43, only for MX-50) to calibrate the pan temperature for precise temperature control.
- □ When calibrating the temperature, you can output the calibration report adapted to GLP, GMP and ISO.
- □ The analyzer can store an ID number to be used in the calibration report. The number can be used for management and maintenance of the analyzer

12.1. Identification Number (ID No.)

The ID number consists of the following seven characters.

Characters	n	1	2	3	4	5	6	7	Ω	9		pac		/	hvp	hor	-/-
	7	1	\ <u>-</u>	7	7 7	<u>۲</u>	-	7		0		μαυ	, C	<u> - '</u>	пур	illei	<u>!/</u>
Display	<u>u</u>	i	ر ر	בו	7	ב	b	$\lfloor I \rfloor$	ᆸ	_ 5					-	•	
	r <u>-</u>	_		_			_								,		
Characters	<u> </u>	В	C	D	E	F	G	H	[J	K	L	M	N	0	P	Q
Display	R	Ь	Γ	Н	F	F	ſ,	Н		.1	μ	1	-	Π		D	Q

Characters	R	S	T	U	٧	W	X	Υ	Z
Display	٦	7	Ł	Ш	ū	יַנ	11	y	L J

12.1.1. Setting the ID Number

1. Turn on the analyzer.

The gram unit (of weighing mode) is displayed.

- 2. Press and hold the SELECT key to enter the function table. Then [[RdJ]] is displayed.
- 3. Press the SELECT key several times to display ...d.
- 4. Press the ENTER key.
- 5. Set the ID number using the following keys.


Example: LRb - 123

SELECT key Selects a figure.

🖳 🚹 key...... Selects a value for the figure.

ENTER key Stores the ID No. and proceeds to step 6.

6. Press the RESET key to return to the weighing mode.



12.2. Calibration of the Weighting Sensor


- A standard mass of 20g or 50g can be used for the calibration
- □ A 20g standard mass (AX-MX-41) is recommend.

Caution

- Avoid vibration and drafts that affect the calibration. If affected, the analyzer may be unable to calibrate the weighing sensor.
- Use a 20g mass for the calibration, because the height between the weighing pan and glass-housing is 26 mm. If a tall mass is used, open the glass-housing and avoid external influence.

12.2.1. Operation

- 1. Display the gram unit (of the weighing mode).
- 2. Install the weighing pan, pan support and pan handle. Close the heater cover.
- 3. Press and hold the PROGRAM key to display [[H]].
- 4. Press the SELECT key to display [FRL].
- 5. Press the ENTER key to display [[RL 0]].
- 6. If 20g mass is used,......Press the ENTER key.
 Proceed to step 8.
 If 50g mass is used,.....Press the SELECT key.
 Proceed to step 7.
- 7. Press the or key to select 50.000g. Press the ENTER key to store it.
- 8. When displaying [RL 0], press the ENTER key to input "Data to display ZERO". The standard mass value is displayed (Example: 20g).
- 9. Open the heater cover and put the standard mass on the center of the pan and press the ENTER key to input "mass value". End is displayed.
- 10. Remove the mass to return to the weighing mode If the report for GLP, GMP and ISO is to be output (Refer to page 50), [GLP] is displayed. The output condition for the report is selected in the function table.




Calibration Report Example for the Weighing Sensor Adapted to GLP, GMP and ISO In case of the printer AD-8121, use MODE 3.

ID L DATE 2002 TIME 13 CALIBRATED CAL.WEIGHT	0:57:24 WEIGHT	Manufacture Model Serial number ID number Date Time } Calibration type } Calibration mass Signature

H

12.3. Calibration of Drying Temperature for MX-50

- □ The temperature calibrator (accessory AX-MX-43) adjusts the drying temperature on the pan. Put the sensor on the pan and input measurement data at 100°C and 160°C.
- Each adjustment needs fifteen minutes. The buzzer sounds at the end.
- u <u>k-up</u> is displayed after no adjustment for five minutes during the operation and calibration is stopped. Press any key to return to weighing mode.
- □ Refer to the instruction manual of the certified temperature calibrator (accessory AX-MX-43).



12.3.1. Operation

- 1. Replace the weighing pan with the sensor pan of the temperature calibrator.
- 2. Curve the sensor wire so it does not touch the heater cover and glass-housing when closing heater cover.


Level the sensor pan.


Do not leave a gap between the pan support and the sensor.


Level the sensor pan.

Curve the sensor wire so as not to touch heater cover.

- Turn on the analyzer.Display the gram unit (of the weighing mode)
- 4. Press and hold the PROGRAM key
- 5. Press the SELECT key to display &-[RL].
- 6. Press the ENTER key.
- 7. Press the START key to start the 100°C measurement.
- 8. After fifteen minutes, the buzzer sounds and blinks [100°C]. Adjust the blinking value to the thermometer value using the [1] or [1] key. (Example: 97°C)
- 9. Press the ENTER key to store the new data and to start the 160°C measurement.








When the heater cover is opened during measurement or the STOP key is pressed, calibration is stopped and the analyzer displays the weighing mode.



Calibration Report Example for Temperature Sensor Adapted to GLP, GMP and ISO In case of the printer AD-8121, use MODE 3.





13. Function Table

The function table can store the following parameters to control the analyzer.

Details of the Function Table

Item and Display	Symbol	Param- eter		Description			
Clock	CL Rau		e and time to built-in clock. o "5.2. Setting the clock and calendar"				
Decimal point	дP	0 *1	Dot " . " Comma " , "	Select decimal point of data.			
		<i>[]</i> *1	Key mode	Data is output by the ENTER key			
Data output	PrE	1	Auto print mode	Data is output after measurement.			
mode	11 [2	Stream mode	Data is output continuously during measurement.			
Data memory	dALA	U *1	Not used.				
function	unch	1	Data is stored at each measurement				
Form selection	5-d	<i>D</i> *1	Moisture content	is output.			
Form Selection	ם - כ	1	Moisture content	loisture content and temperature are output.*2			
Output format		□ *1	Not used				
adapted to GLP, GMP and ISO	inFo	1	Outputs calibration report that includes date a when finishing weighing sensor calibration or temperature sensor calibration.				
ID number	ıd	Set ID number. Used for the calibration report.					
Factory settings	[Lr	Resets	Resets the analyzer to the factory settings.				

^{*1:} Factory settings

^{*2:} Use this parameter when connected to a computer. The AD-8121 printer can not print this correctly.


13.1.1. Operation


1.	Display the gram unit (of the weighing mode).	0.000g
2.	Press and hold the SELECT key to enter the function table.	SELECT
		CL Adu
Salac	t an Item	1
	Select an item using the following keys.	SELECT:
	Example: Data output mode Prt is selected.	PrE
	SELECT key Selects a figure. ENTER key Enters to the selected item.	RESET
	RESET key Cancels the operation and	PP-E Ü
	returns to the weighing mode.	
Selec	t a Parameter	
4.	Select a parameter using the following keys.	
	Example: Auto print mode Prt / is selected. New parame , which was a parameter.	
	ENTER key Stores the parameter and proceeds to	OP L
	the next item.	
	RESET key Cancels the operation and returns	дяня —
	to the weighing mode.	1
5.	y = 1 the to the total total properties	RESET
	RESET key to return to the weighing mode.	0.000g
		g
_		
Exam	ple, Use Comma for Decimal Point	0000
1.	Proce and hold the COULTON Issues automate to the	QUUUg SELECT
	Press and hold the SELECT key to enter the function table.	
2.	Press the SELECT key to display dP.	EL Adu
	noy to display [III].	
		dP
3.	Press the ENTER key to enter the item. Last parameter	I ENTER
		Ogb U
4.	Press the ☐ or ↑ key to display ☐ ☐. New parameter	
	<u> </u>	d₽ ▲ 1
5.	Press the ENTER key to store the new parameter.	ENTER
_		PrE
6.	Press the RESET key to return to the weighing mode.	RESET
		0,000g



14. Maintenance

- □ Turn off the power switch and remove power cord during maintenance.
- Cool down all parts of the analyzer before maintenance.
- Pan support, sample pan and breeze break ring can remove.
- Clean the analyzer with a lint free cloth that is moistened with warm water and a mild detergent.
- Do not use organic solvents to clean the analyzer.
- Dry the parts and reassemble them. Refer to "2. Precautions" and "5.1. Installing the Instrument"
- □ Use the original packing material and box for transportation.







Example

14.1. Cleaning the Heater Unit

- □ Clean the glass-housing when it is stained (not clear) to maintain the drying performance.
- □ The glass-housing can be removed by removing two screws.
- Remove a fingerprints from the halogen lamp to keep its life.
- Do not touch to reflective surface of the metal reflector. If the surface is touched, it may be the cause of a drying temperature error.
- Do not touch the temperature sensor that is at the side of halogen lamp. If the surface is touched, it may be the cause of a drying temperature error.





Heater unit



14.2. Replacement of the Halogen Lamp

Replace the halogen lamp, when the drying time is excessive or the lamp is defective. Use the halogen lamp of accessory AX-MX-34-120V or AX-MX-34-240V that is adapted to your local voltage. The life of the halogen lamp is approximately 5000 hours.

Caution


- Remove power cord before replacement. If the power cord is not removed during lamp replacement, it may cause receiving an electric shock.
- Read the power supply voltage label on the back of the heater cover and confirm that the rated voltage of the halogen lamp is correct for your power supply voltage.


Voltage Label	The Rated Voltage of the Halogen Lamp	Accessory number
100 - 120 V	AC 120 V	AX-MX-34-120V
200 - 240 V	AC 240 V	AX-MX-34-240V


- □ Do not drop, throw or crack the halogen lamp. Broken glass may cause an injury.
- Clean the surface of the halogen lamp. If there is stain or fingerprint, it may shorten life of the halogen lamp. Do not touch the lamp directly.
- Dispose of a used halogen lamp that keeps its shape. If it is broken, glass may spread and cause of injury.
- We recommend you to replace halogen lamp, when it exceeds the rated life.
- Affix the lamp wire to the hook so that the lamp wire does not touch the glass-housing and heater cover.
- 1. Turn off the power switch and remove power cord.

There is downward projection.

- 2. Check rated voltage of the halogen lamp that is printed around the holder.
- 3. Check that the lamp is cool.
- 4. Remove the two screws holding the glass-housing.
- 5. Remove halogen lamp.
- 6. Install the new halogen lamp so that there is downward projection of the heat and light.
- 7. Affix the lamp wire to the hook.
- Affix the glass-housing with the two screws.Do not pinch the wire between the glass housing and lid.







14.3. Factory Settings

This function can set the following parameters to factory settings.

- All measurement programs
- All results stored in memory function.
- All parameters of the function table
- ID number is reset to 0000000.
- Order of calendar and date.

14.3.1. Operation

1. Turn on the analyzer.

The the gram unit (of the weighing mode) is displayed.

0,000g

2. Press and hold the SELECT key to enter the function table.

Ban

3. Press the SELECT key several times to display [[Lr]

SELECT [Lr

4. Press the ENTER key to enter the item.

[Lr ng

5. Press the ↓ or ↑ key to display [[Lr [g]].

Caution

If pressing the ENTER key with [Lr ng and pressing the RESET key, operation is canceled.



6. Press the ENTER key to reset. And End is displayed.

End

7. Press the RESET key to return to the weighing mode.


Cr 897

0,000g



14.4. Troubleshooting


- 1. In the Case that Proper Results are not be Obtained.
 - □ Use the self-check function. Refer to 8.1 Self-Check Function (Motion Check).
 - Check repeatability. (Weigh the same mass several times in the weighing mode.) A taller mass may touch the glasshousing. Use a short mass if possible. If a tall 50g mass is used, open the heater cover and avoid external influence.
 - □ The height from sample pan to glass-housing is 26 mm.
 - Check whether the test sample can be measured correctly.
 - Avoid the breeze form an air conditioner and vibration.
 - □ Check sample condition. Refer to 5.3.Proper Operation for Precision Measurement
 - □ Check measurement procedure and pre-heating process. Refer to 5.3.Proper Operation for Precision Measurement




- It requires six seconds to light the halogen lamp using the START key.
- When the heater cover is opened, power is not supplied to the halogen lamp.
- When an overheat has occurred, power is not supplied to the halogen lamp until the halogen lamp becomes cool.
- Check the rated voltage of the halogen lamp that printed around the holder.
- Read the power supply voltage label on the back of the heater cover and confirm that the rated voltage of the halogen lamp is correct for your power supply voltage.

	11,3	The Rated Voltage of the Halogen Lamp	Accessory number
100 - 120 V	AC 100 V to AC 120 V	AC 120 V	AX-MX-34-120V
200V - 240 V	AC 200V to AC 240 V	AC 240 V	AX-MX-34-240V

- Is a fuse blown? Check the fuses after removing the power cord. Check the rated value and put new fuses into the correct holders.
- Do you measure a lower drying temperature after a high drying temperature? If the lamp is hotter than the drying temperature, the measurement can not be started.
- Check that the sample pan is cool.
- Other cases, the halogen lamp may be defective.
 Replace with a new halogen lamp. Refer to "0.
 Replacement of the Halogen Lamp".



Maximum height of mass is 26 mm.



14.5. Error Message

[H no

Internal Error

An internal error indicated by the result of the self-check function. If repair is needed, contact the local A&D dealer.

[L PF

Clock Battery Error

Press any key and input the date and time. Refer to "5.2. Setting the Clock and Calendar".

[L Err

Clock Error

Contact the local A&D dealer to repair the analyzer.

CLoSE

Heater Cover Error

The heater cover is opened when starting self-check function. If it is closed, the self-check function is started.

ErrorB |

Internal Error

Trun the power switch off and then on .

Check the frequency of the power supply.

Contact the local A&D dealer to repair the analyzer, if the error is not cleared.

Error3 Error8

IC Error

Contact the local A&D dealer to repair the analyzer.

Error9 Ht Err

Temperature Control Error

Contact the local A&D dealer to repair the analyzer, if an error is not cleared when turning the power switch off for more than a half hour and recheck it.

t-UP

Time Error at Temperature Calibration

There is no key operation for five minutes during temperature calibration. If pressing any key, the weighing mode is displayed.

Ε

Positive Overload, Overweight

The sample has exceeded the weighing capacity.

If the weighing sample pan is empty and this error is displayed, contact the local A&D dealer to repair the analyzer.

-E

Negative Overload, Sample Pan Error

The weight value is too light.

Check the pan, pan support and press the RESET key.

Calibrate the weighing sensor.

If an error can be not cleared, contact the local A&D dealer to repair the analyzer.

MEM

Full Memory

FUL The num

The number of results stored in memory has reached the upper limit.

Clear the data to store the new results. Refer to "11. Data Memory Function".




15. Specifications

		MX-50	MF-50			
Measuremer	nt method	400 W halogen lamp, th	ermogravimetric analysis			
	ature range at sample pan	50 °C to 200 °C	(1 °C increments)			
Drying temper	·· · · · · · · · · · · · · · · · · · ·	Standard drying, Lamp drying, Step drying				
Temperature		By Accessory AX-MX-43				
Sample weig		0.1 g t	to 51 g			
		ent, (Standard deviation)				
Moisture	over 5 g sample	0.02%	0.05%			
content *1	over 1 g sample	0.1%	0.2%			
Weighing		0.001g	0.002g			
Minimum rea						
Moisture of	·	0.01%, 0.1%	0.05%, 0.1%, 1%			
Weighing		0.001g	0.002g			
Measuremer	nt programs					
		Set accuracy from HI, MID	or LO and drying			
		temperature. Sample weig	ght and termination value			
!	Standard mode	is set automatically. Wher	drying rate reaches fixed			
		termination value, measur	rement is automatically			
A ! !	11	completed. (*2)				
Analyzing	User mode	1240				
mode	Automatic complete	When drying rate is less than preset termination				
	mode	value, measurement is automatically completed. (*2)				
	Timer mode	After heating for the preset drying time, measurement				
		is automatically stopped. (1min. to 480 min.)				
	Manual mode	When pressing the key at any time, measurement				
		is stopped and the result				
		Moisture content (Wet-base)				
Measureme	ant unit	Moisture content (Dry-base, Atro)				
Measureme	ant Gint	Dry content				
		Ratio				
Number of	f memory	Weight (g) 20 sets	100			
Data memor			10 sets			
Communicat		Storage of 100 results RS-232C serial interface	Storage of 50 results			
	oftware for Windows	WinCT-Moisture	WinCT			
(CD-ROM)	Citatale for validows	i	WinCT			
		Analyzing utility Communication software				
Operation en	vironment	5 °C to 40 °C (41°F to 104°F),				
Sample pan		85%RH or less (no condensation) \$\phi 85 \text{ mm}\$				
Power source,		 '	AC 200 V to 240 V 1 5A			
		AC 100 V to 120 V, 3A or AC 200 V to 240 V, 1.5A				
Maximum cu		50Hz or 60Hz, Approximately 400W				
Maximum co	nsumption	Please confirm that this instrument is correct for your local voltage and receptacle type.				
External dim	ensions	215(W) x 320(D) x 173(H)mm, 8.46(W) x 12.60(D) x 6.81(H)in.				
Mass (Net we	eiaht)					
*1: After probact		Approximately 6kg (without accessories)				

After preheating the analyzer, the data can be obtained with approximately 5 g test sample (Sodium tartrate dihydrate) in standard mode (MID), standard drying, 160 °C When change of moisture content per one minute reaches the preset termination value, the measurement is completed.



봊 15.1. Dimensions





15.2. Accessories and Peripheral Equipment

Accessories

Name	Order number
Sample pan (685 mm, 100 pcs)	AX-MX-31
Glass fiber sheet (φ70 mm, 100 sheets)	AX-MX-32
Test sample (Sodium tartrate dihydrate, 30gx12 pcs)	AX-MX-33
Halogen lamp for AC 100V to 120 V	AX-MX-34-120V
Halogen lamp for AC 200V to 240 V	AX-MX-34-240V
Pan handle (2 pcs)	AX-MX-35
Tweezers (2 pcs)	AX-MX-36
Spoon (2 pcs)	AX-MX-37
Display cover (5 pcs)	AX-MX-38
Dust cover	AX-MX-39
RS-232C cable (2m, 25 pins - 9 pins)	AX-MX-40
Calibration mass (20g, equivalent to OIML class F1)	AX-MX-41
WinCT-Moisture (CD-ROM: Application software for Windows)	AX-MX-42
Certified Temperature calibrator (only for MX-50)	AX-MX-43

Peripheral equipment

AD-8121 Dot matrix compact printer

Function:

Statistical function, interval printing, chart printing,

Character:

5x7 dot, height 2.5mm/01.in., 16 characters/line

AC adapter or alkaline batteries Power source:



¥ 16. Index

%/min 17, 22	[Lr Go 54
ENTER key 13	Comma 50
PROGRAM	Command 42
, PROGRAM key 13	Continuous measurement 16
RESET key 13	CR 41
	CTS 40
SELECT key 13	d위೬위 43, 50
(STOP), START key 13	Data bits 40
	Data memory 43
stop key 13	Data memory function 50
	Data output mode 50
▼ ▽ Lamp drying13, 27, 29	Decimal point 50
▼ Step drying13, 27, 29	Display 12
Sign Δ14	Display cover11
and key13	dōy 15 Dot 50
	dP 50
Operation state indicator12	Dried sample mass 23
Level indicator 12	Dry content 23
	Drying program 13, 21
ACCURACY17, 21, 22	Drying rate 17, 21
AD-812138, 58	Drying temperature 21, 22, 28, 30, 48
Ambient condition5	DSR 40
Analyzing mode21, 22	Dust cover 11
Automatic mode	E 56
Automatic mode8, 21, 22	- <i>E</i> 56
Baud rate40	Earth terminal 14
Breeze break ring6, 10, 11, 14 Bubble spirit level10, 14	ENTER key 13
Calendar15	Error 0 56
Calibration45	Error3 56
Calibration report47, 49	Error8 56
Cancel key13	Error9 56
EH36	Factory settings 50
[H na56	FG
CH PRSS36	FULL 43, 56 Fuse 10, 11
Character45	Glass-housing6, 10, 11, 53
EL PF56	<i>GLP</i> 47, 49
EL AdJ50	GLP 38, 46, 49, 50
[L Err56	GMP 38, 46, 49, 50
[La5E36, 56	Gram value 23
Clock15, 50	Grip6, 10
<i>[Lr</i> 44, 50	Halogen lamp 5, 8, 10, 11, 14, 53, 55
	5 2, 5, 15, 17, 17, 50, 50

Heater cover	10, 39, 40 40 21 -6, 10, 11 41, 50 13
## Err	40 21 -6, 10, 11 41, 50 13
RXD	40 21 -6, 10, 11 41, 50 13
Indicators 50 Sample mass Sample mass Sample pan 5-d Select key Solution Select key Select key Solution Select key Select key	21 -6, 10, 11 41, 50 13
Indicators 50 Sample mass Sample mass Indicators 5-d Select key Indicators 50 Select key	-6, 10, 11 41, 50 13 40
D number	-6, 10, 11 41, 50 13 40
Indicators	41, 50 13 40
inF ₀ 50. SELECT key	13 40
SO SG SG	40
, , ,	
Key mode Sodium tartrate dihydrate	
Keys 12 Spoon	
Lamp drying27, 29 Standard accessories	
Leveling foot	
LF41 Standard mode	•
LO	
Manual mode8, 21	
· · · · · · · · · · · · · · · · · · ·	•
ਜੇਰੁੱਧੰ	
Measurement program21 STOP key	
MEM20, 43, 56 Stream mode	
MID	
MOIST /D23 Temperature	
MOIST /W23 Temperature sensor	
Moisture content23, 45, 50 Terminator	-
out44 Test sample	•
Output format41, 50 Thermogravimetric analysis	
Pan handle10, 11, 14 Thermometer	
Pan support10, 11, 14 Timer mode	
Parity 40 Test sample	
Polarity	
Power cord 10, 11 Tweezers	
Power input 10 TXD	
Power supply voltage label5, 14, 55	,
Power switch 10, 14 $U = \bar{n}$	13, 21
Pre-heating process16 Unit16	23, 41
Printer 38, 58 User mode	21
PROG20	13, 21
PROGRAM key13 Weighing sensor13	45, 46
Prt Wet sample mass	23
Ratio23 WinCT	
RATIO D/W23 WinCT-Moisture23	8, 39
RATIO W/D23	
Reference card10 zero display	
Repeatability16	



A&D Company, Limited

3-23-14 Higashi-Ikebukuro, Toshima-ku, Tokyo 170-0013 JAPAN Telephone: [81] (3) 5391-6132 Fax: [81] (3) 5391-6148

A&D ENGINEERING, INC.

1555, McCandless Drive, Milpitas, CA. 95035 U.S.A. Telephone: [1] (408) 263-5333 Fax: [1] (408)263-0119

A&D INSTRUMENTS LTD.

Unit 24/26 Blacklands Way, Abingdon Business Park, Abingdon, Oxon OX14 1DY United Kingdom Telephone: [44] (1235) 550420 Fax: [44] (1235) 550485

<German Scales Office>

Berner Straße 64, 60437 Frankfurt/Main 50 GERMANY Telephone: [49] (69) 507-1017 Fax: [49] (69) 507-2054

A&D MERCURY PTY. LTD.

32 Dew Street, Thebarton, South Australia 5031 AUSTRALIA Telephone: [61] (8) 8352-3033 Fax: [61] (8) 8352-7409

A&D KOREA Limited

8th Floor, Manhattan Bldg. 36-2 Yoido-dong, Youngdeungpo-ku, Seoul, KOREA Telephone: [82] (2) 780-4101 Fax: [82] (2) 782-4280