



# User Manual

PCE-XXM 20 Colorimeter



User manuals in various languages (français, italiano, español, português, nederlands, türk, polski, русский, 中文) can be found by using our product search on: [www.pce-instruments.com](http://www.pce-instruments.com)

Last change: 1 August 2019  
v1.0



## Contents

<b>1</b>	<b>Safety notes</b> .....	<b>1</b>
<b>2</b>	<b>Working principle</b> .....	<b>2</b>
<b>3</b>	<b>Technical specifications</b> .....	<b>3</b>
<b>4</b>	<b>Device description</b> .....	<b>3</b>
<b>5</b>	<b>Operation</b> .....	<b>4</b>
5.1	Powering On and Off .....	4
5.2	Calibration .....	5
5.3	Comparative measurement .....	6
5.4	Checking XYZ, RGB, CMYK and Pantone values .....	6
<b>6</b>	<b>Functions menu</b> .....	<b>7</b>
6.1	Set time .....	7
6.2	Set language .....	8
6.3	Energy saving .....	9
6.4	Set number of measurements for average calculation .....	9
6.5	Set tolerance .....	9
6.6	Set colour formula .....	9
6.7	USB connection .....	10
6.8	Bluetooth connection .....	10
<b>7</b>	<b>Memory</b> .....	<b>10</b>
<b>8</b>	<b>Charging the battery</b> .....	<b>10</b>
<b>9</b>	<b>Troubleshooting</b> .....	<b>11</b>
<b>10</b>	<b>Warranty</b> .....	<b>12</b>
<b>11</b>	<b>Disposal</b> .....	<b>12</b>

## 1 Safety notes

Please read this manual carefully and completely before you use the device for the first time. The device may only be used by qualified personnel and repaired by PCE Instruments personnel. Damage or injuries caused by non-observance of the manual are excluded from our liability and not covered by our warranty.

- The device must only be used as described in this instruction manual. If used otherwise, this can cause dangerous situations for the user and damage to the meter.
- The instrument may only be used if the environmental conditions (temperature, relative humidity, ...) are within the ranges stated in the technical specifications. Do not expose the device to extreme temperatures, direct sunlight, extreme humidity or moisture.
- Do not expose the device to shocks or strong vibrations.
- Avoid corrosive media and heavy dust.
- The case should only be opened by qualified PCE Instruments personnel.
- Never use the instrument when your hands are wet.
- You must not make any technical changes to the device.
- The appliance should only be cleaned with a damp cloth. Use only pH-neutral cleaner, no abrasives or solvents.
- The device must only be used with accessories from PCE Instruments or equivalent.
- Before each use, inspect the case for visible damage. If any damage is visible, do not use the device.
- Do not use the instrument in explosive atmospheres.
- The measurement range as stated in the specifications must not be exceeded under any circumstances.
- This instrument contains a lithium battery. Therefore, avoid high temperatures and strong magnetic environments to protect the battery from damage.
- Non-observance of the safety notes can cause damage to the device and injuries to the user.

We do not assume liability for printing errors or any other mistakes in this manual.

We expressly point to our general guarantee terms which can be found in our general terms of business.


If you have any questions please contact PCE Instruments. The contact details can be found at the end of this manual.



### 3 Technical specifications

Color space	CIELAB CIEXYZ RGB, Pantone, CMYK
Color difference formula	$\Delta E^*_{Lab}$ (CIE76/CIE94)
Measuring aperture	Ø 8mm
Measuring geometry	45°/diffused illumination
Type of light source	LED
Sensor	RGB silicon photoelectric diode
Viewing angle	CIE 10°Standard angle
Measurement interval	1.5 s
Battery	Li-ion battery, chargeable via USB
Operating conditions	0 ... 40 °C <80 %
Storage conditions	10 ... 30 °C <70 %

### 4 Device description



#### 1. LC display

Shows colour information, status and options

#### 2. MEAS button

Press to measure

#### 3. Up button

Move cursor up

#### 4. Left button

Move cursor left

#### 5. Down button

Move cursor down

#### 6. Speaker

For beeping sound

#### 7. MEAS/ENTER button

Selects menu items and shows notes

#### 8. Right button

Move cursor right

#### 9. Power button

Turns instrument on and off

#### 10. USB port

For charging and software connection

#### 11. Measurement optics


Illumination of measuring area, colour measurement

#### 12. White reference slider

Positions the calibration tile for measurement or calibration/storage



## Front, side and rear view



## 5 Operation

### 5.1 Powering On and Off

Turn on the instrument by pressing the Power button. The start screen looks as follows:



To turn off the meter, press the Power button again.

## 5.2 Calibration

When your instrument is first turned on, you should perform a calibration. Thereafter, a calibration is required every hour or if a 5 °C temperature change has occurred. Calibration of the instrument ensures optimum colour matching performance.

1. Move the white reference slider to the closed/calibration position over the optics.
2. Power on the instrument, then go the "Calibration" menu (left button – down button until cursor is on "Calibration" – confirm with MEAS/ENTER). The display will show the following:



3. Use the arrow keys to select "StandWhite" and press MEAS to initiate the calibration.
4. Open the optics and align the measuring aperture in the air without aligning it directly with a light source. Go to the "Calibration" menu and select "StandZero". Then press the MEAS key to carry out the calibration.
5. If the calibration was successful, "StandWhite" or "StandZero" will be ticked. If not, there will be an "X" instead.
6. Make sure to always reposition the slider back to "Measure" location (optics opened) before making a measurement.

**Note:** The calibration reference is dramatically affected by smudge marks and dust and must be kept clean. It is recommended that the instrument is cleaned regularly.

### 5.3 Comparative measurement

Power on the instrument, initiate a calibration and then do measurement on selected standard sample (Select standard from main menu – Standard or use your own standard). Press button MEAS or MEAS/ENTER to measure and get the measurement result as shown in photo 1. If the measurement has already been made or if the measuring time was too short, an error message will appear. The result will be shown as in photo 1. When the value has stabilised, press right button to view more results as in photo 2. Then measure your desired sample by pressing MEAS or MEAS/ENTER.

S = standard measurement value  
 B = sample reading  
 $\Delta E$  = overall colour difference

The meter will then compare the test results and either show “Pass” (photo 2.1, high conformity) or “Fail” (photo 2.2, low conformity).

The three mentioned values will be saved to the memory automatically.



Photo 1



Photo 2




Photo 2.1



Photo 2.2

### 5.4 Checking XYZ, RGB, CMYK and Pantone values

After a measurement, when the display looks as in photo 1, press the up or down key to check the XYZ, RGB, CMYK or Pantone value (as shown in photo 2).




Photo 1



Photo 2

## 6 Functions menu

After powering on, press the left key to enter the main menu that looks as follows:



### 6.1 Set time

In the "Settings" menu, press the up and down keys to select "DateTime" and confirm with MEAS/ENTER. Go to the respective menu items by using the up and down keys and press MEAS/ENTER to be able to change the values. Set the hours and then the minutes by using the arrow keys. The seconds cannot be changed. Confirm the individual entries with the MEAS/ENTER key.





## 6.2 Set language

In the main menu, go to "Settings" by pressing the up and down keys and confirm with MEAS/ENER. The display will show the following:



On this page, select "MeterSetup" in the same way to enter the following page:



Confirm with MEAS/ENTER. You can then change the language (English or Chinese) with the up and down keys. After making your selection, confirm with MEAS/ENTER.

### 6.3 Energy saving

To save energy, you can set a time after which the display backlight or the device itself switches off automatically. When you are in the main menu, use the up and down keys to select “Settings” and confirm with the MEAS/ENTER key. Then select “MeterSetup” with the arrow keys and confirm with MEAS/ENTER again get to the respective submenus.

These submenus SreenOff and PowerOff can be opened with the MEAS/ENTER key. Changes can be made by using the up and down keys and confirmed with MEAS/ENTER.

The following can be selected:

SreenOff: 1 ... 99 seconds

PowerOff: Off (No), 10, 20, 30 minutes

### 6.4 Set number of measurements for average calculation

In the “Settings” menu, select “MeasSetup” with the up and down keys and confirm with MEAS/ENTER. Go to the menu item “AverTime” by using the up and down keys and press MEAS/ENTER. Now set the desired number of measurements you want to be included in the average calculation with the up and down keys and confirm with MEAS/ENTER.

### 6.5 Set tolerance

In the “Settings” menu, select “MeasSetup” with the up and down keys and confirm with MEAS/ENTER. Go to the menu item “DeSetting” by using the up and down keys and press MEAS/ENTER. Now set the desired tolerance with the up and down keys and confirm with MEAS/ENTER. A tolerance of 1.0 is preset.




### 6.6 Set colour formula

In the “Settings” menu, select “MeasSetup” with the up and down keys and confirm with MEAS/ENTER. Go to the menu item “Delta-E” with the down key and press MEAS/ENTER. Now select the desired colour formula (CIE76 or CIE94) by using the up and down keys and confirm with MEAS/ENTER.



## 6.7 USB connection

Connect the meter to your computer by using the Micro USB cable. The colour meter is recognised as a HID device and all drivers will be installed automatically. When the installation is completed, the PCE-XXM 20 will be recognised as follows:



Download the PC software from the following link:

[https://www.pce-instruments.com/english/download-win\\_4.htm](https://www.pce-instruments.com/english/download-win_4.htm)

Install and start the software. Further instructions can be found in the help file of the software.

### Note:

The meter can only connect to the software if the USB icon is shown in the upper left part of the display.

## 6.8 Bluetooth connection

Connect the instrument to smartphone via Bluetooth to transfer the measuring data to the Android or iOS app.



## 7 Memory

The colour meter has memory capacity for up to 20 groups of data (S = standard measurement value, B = sample reading, DE = overall colour difference) which are saved automatically after a comparative measurement. In order to read out the memory, go to the menu item "DataLog" in the main menu and confirm with the MEAS/ENTER key. To view a group of data, select it by means of the up and down keys and confirm your selection with MEAS/ENTER. With the arrow right key, you can delete the selected individual group of data. To delete all groups of data, select "Delete All" from the overview and confirm with MEAS/ENTER.

### Note:

When clearing the complete memory, you will not be asked to confirm that you wish to delete all data.

## 8 Charging the battery

Before using the colorimeter for the first time, it is important that you fully charge the battery. Otherwise, the internal lithium-ion battery may experience a shortened life.

The meter can be charged when switched off or when switched on. However, operation during charging is not possible. Connect the supplied USB cable or a USB cable of the same type to the colour meter and to your computer's USB port. If the meter is on, you will see this icon  when the meter is charging. A full charge of a completely empty battery will take approx. 6 hours.

### Battery icon information



fully charged



half charged - sufficient for a substantial number of measurements



low - measurements still possible but battery should be charged soon



charging.

## 9 Troubleshooting

Variables that may affect the measuring results and should be avoided include:

- Sensor blocked
- Environmental temperature too low – slow display reaction, limited accuracy
- Improper use of the instrument or unsuitable sample:
  - The instrument does not lie flat on the sample.
  - The sample has an uneven texture.
  - The sample is dirty.
  - The sample contains fluorescent, metallic, or pearlescent colorants.
  - The sample looks different when viewed at different angles.



## 10 Warranty

You can read our warranty terms in our General Business Terms which you can find here: <https://www.pce-instruments.com/english/terms>.

## 11 Disposal

For the disposal of batteries in the EU, the 2006/66/EC directive of the European Parliament applies. Due to the contained pollutants, batteries must not be disposed of as household waste. They must be given to collection points designed for that purpose.

In order to comply with the EU directive 2012/19/EU we take our devices back. We either re-use them or give them to a recycling company which disposes of the devices in line with law.

For countries outside the EU, batteries and devices should be disposed of in accordance with your local waste regulations.

If you have any questions, please contact PCE Instruments.



## PCE Instruments contact information

### Germany

PCE Deutschland GmbH  
Im Langel 4  
D-59872 Meschede  
Deutschland  
Tel.: +49 (0) 2903 976 99 0  
Fax: +49 (0) 2903 976 99 29  
info@pce-instruments.com  
www.pce-instruments.com/deutsch

### Germany

Produktions- und  
Entwicklungsgesellschaft mbH  
Im Langel 26  
D-59872 Meschede  
Deutschland  
Tel.: +49 (0) 2903 976 99 471  
Fax: +49 (0) 2903 976 99 9971  
info@pce-instruments.com  
www.pce-instruments.com/deutsch

### The Netherlands

PCE Brookhuis B.V.  
Institutenweg 15  
7521 PH Enschede  
Nederland  
Telefoon: +31 (0)53 737 01 92  
Fax: +31 53 430 36 46  
info@pcebenelux.nl  
www.pce-instruments.com/dutch

### United States of America

PCE Americas Inc.  
711 Commerce Way suite 8  
Jupiter / Palm Beach  
33458 FL  
USA  
Tel: +1 (561) 320-9162  
Fax: +1 (561) 320-9176  
info@pce-americas.com  
www.pce-instruments.com/us

### France

PCE Instruments France EURL  
23, rue de Strasbourg  
67250 Soultz-Sous-Forêts  
France  
Téléphone: +33 (0) 972 3537 17  
Numéro de fax: +33 (0) 972 3537 18  
info@pce-france.fr  
www.pce-instruments.com/french

### United Kingdom

PCE Instruments UK Ltd  
Unit 11 Southpoint Business Park  
Ensign Way, Southampton  
Hampshire  
United Kingdom, SO31 4RF  
Tel: +44 (0) 2380 98703 0  
Fax: +44 (0) 2380 98703 9  
info@industrial-needs.com  
www.pce-instruments.com/english

### Chile

PCE Instruments Chile S.A.  
RUT: 76.154.057-2  
Calle Santos Dumont N° 738, Local 4  
Comuna de Recoleta, Santiago  
Tel. : +56 2 24053238  
Fax: +56 2 2873 3777  
info@pce-instruments.cl  
www.pce-instruments.com/chile

### Turkey

PCE Teknik Cihazları Ltd.Şti.  
Halkalı Merkez Mah.  
Pehlivan Sok. No.6/C  
34303 Küçükçekmece - İstanbul  
Türkiye  
Tel: 0212 471 11 47  
Faks: 0212 705 53 93  
info@pce-cihazlari.com.tr  
www.pce-instruments.com/turkish

### Spain

PCE Ibérica S.L.  
Calle Mayor, 53  
02500 Tobarra (Albacete)  
España  
Tel. : +34 967 543 548  
Fax: +34 967 543 542  
info@pce-iberica.es  
www.pce-instruments.com/espanol

### Italy

PCE Italia s.r.l.  
Via Pesciatina 878 / B-Interno 6  
55010 Loc. Gragnano  
Capannori (Lucca)  
Italia  
Telefono: +39 0583 975 114  
Fax: +39 0583 974 824  
info@pce-italia.it  
www.pce-instruments.com/italiano

### Hong Kong

PCE Instruments HK Ltd.  
Unit J, 21/F., COS Centre  
56 Tsun Yip Street  
Kwun Tong  
Kowloon, Hong Kong  
Tel: +852-301-84912  
jyi@pce-instruments.com  
www.pce-instruments.cn

### China

PCE (Beijing) Technology Co., Limited  
1519 Room, 6 Building  
Zhong Ang Times Plaza  
No. 9 Mentougou Road, Tou Gou District  
102300 Beijing  
China  
Tel: +86 (10) 8893 9660  
info@pce-instruments.cn  
www.pce-instruments.cn