TSURUGA

MODEL 3585

Digital Resistance Meter

Operation Manual

I-02455

	Contents
1. Pref	ace 1
1.1 Prep	parations prior to use ······2
1.2 Cont	firmation prior to use ······2
1.3 War	ning and caution during measurement3
2. Nam	e of parts······4
2.1 Fron	t panel ······4
2.2 Rear	panel
2.3 Disp	lay Portion6
3. Basi	c operation method ······7
	er supply······7
	nection of measuring terminals ·······7
	Connection of measuring terminals (Model 5813-21B : Option)
	Connection of temperature measurement terminals
51212	(Temperature sensor Model 5803-11 : Option)
3.3 Star	tup display (Self-check) ·······8
	surement ·······
	lock
	adjustment ·······11
	ng operation ······· 12
4 1 Sett	ing flow
	ing flow
4.1.1	MEMORY SET flow
4.1.1 4.1.2	MEMORY SET flow 13 GENERAL SET flow 14
4.1.1 4.1.2 4.1.3	MEMORY SET flow
4.1.1 4.1.2 4.1.3 4.2 Men	MEMORY SET flow 13 GENERAL SET flow 14 SYSTEM SET flow 14
4.1.1 4.1.2 4.1.3 4.2 Men	MEMORY SET flow 13 GENERAL SET flow 14 SYSTEM SET flow 14 nory 15
4.1.1 4.1.2 4.1.3 4.2 Men 4.3 MEM	MEMORY SET flow 13 GENERAL SET flow 14 SYSTEM SET flow 14 hory 15 IOREY SET 16
4.1.1 4.1.2 4.1.3 4.2 Men 4.3 MEM 4.3.1	MEMORY SET flow 13 GENERAL SET flow 14 SYSTEM SET flow 14 nory 15 IOREY SET 16 Selection of Memory 17
4.1.1 4.1.2 4.1.3 4.2 Men 4.3 MEM 4.3.1 4.3.2	MEMORY SET flow 13 GENERAL SET flow 14 SYSTEM SET flow 14 nory 15 IOREY SET 16 Selection of Memory 17 Setting of Measurement function 17
4.1.1 4.1.2 4.1.3 4.2 Mem 4.3 MEM 4.3.1 4.3.2 4.3.3	MEMORY SET flow 13 GENERAL SET flow 14 SYSTEM SET flow 14 nory 15 IOREY SET 16 Selection of Memory 17 Setting of Measurement function 17 Setting of Measurement range 18
4.1.1 4.1.2 4.1.3 4.2 Men 4.3 MEN 4.3.1 4.3.2 4.3.3 4.3.4	MEMORY SET flow 13 GENERAL SET flow 14 SYSTEM SET flow 14 nory 15 NOREY SET 16 Selection of Memory 17 Setting of Measurement function 17 Setting of Measurement range 18 Setting of comparator 19
4.1.1 4.1.2 4.1.3 4.2 Men 4.3 MEN 4.3.1 4.3.2 4.3.3 4.3.4 4.3.5 4.3.6	MEMORY SET flow 13 GENERAL SET flow 14 SYSTEM SET flow 14 hory 15 IOREY SET 16 Selection of Memory 17 Setting of Measurement function 17 Setting of Measurement range 18 Setting of comparator 19 Ratio display 20
4.1.1 4.1.2 4.1.3 4.2 Men 4.3 MEM 4.3.1 4.3.2 4.3.3 4.3.4 4.3.5 4.3.6 4.3.7	MEMORY SET flow 13 GENERAL SET flow 14 SYSTEM SET flow 14 hory 15 IOREY SET 16 Selection of Memory 17 Setting of Measurement function 17 Setting of Measurement range 18 Setting of comparator 19 Ratio display 20 Zero adjustment 22
4.1.1 4.1.2 4.1.3 4.2 Men 4.3 MEM 4.3.1 4.3.2 4.3.3 4.3.4 4.3.5 4.3.6 4.3.7	MEMORY SET flow 13 GENERAL SET flow 14 SYSTEM SET flow 14 nory 15 IOREY SET 16 Selection of Memory 17 Setting of Measurement function 17 Setting of Measurement range 18 Setting of comparator 19 Ratio display 20 Zero adjustment 22 Temperature correction (T.C.) 23
4.1.1 4.1.2 4.1.3 4.2 Men 4.3 MEN 4.3.1 4.3.2 4.3.3 4.3.4 4.3.5 4.3.6 4.3.7 4.4 GEN	MEMORY SET flow 13 GENERAL SET flow 14 SYSTEM SET flow 14 nory 15 NOREY SET 16 Selection of Memory 17 Setting of Measurement function 17 Setting of Measurement range 18 Setting of comparator 19 Ratio display 20 Zero adjustment 22 Temperature correction (T.C.) 23 ERAL SET 24
4.1.1 4.1.2 4.1.3 4.2 Men 4.3 MEN 4.3.1 4.3.2 4.3.3 4.3.4 4.3.5 4.3.6 4.3.7 4.4 GEN 4.4.1	MEMORY SET flow 13 GENERAL SET flow 14 SYSTEM SET flow 14 hory 15 IOREY SET 16 Selection of Memory 17 Setting of Measurement function 17 Setting of Measurement range 18 Setting of comparator 19 Ratio display 20 Zero adjustment 22 Temperature correction (T.C.) 23 ERAL SET 24 Setting of Sampling 25
4.1.1 4.1.2 4.1.3 4.2 Mem 4.3 MEM 4.3.1 4.3.2 4.3.3 4.3.4 4.3.5 4.3.6 4.3.7 4.4 GEN 4.4.1 4.4.2	MEMORY SET flow 13 GENERAL SET flow 14 SYSTEM SET flow 14 nory 15 IOREY SET 16 Selection of Memory 17 Setting of Measurement function 17 Setting of Measurement range 18 Setting of comparator 19 Ratio display 20 Zero adjustment 22 Temperature correction (T.C.) 23 ERAL SET 24 Setting of Sampling 25 Selection of memory setting by rear panel control 25

Contonto

4.5 SYS	TEM SET30
4.5.1	Setting of contrast ······30
4.5.2	Display of equipment information ·······3
5. Exte	ernal control ·······32
5.1 Con	trol terminal·······32
5.1.1	Terminal arrangement ·······32
5.1.2	Connection ····································
5.1.3	Input / output signal ·······33
5.1.4	External control timing chart ······34
	Memory operation 36
5.1.6	Internal circuit configuration
6. Com	nmunication (RS-232C)·······38
6.1 Spe	cification ······38
6.1.1	Communication specification
6.1.2	Connecter pin arrangement ······ 38
6.1.3	Operation
6.2 List	of communication command and response4(
7. Ana	log output (Option) ······54
7.1 Out	put specifications ······54
	output (Option) 55
	put specifications ······55
	TTL output (-03)
	Open collector output (-04) ······55
	nector pin array
	cription of input and output signals57
	Output signal57
	Input signal ······58
9. Erroi	r display ······ 62
	e in panel-mount ······ 63
	sembly drawing ······ 63
10.2 Ex	ternal dimensions when fitted with panel-mount bracket
11. Mai	ntenance ······ 64
12. Fail	ure symptom ······ 64
13. Sp	ecifications
13.1 Mc	del name······65
13.2 Me	easuring range and accuracy ······65
13.3 Ge	neral specifications······67
13.4 Ad	aptability ······69
13.5 Ini	tial setting list (at the factory shipment) ······70
13.6 Ex	ternal dimensions······7

This page is blank.

1. Preface


The model 3585 is a digital resistance meter used for measuring resistance of motors, coils and etc.

3585 can perform the measurement with high speed samplings 90 times/sec with wide range of measurement from $30m\Omega$ to $300 k \Omega$, with high resolution of $1\mu\Omega$ and with high accuracy. Furthermore, temperature correction function and ratio display are originally equipped with 3585.

We would like to thank you for your purchase of our MODEL 3585. For safety and proper use of this product, please carefully read this operation manual before the use.

This product should be handled by persons having good knowledge in electricity.

The following symbol marks are used in this manual for the safety use of the product.



Caution This is the caution to avoid danger. Minor injury to the user or physical obstacle may occur in case the product is mishandled.

▲ Warning

- Do not open the case or modify the main body.
- Never touch the terminals when power is ON. There may be risk of electric shock.

▲ Caution

- The instrument may be damaged if testing method not specified by manufacturer is used. Read the instruction manual carefully and understand the contents before the use.
- The rated data for warm up is specified for more than 30 minutes.
- To avoid break-down, malfunction or deterioration of life time, do not use this product in such places where:
 - Exposed to rain, water drops or direct sunlight.
 - ♦ High temperature or humidity, heavy dust or corrosive gas.
 - Affected by external noise, radio waves or static electricity.
 - ♦ Where there is constant vibration or shock.
- Store this product at -20 to 70 $^{\circ}$ C.
- Wipe off front panel and housing with dry soft cloth. If necessary, use cloth with small amount of synthetic detergent for cleaning.
 Do not use an organic solvent such as thinner, benzine for front panel or housing cleaning, which might damage shape and color of front panel and housing.

1.1 Preparations prior to use

Unpacking

When the tester is delivered, please check whether it conforms to the required specifications and has not been damaged in transit. If there is any damage on the tester or it does no work in conformity with the specifications, please inform us of the model and product name.

Storage

In case of storing the tester for a long time, store it at the place of low humidity and where it is not exposed to the direct sunlight.

1.2 Confirmation prior to use

Power supply

Use the tester with the power source voltage within 90 to 250VAC and the frequency 50 / 60Hz. When connecting the power supply cable, confirm that the power supply switch is turned OFF.

• Set the power switch for the instrument where it can be used very easily. • To prevent an electric shock or failure of the unit, connect the power supply cord to a grounded 2 pole outlet. • Don't upplug the power supply cord pulling the cord. Upplugging must

• Don't unplug the power supply cord pulling the cord. Unplugging must be done holding the plug properly.

Power supply cable

The plug of power supply cable connected to the tester is for 100VAC use. When the tester is used with 200VAC, replace the plug with appropriate one for 200VAC use. Please connect the power supply cable to the power supply connector on the rear panel of the tester. The plug of power supply cable has 3 pins and the round shape pin in the center is for grounding.

1.3 Warning and caution during measurement

Electric shock accident or malfunction

\land Warning
ullet In order to prevent the electric shock accident or the failure of this unit, do
not apply voltage to the measurement terminal.
ullet In order to prevent the failure, conduct the measurement after turning off
the power related to the measurement.
ullet In order to avoid electric shocks and to ensure the safety of the tester, pro-
tective earth connection is necessary. Connect the supplied power cord with
ground insulating type bipolar outlet.
ullet When the tester is used, use the supplied power cord by the manufacturer
only. If the power cord not specified by manufacturer is used, it may be
the cause of fire.

Connection of the control cable and communication cable

▲ Caution

- Use the specified cable size to connect the control terminal.
- Make sure that communication cable and control cable are connected surely. If the connection is not undertaken correctly, it may cause of the failure to satisfy specification or malfunction.
- Power supply must be turned off on each device before connection of communication cable and control cable. Failure to turn of the electric power cause the electric shock or malfunction.


Other caution

▲ Caution

• If power supply is done by UPS (Uninterruptible power supply device) or DC-AC inverter, do not use rectangular wave or pseudo rectangular wave output of UPS or DC-AC inverter. If used, this may cause the malfunction of the instrument.

2. Name of parts

2.1 Front panel



 Measuring terminal 	SENSE Hi: + Terminal of voltage inputSENSE Lo: - Terminal of voltage inputSOURCE Hi: + Terminal of current outputSOURCE Lo: - Terminal of current output
② Display Portion	Display setting like Measurement function, Measurement range, Measurement value, Comparator setting, Memory No. can be done.
③ FUNCTION Key	It is used for selecting measurement function.
④ RANGE Key	Setting range: 30m Ω to 300k Ω , AUTO range
⑤ HIGH GOOD LOW	Red LED is lit up when the measured value exceeds the upper limit value. GOOD: Green lamp is lit up with a good judgment. Red lamp is lit up when the measured value exceeds the lower limit value.
6 SETTING key	Key F1 to F4 are used for setting the measurement condition, device setting etc.

	13
ا_1	
⑦ Power supply switch	Power supply ON/OFF switch
8 Power inlet	Connect the supplied power supply cord. Use the power supply voltage and frequency within the specified range.
Rear measuring Terminal	SENSE Hi: + Terminal of voltage inputSENSE Lo: - Terminal of voltage inputSOURCE Hi: + Terminal of current outputSOURCE Lo: - Terminal of current output
RS-232C connecter	Connector for RS-232C communication
Input and output Terminal	Terminals for external control
Input terminal	The connector of Pt100 Ω temperature sensor. Accessory temperature sensor (5803-11) is connected for temper- ature correction function.

(3) Interface board mounting part


This is Installation part area for the BCD interface board or analog output board.

2.3 Display Portion

(1	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
① Memory No.	Displays memory No. (No.1 to No.15)
②Function	Displays measurement function
	OHM : Resistance measurement T.C. : Temperature correction
	OHM R : Resistance measurement Ratio display
	T.C.R : Temperature correction Ratio display
	TEMP : Temperature measurement
③Sampling	Displays sampling rate
	S : Sampling rate 200ms M : Sampling rate 50ms
	F : Sampling rate 11.1ms
Range	Displays the measured range.
	30mΩ, 300mΩ, 3Ω, 30Ω, 300Ω, 3kΩ, 30kΩ, 300kΩ
④External control	Displays the status of outer control.
	RT : Memory is controlled from the rear panel terminal
	RB : Controlled from BCD
	F : RS-232C communication is ON
5 Auto-range	Displays the setting of Auto-range measurement
	AUTO : Auto-range ON (None) : Auto-range OFF
©Unit	Measurement unit
	m Ω : Range of 30m Ω and 300m Ω
	Ω : Range of 3 Ω , 30 Ω and 300 Ω
	$k\Omega$ $\ $: Range of $3k\Omega,30k\Omega$ and $300k\Omega$
⑦Comparator	Displays the setting of comparator
	HI SET : Upper limit value of the comparator
	LO SET : Lower limit value of the comparator
8Hold	Display the condition of sampling
	RUN : Sampling is in process
	HOLD : Sampling is stopped and HOLD status
Ourrent cut	During the hold of sampling, measured current is off.
	C.OFF : Current cut function is valid
	(None) : Current cut function is not valid.
In Source open	Displays when the source terminal is open or the value exceeds the measurement
	range drastically.
①Key guidance	Displays the detail of keys F1 to F4.

3. Basic operation method

3.1 Power supply



First confirm the power OFF of the switch located at the rear panel of the instrument and connect cord to the power supply. Then, ON the power supply switch. This instrument becomes in operation condition immediately but it is preferred for preheating for 30 minutes before the use.


As this instrument is equipped with a parameter holding function, following (1) to (3) status can be memorized even though the power supply is turned OFF.

- 15 sets of memories (Measurement conditions such as measurement function, ranges, comparator settings, zero adjustment settings)
- (2) Key lock state
- (3) Various types of setting


3.2 Connection of measuring terminals

3.2.1 Connection of measuring terminals (Model 5811-21C : Option)

Measuring cables are connected to the measuring terminals on either front panel or rear panel. Terminals on front and rear panel cannot be used simultaneously. Kelvin clips are to be connected as follows.



Connection with the device (Connection by four-terminal method) Measurement wires are connected with 4 cables to the measured specimen.




Note: Penetration of disturbing noise to the measuring terminals may cause instability or display or auto range operation. Prevent the noise by connecting with shield wire the shield side to SOURCE Lo. If all 4 wires are not connected properly, the displayed value may be fluctuated.

3.2.2 Connection of temperature measurement terminals (Temperature sensor Model 5803-11: Option)

Temperature sensor is connected during temperature measurement (TEMP), temperature correction (T.C and T.C RATIO).


Temperature sensor is connected to temperature sensor connector of rear panel.



Used connector : R05-R5F Corresponding plug : R05F-PB5M

3.3 Startup display (Self-check)

Self-check screen is displayed for approx. 5 sec. after Power ON., then the display shifts to measurement display.



Model name Model name and output option
 3585-X (None)
 3585-03 : BCD TTL output
 3585-04N : BCD OC NPN output
 3585-04P : BCD OC PNP output
 3585-07 : Analog output

② ROM No. The number of the firmware.

③ Self-check result The result of self-check of internal circuit.

EEPROM OK : Memories like setting value are checked

TMP ADC TEST OK : The test result of ADC for temperature


OHM ADC TEST OK : The test result of ADC for resistance

- ① If the self-test is not good, it shows FAIL.
- ② In case of FAIL, if FUNCTION key is pressed, display can be changed to measurement mode, but the correct measurement cannot be obtained. Contact the nearest distributor or TSURUGA Electric Corporation office.

Refer to "12. Failure symptom"


- When POWER supply is turned ON, self-check is done, the screen shifts measurement display.
- ② The measurement function is set by pressing 'FUNCTION' key. To measure resistance, choose 'OHM'.
- ③ Select the measurement range by pressing 'RANGE' key.
 If the resistance value is unknown, choose 'AUTO' range.
 Pressing 'RANGE' key for more than 1 sec., ON/OFF of 'AUTO' range can be chosen either ON or OFF.
 During 'AUTO' range, 'AUTO' is displayed above the unit on the screen.
- ④ The result is displayed, when the measurement cable is connected with the instrument and object to be measured.
- ⑤ Refer to "4. Measurement method" for setting of sampling, comparator and etc.

Function	: OHM	Resistance measurement
	T.C.	Temperature correction
	T.C.R	Temperature correction ratio display
	OHMR	Resistance ratio display
	TEMP	Temperature measurement
Range	: 30mΩ	Measuring at $30m\Omega$ range
	300mΩ	Measuring at $300m\Omega$ range
	3Ω	Measuring at 3Ω range
	30Ω	Measuring at 30Ω range
	300Ω	Measuring at 300Ω range
	3 k Ω	Measuring at $3 \text{ k} \Omega$ range
	30 k Ω	Measuring at 30 k Ω range
	300 k Ω	Measuring at 300 k Ω range
	AUTO	Measuring with automatically switched range between $30\text{m}\Omega$ to
		$300 \text{k}\Omega$ range



3.5 Key lock

It is a switch that prohibits operation of the instrument from the front panel in order to avoid the measurement by unintentional change of setting. Display of the LOCK is converted to reverse color during key lock condition. If other keys are required to use during key lock condition, key lock must be released first to use the other keys.



• Key lock method

Press F4 [LOCK] key for more than 3 sec.

Display of the LOCK is converted to reverse color which shows that instrument is in locked condition.


Cancellation of key lock

During the key in locked condition, press F4 [LOCK] key for more than 3 s. Key lock will be released.

3.6 Zero adjustment


This is the function to eliminate the external cable resistance and connection fixtures during resistance measurement.

Zero adjusted value is subtracted from the measured value and remaining value is displayed.



Note) Zero adjustment is not done for temperature measurement (TEMP).

The zero adjustment is done in the upper range, over measurement may occur in lower range.



• ON/OFF of Zero adjustment function


Pressing 'F 3'[0ADJ] key to switch ON/OFF of zero adjustment. [0ADJ] is converted to reverse display when zero adjustment is ON.

Memory of Zero adjustment value

The measured value is saved as zero adjustment value when [0ADJ] key is pressed more than 1 sec. during OFF state of zero adjustment.

4. Setting operation


4.1 Setting flow




Setting screen


SETTIMG	MODE				
MEMORY GENERAL System	SET				
[SEL] [][]	[ENT]

4.1.1 MEMORY SET flow





4.1.3 SYSTEM SET flow



Note: If F1 <code>[SEL]</code> key is pressed, 1/2 of the screen switches to SYSTEM SET.


4.2 Memory

This instrument is equipped with 15 pairs of memories that store comparator and measurement conditions. The following 6 items are available for memory storage.

- $\boldsymbol{\cdot}$ Measurement function
- \cdot Measurement range
- Setting of comparator (Upper limit value, Lower limit value, Range)
- $\boldsymbol{\cdot}$ Standard value of ratio calculation and deviation
- · Zaro adjust value and operation
- The standard temperature and temperature coefficient for calculation of temperature correction
- Note: Setting can't be done in ONLINE condition.
 - Memory cannot be set during memory valid selection signal.
 - Memory cannot be selected during HOLD.

[Selection of memory]

Method from front panel



Call

When F2 [RCL] key (①) is pressed in standby state, memory No. will be increased, set state is called and displayed.

Memory No. from 1 to 15 can be selected.

Method from external control

Refer to memory operation (5.1.5) for detailed instruction.


[Memory registration]

After selecting the storage No., set Measurement mode, Measurement range, Comparator, Timer and etc. can be set in MEMORY SET.

4.3 MEMOREY SET


Memory No., Measurement function, Measurement range, Comparator, Ratio calculation, zero adjustment and Temperature correction can be set at Memory setting.

MEMORY SET



- Press F1 [SET] key in standby state.
 Display changes to SETTING MODE.
- ② Press F4 [ENT] key to change memory setting.


Basic operation



Operation key

F1 [SEL] :		Select setting item (Forward).
FUNCTION :		Select setting item (Reverse).
RANGE	:	Select setting item (Forward. Same as F1 [SEL]).
		The selected item is converted to reverse color.
F2 [▲]·F3 [▼]	:	Select a setting item or change the setting value.
		Setting value can be increased(\blacktriangle) or decreased(\blacktriangledown) by numerical
		setting.
F4 [ENT]	:	Save the setting and the display returns to measurement standby
		state.


4.3.1 Selection of Memory



- ① Press F1 [SEL] key to select the MEMORY No. and pressF4(ENT) key.
- ② Select the Memory No. by F2 [▲], F3 [▼] key.
- Press F4 [ENT] to save the setting and the display returns to measurement standby state.
 To continue other setting, select the items by pressing F1 [SEL]

MEMEORY : No. 1 to No. 15 (Memory No.)

4.3.2 Setting of Measurement function




1 Press F1 [SEL] key to select the MEMORY SET and press F4 (ENT).

Press F1 (SEL) again to select the Function.

- ② Press F2 [▲], F3 [▼] key to select measurement function.
- Press F4 [ENT] to save the setting and the display returns to measurement standby state.
 To continue other setting, select the items by pressing F1 [SEL].

Available FUNCTION	: OHM	Resistance measurement
	T.C.	Temperature correction
	T.C.R	Temperature correction ration display
	OHM R	Resistance ratio display
	TEMP	Temperature measurement

4.3.3 Setting of Measurement range



- Press F1 [SEL] key to select MEMEORY SET and press F4 [ENT] key. Select RANGE by F1 [SEL] KEY.
- ② Press F2 [\blacktriangle], F3 [\blacktriangledown] key to select measurement range.
- Press F4 [ENT] to save the setting and display returns to measurement standby state.
 To continue other setting, select the items by pressing F1 [SEL].

RANGE	: 30mΩ	Measuring at $30m\Omega$ range
	300mΩ	Measuring at $300m\Omega$ range
	3Ω	Measuring at 3Ω range
	30 Ω	Measuring at 30 Ω range
	300Ω	Measuring at 300 Ω range
	3 k Ω	Measuring at $3 \text{ k} \Omega$ range
	30 k Ω	Measuring at 30 k Ω range
	300 k Ω	Measuring at 300 k Ω range
	AUTO	Measuring for automatic switching range from 30m Ω to 300 k $\Omega.$

4.3.4 Setting of comparator

Digital comparator can show the comparison result of the displayed value and the upper limit, lower limit value.

Comparison condition

Displayed value \geq Upper limit set value (HIGH)	HIGH(HI)	output
Upper limit set value (HIGH) $>$ Displayed value $>$ Lower li	mit set value	(LOW)
	GOOD(GO)	output
Displayed value \leq Lower limit set value (LOW)	LOW(LO)	output
Over is displayed (OVER)	HIGH(HI)	output
Under is displayed (UNDER)	LOW(LO)	output

Comparison output

The open collector output can be obtained from the terminal of rear side.

(Refer to section 5.1 External control)


Display HIGH, LOW : Red

GOOD : Green

Setting range

Comparator can be set from -19999 to 35000 Range can be set at $30m\Omega$, $300m\Omega$, 3Ω , 30Ω , 30Ω , $3k\Omega$, $30k\Omega$ and $300k\Omega$.

Setting method



 Press F1 [SEL] key to select MEMORY SET and press F4 [ENT] key to fix it Select HIGH SET or LOW SET or RANGE by F1 [SEL] key.

(Selection of setting items can be chosen either forward or reverse way by FUNCTION and RANGE key respectively.)

② Press F2 [\blacktriangle], F3 [\blacktriangledown] key to change the setting values.

If F2(\blacktriangle), F3(\triangledown) are pressed continuously, HIGH set and LOW set can be changed in 3 steps.

- $\ensuremath{\textcircled{}}$ $\ensuremath{\textcircled{}}$ $\ensuremath{\textcircled{}}$ Press F1 [SEL] to select RANGE.
- ④ Press F2 [▲], F3 [▼] KEY to change the setting

The decimal point and unit of 'HIGH SET', 'LOW SET' are changed accordingly.

⑤ Press F4 [ENT] to save the setting and the display returns to measuring mode. To continue other setting, select the item by pressing F1 [SEL].

4.3.5 Ratio display

It is a function displayed in percentage with respect to standard resistance value by comparing measured resistance value Rx and standard resistance value Rs. The comparison judgment $(\pm \Delta N)$ of deviation can be done.

The comparison judgment ($\pm \triangle$ %) of deviation can be done.

Equation)
$$X = \frac{Rx}{Rs} \times 100\%$$

 $\Delta = \left(\frac{Rx}{Rs} - 1\right) \times 100\%$

X : Ratio (%) Rs : Standard resistance (Ω) STD SET Rx : Measured resistance value (Ω) DEV STD \triangle : Deviation (%)

Display range -199.9 - 199.9%

'OVER' or 'UNDER' is displayed, when the value exceeds display range.

Comparison operation

Comparison operation $\pm \triangle \%$

Compare values regarding 'DEVSET' as upper and lower deviation.

When comparison range \triangle % is set to 10.0%, ±10% of the range corresponding to 100% is made GO judgment.

LOW judgment : -199.9 to 90.0%, UNDER GOOD judgment : 90.1 to 109.9% HIGH judgment : 110.0% - 199.9%, OVER

Comparison output


The open collector output can be obtained from the terminal of rear side. (Refer to section 5.1 Control terminal) Display HIGH, LOW : Red

GOOD : Green

Setting range

STD SET can be set from 00000 to 35000 DEV SET can be set from 0.0% to 100.0% Range can be set at $30m\Omega$, $300m\Omega$, 3Ω , 30Ω , $30\Omega\Omega$, $3k\Omega$, $30k\Omega$ and $300k\Omega$.

Setting method



- Press F1 [SEL] key to select MEMORY SET and press F4 [ENT] key.
 Select STD SET, DEV SET or RANGE by F1 [SEL] key.
 (Selection of setting items can be chosen either forward or reverse way by FUNCTION and RANGE key respectively.)
- ② Press F2 [▲], F3 [▼] key to change the setting values.
 If F2(▲) and F3(▼) are pressed continuously, STD set, DEV set can be changed in 3 steps.
- $\ensuremath{\textcircled{}}$ $\ensuremath{\textcircled{}}$ Press F1 [SEL] to select RANGE.
- ④ Press F2 [▲], F3 [▼] KEY to change the setting

The decimal point and unit of 'HIGH SET', 'LOW SET' are changed accordingly.


⑤ Press F4 [ENT] to save the setting and the display returns to measuring mode. To continue the other setting, select the items by pressing F1 [SEL].

4.3.6 Zero adjustment

This is the function to eliminate the external cable resistance and connection fixtures etc. The value where zero adjust value is subtracted from the measured value is displayed.



Setting method



 Press F1 [SEL] key to select MEMORY SET and press F4 [ENT] key.
 (Selection of setting items can be chosen either forward or reverse way by FUNCTION and RANGE key respectively.)

Select 0ADJ or RANGE by pressing F1 [SEL] key.


- ② Press F2 [▲], F3 [▼] key to change the setting values.
- $\ensuremath{\textcircled{}}$ 3 Select VALUE by pressing F1 [SEL] key.
- ④ Press F2 [▲], F3 [▼] key to change the setting.
 If F2(▲) and F3(▼) are pressed continuously, the speed can be changed in 3 steps.
- S Press F4 [ENT] to save the setting and the display returns to measurement mode.
 If 0ADJ is set ON and the setting operation is stopped, zero adjustment operation is activated.
 To continue other setting, select the items by pressing F1 [SEL].

Operation of zero adjustment key (F3: 0ADJ)

ON/OFF of zero adjustment function can be set by pressing 0ADJ key (F3) during measurement.

The calculation is done according to the set zero adjustment.

Pressing 0ADJ key (F3) for more than 1 sec., the measured value is saved and the calculation is done.



4.3.7 Temperature correction (T.C.)

The conductor resistance and ambient temperature are measured, and temperature correction is computed and displayed considering conduct resistance as reference value.

The standard temperature and temperature coefficient can be set in the range of 0 to 99.9 °C and 1000 to 19999 ppm respectively.

The ambient temperature is measured by connecting temperature sensor $Pt100\Omega$.

Equation)
$$R_T = \frac{\text{R t}}{1 + (\alpha \times 10^{-6}) \times (t-T)}$$
 (Ω)

- t : Ambient temperature (°C)
- R_T : Resistance Correction (Ω)
- Rt : Resistance value at t $^{\circ}$ (Ω)
- α : Temperature coefficient
 - Setting range from 1000 to 19999ppm
- T : Standard temperature


Setting range 0.0 to 99.9℃

Range of calculation : Max. 39999

When the calculation result exceeds 39999, OVER is displayed.

The accuracy during the temperature correction works: \pm 0.3% of rdg. is added to the accuracy of resistance measurement.

Setting method



- Press F1 [SEL] key to select MEMORY SET and press F4 [ENT] key.
 Select STD TEMP or STD T.C by pressing F1 [SEL] key.
 (Selection of setting items can be chosen either forward or reverse way by FUNCTION and RANGE key respectively.)
- ② Press F2 [▲], F3 [▼] key to change the setting value.


If the key is pressed continuously, speed can be changed in 3 steps.

Press F4 [ENT] to save the setting and displays returns to measurement mode.
 To continue other setting, select the items by pressing F1 [SEL].

4.4 GENERAL SET


Sampling cycle, external control, averaging process, measuring current control function, buzzer and communication can be set in GENERAL SET.

Select GENERAL SET



- Press the F1 [SET] key in the standby state.
 Display changes to SETTING MODE.
- Press F1 [SEL] key and select GENERAL SET.
 If F4 [ENT] is pressed, display changes to equipment setting.

Basic operation




Operation key

F1 [SEL]	: Select setting item (Forward).
FUNCTION	: Select setting item (Reverse).
RANGE	: Select setting item (Forward. Same as F1 [SEL]).
	The color of selected item is converted to reverse color.
F2 [▲], F3 [▼]	: Setting values can be changed.
F4 [ENT]	: Save the set value and the display returns to the measurement mode.

4.4.1 Setting of Sampling


The sampling speed of resistance measurement can be set.



- Press F1 [SEL] key to select GENERAL SET and press F4 [ENT] key.
 Select SAMPLE by pressing F1 [SEL] key.
 (Selection of setting items can be chosen either forward or reverse way by FUNCTION and RANGE key respectively.)
- ② Press F2 [▲], F3 [▼] key to select SLOW / MEDIUM / FAST.
- ③ Press F4 [ENT] to save the setting and the display returns to the measuring mode.
 To continue other setting, select the items by pressing F1 [SEL].

4.4.2 Selection of memory setting by rear panel control

Rear terminals can be used for setting enable / disable of the memory selection.



- Press F1 [SEL] key to select GENERAL SET and press F4 [ENT] key.
 Select MEM. CRTL by pressing F1 [SEL] key.
 (Selection of setting items can be chosen either forward or reverse way by FUNCTION and RANGE key respectively.)
- ② Press F2 [▲], F3 [▼] to select MANUAL / REMOTE


MANUAL : Memory is selected by operation of the front panel F2[RCL] key. REMOTE : Memory is selected by MEM1, MEM2, MEM4, MEM8 of rear control terminals.

③ Press F4 [ENT] to save the setting and display returns to measurement mode.

To continue other setting, select the items by pressing F1 [SEL].

4.4.3 Setting of average number of sampling times

Setting of average sampling number of resistance measurement can be done. Measured resistance value is displayed by calculating moving average value.



Press F1 [SEL] key to select GENERAL SET and press F4 [ENT] key.
 Select AVERAGE by pressing F1 [SEL] key.
 (Selection of setting items can be chosen either forward or reverse way by FUNCTION and

RANGE key respectively.)
② Press F2 [▲], F3 [▼] to set average number of sampling times.

Setting range : 1 to 100 times


Press F4 [ENT] to save the setting and display returns to measurement mode.
 To continue the other setting, select the items by pressing F1 [SEL].

When the average sampling number is set 3 times,

HOLD	OFF ON						
Sampling		Sw X Sx	\$1) <u>S2</u>	\$3	S4	<u>\$5</u>
RST	OFF ON						
EOC	OFF ON						
Display		(Su+Sv+Sw)/3	(Sv+Sw+Sx)/3	<u> </u>	(S1+S2)/2	(\$1+\$2+\$3)/3	(S2+S3+S4)/3
Judgment		(Su+Sv+Sw)/3	(Sv+Sw+Sx) /3	\$1	(\$1+\$2)/2	(\$1+\$2+\$3)/3	(\$2+\$3+\$4)/3

4.4.4 Setting of measuring current control.

Setting of the measuring current can be controlled during resistance measurement. When the setting is ON and SAMPLING HOLD is ON, measurement current is set OFF.



Press F1 [SEL] key to select GENERAL and press F4 [ENT] key.
 Select CC. CTRL by pressing F1 [SEL] key.

(Selection of setting items can be chosen either forward or reverse way by FUNCTION and RANGE key respectively.)

② Press F2 [▲], F3 [▼] key to select ON/OFF.


ON : Measuring current is set OFF when SAMPLING HOLD is ON.

C.OFF is displayed, when measurement current is set OFF.

OFF : Control of the current is not done. The output current is applied continuously.


③ Press F4 [ENT] to save the setting and display returns to measurement mode.To continue the other setting, select the items by pressing F1 [SEL].

When the control of measuring current is ON,



4.4.5 Setting of Buzzer

Buzzer operation and volume of sound can be set.



- Press F1 [SEL] key to select GENERAL SET and press F4 [ENT] key.
 Select BUZZ MODE / BUZZ VOL / BUZZ CONT by pressing F1 [SEL] key.
 (Selection of setting items can be chosen either forward or reverse way by FUNCTION and RANGE key respectively.)
- ② Press F2 [▲], F3 [▼] key to change the setting.

BUZZ MODE

The condition of buzzer ringing is set.

GOOD : Ring the buzzer during GOOD judgment.

- NG : Ring the buzzer during HIGH or LOW judgment.
- HI : Ring the buzzer during HIGH judgment.
- LO : Ring the buzzer during LOW judgment.
- OFF : No judgment buzzer.

BUZZ VOL

Setting range: 1 to 9

BUZZ CONT

The condition of buzzer ringing time is set.

CONT. : Ring buzzer continuously.


- 1s : Ring buzzer for 1 sec.
- 5s : Ring buzzer for 5 sec.
- ③ Press F4 [ENT] to save the setting and display returns to measurement mode To continue other setting, select the items by pressing F1 [SEL].

4.4.6 Setting of communication

RS-232C communication setting is carried out here.

ON/OFF of communication function is carried out by ONLINE setting.

The setting of communication speed by the RS BPS and setting of parity bit by RS PARITY are carried out. The communication speed and parity bit should be set according to the setting of higher level equipment like PC etc.



- Press F1 [SEL] key to select GENERAL SET and press F4 [ENT] key.
 Select ONLINE, RS BPS, RS PARITY by pressing F1 [SEL] key.
 (Selection of setting items can be chosen either forward or reverse way by FUNCTION and RANGE key respectively.)
- ② Press F2 [▲], F3 [▼] key to select setting as below.
 - ONLINE : ON/OFF of the communication function

Output of RS-232C communication can be obtained with ON. To get the communication through RS-232C, ONLINE must be set to ON condition.)

- RS BPS : Set communication speed 9600bps, 19200bps, 38400bps
- RS PARITY : Set parity bit of communication data.


NONE
ODD
EVEN

③ Press F4 [ENT] to save the setting and the display returns to measurement mode.To continue the other setting, select the items by pressing F1 [SEL].

4.5 SYSTEM SET

The contrast of display is adjusted and equipment information is shown.

Select SYSTEM SET




- Press the F1 [SET] key in the standby state.
 Display changes to SETTING MODE.
- ② Press F1 [SEL] key to select SYSTEM SET.

If F4 [ENT] pressed, the display changes to SYSTEM SET.

4.5.1 Setting of contrast

Adjust the brightness of the display panel.




- Press F1 [SEL] key to select SYSTEM SET and press F4 [ENT] key to fix it.
 Press F1 [SEL] key to select CONTRAST
- ② Press F2 [▲], F3 [▼] key for setting

Setting range: 1 to 5

Press F4 [ENT] to save the setting and the display returns to measuring mode.
 Press F1 [SEL] to continue the display of equipment information.

4.5.2 Display of equipment information

Equipment information is displayed.



- MODEL : Model No. with or without option
- ROM : The number of the firmware

SERIAL : Serial number of the 3585

Press F4 [ENT] to save the setting and the display returns to measuring mode.
 Press F1 [SEL] to setting of contrast.

5. External control

Selection of memory, Control of sampling hold, Signals like judgment and etc. can be obtained from the control terminal located at rear panel of the tester.

5.1 Control terminal

5.1.1 Terminal arrangement


No.	Signal name	Input / output	Function				
1	O-COM	_	Output common (2 to 6 Common) It is internally connected with I-COM No.7.				
2	GO	Output	Comparator It is output of GOOD judgment. Output of ON is obtained during GOOD judgment.				
3	LO	Output	Comparator It is output of LOW judgment. Output of ON is obtained during LOW judgment.				
4	HI	Output	Comparator It is output of HIGH judgment. Output of ON is obtained during HIGH judgment.				
5	ERR-CC	Output	ON is output, when SOURCE of resistance measurement input is open or the resistance is large with respect to the measurement range.				
6	EOC	Output	ON is output during sampling stops. Width 2ms pulse is output during continuous sampling.				
7	I-COM	_	Common (8 to 14 Common) input It is internally connected with O-COM No. 1.				
8	MEM1	Input					
9	MEM2		Memory is called by inputting memory No.				
10	MEM4		Refer to the table of memory operation (Section 5.1.5) for selection of memory.				
11	MEM8		or memory.				
12	0.ADJ	Input	Zero adjustment input During ON, zero adjust is activated.				
13	HOLD	Input	Sampling hold input During ON, measurement is stopped, the result and judgments are retained. The output of the measurement data can be obtained through RS-232C.				
14	RST	Input	Judgment reset, hold for one sampling hold input During ON, judgment output is turned OFF. When sampling hold is ON, and reset is switch to ON, one time measurement is done.				

5.1.2 Connection

Compatible electrical wire: AWG26 to AWG20

End of electrical wire is peeled off as shown in figure below and wire is inserted into the terminal by pressing the release button down with help of screwdriver.






5.1.3 Input / output signal

Input signal		
Input ON residual voltage	: Less than 1V	(ON current less than 30 mA) $$
Response time	: 5ms (MAX.)	
Output signal		


output signal	
Signal	: Open collector output (NPN)
Max. load	: DC30V 30mA
Residual voltage	: Less than 1V (During load current: 30mA)

5.1.4 External control timing chart


- Timing of measurement
- Average measurement NO. 1



Average measurement No.2 (One sampling hold)



Average measurement No.3 (When HOLD is released.)



HOLD	OFF ON			[Renewal	of the first	sampling —	
Sampling		Sx (SO]	S1]	_	
EOC	OFF ON					1	_	
Display		X	Sx	χ	S0	χ <u></u> \$1	_	
Judgment			Sx		S0	S1	-	
• Zero ac	ljustr	nent						

Average measurement No.3 (When the HOLD is released by the pulse.)

OFF ON HOLD L Sx) S0 S1 S2 S3 S4 S5 Smpling OFF ON 0. ADJ Save Sx When HOLD is ON, no data is saved. SO-Sx S1-Sx S2 S4 S5-Sx Sx S3 Display

5.1.5 Memory operation

- 1 Set the MEM.CTRL to REMOTE at GENERAL SET.
- ② Input the code of the memory No.


Note: Memory can't be called except the memory No. code from 1 to 15.

MEM No.	MEM1	MEM2	MEM4	MEM8	
1	0	_	_	_	
2	_	0	_	_	
3	0	0	—	—	
4	_	_	0	_	
5	0	—	0	—	
6	_	0	0	—	
7	0	0	0	_	
8	_	_	_	0	
9	0	_	_	0	
10	_	0	_	0	
11	0	0	_	0	
12	_	_	0	0	
13	0		0	0	
14		0	0	0	
15	0	0	0	0	
	Invalid except above				


 \bigcirc : ON (Connection with I-COM)

- : OFF (Open)

Memory selection



5.1.6 Internal circuit configuration



6. Communication (RS-232C)

The setting of Function, Range, Memory etc., as well as measurement data and judgment result can be obtained by RS-232C communication.


6.1 Specification

6.1.1 Communication specification

Transmission system	: Start-stop synchronization Full duplex
Transmission rate	: 9600, 19200, 38400bps (Factory setting 9600bps during delivery)
Data bit length	: 8 bit
Stop bit	: 1 bit
Parity bit	: None, even number, odd number (During shipment, set: None)
Delimiter	: CR+LF (0DH+0AH)
Connector	: D-sub 9 Pin (Male) Inch screw type

6.1.2 Connecter pin arrangement


RS-232C connector



RS-232C connector arrangement

Pin No.	3585 signal JIS (RS-232C)	Direction	Function
1			Not used
2	RD (RXD)	Input	Receiving data
3	SD (TXD)	output	Transmitting data
4			Not used
5	SG (GND)		Ground signal
6			
7			Netwood
8			Not used
9			

6.1.3 Operation



- Ta Command Response time : Max. Approximately 5ms
- Tb After response, command prohibition time : RS-232C Max. 5ms
- Note: To control the operation by data communication, set ONLINE to ON condition in general SETTING (Refer to 4.4.6). When power is turned to OFF, ONLINE setting is returned to OFF condition. During every power ON time, ONLINE should be set to ON by outside ONLINE command. If the communication is carried out when ONLINE is OFF condition, an error response is obtained except read command.

6.2 List of communication command and response

Symbols used in command response

Symbol	Content	Hexadecimal code
Sp	Space	20H
C _R	Carriage return	0DH
LF	Line feed	0AH

Error response

Error response	Content		
CommandErr	Command message is not right.		
ERR	Not on line.		
	Set message is not right or set value is out of range.		
ERROR	Memory cannot be written down with WRITEMEMORY command.		

Caution

The setting contents of communication command cannot be saved, if power is shut down.

If WRITE MEMORY command is used, the setting contents are saved in memory, eventhough power is shut down during measurement.

Command	Response	Contents
Read	OHM=ኽ 199.99kOHM,JUDGE=HIGH ኽ LOW 际문	Read measurement data
DATA? 🖫 🕞	1 2 3 4	①Response ②Measured value ③Judgment result
		④Delimiter
		The beginning of the measured data is sign, when plus 🛐,
		minus [-]
	When FUNCTION=OHM,	(The minimum digit is fixed to 0 during FAST sampling.)
	OHM=팀 199.99kOHM,JUDGE=HIGH 팀 LOW 뎲屇	Measured data 199.99k Ω HIGH LOW judgment
	OHM=ନ୍ଧ୍ OVER କ୍ରିକ୍ତି kOHM,JUDGE=HIGH କ୍ରିଲ୍ରିଲ୍ରିଲ୍ଲୋକ୍	Measured data Overrange HIGH judgment
	OHM=ኽ UNDER ኽ kOHM,JUDGE=LOW ኽኽኽኽዀዀ	Measured data Underrange LOW judgment
	OHM=ନ୍ଧି ERR-C କ୍ରି kOHM,JUDGE=LOW କ୍ରିଲ୍ରିଲ୍ରିଲ୍ଲିଲ୍ଲୋକ୍	Measured data Source open error LOW judgment
	OHM=팀 ERR-H 🗟 kOHM,JUDGE= HIGH 🗟 LOW 🖫 🗐	Measured data Hardware error HIGH LOW judgment
	OHM=ኽ 1.0000kOHM,JUDGE=GOOD ኽኽኽዀዀ	Measured data $1.0000 k\Omega$ GOOD judgment
	OHM=퉌 12.345 퉌 OHM,JUDGE=HIGH 퉌훤퉌┗匠	Measured data 12.345Ω HIGH judgment
	OHM=ኽ 200.00mOHM,JUDGE=LOW ኽኽኽኽኽዀዀ	Measured data 200.00m Ω LOW judgment
	When FUNCTION=T.C,	
	TC=ዄ 123.45kOHM,R=ዄ 100.00 k OHM,TEMP=ዄ 100.0'C,JUDGE=HIGH ዄ LOW ዄም	Calculated value of TC 123.45k Ω the measured resistance
		value 100.00k Ω , temperature 100°C
		HIGH LOW judgment
	TC=ନ୍ତ୍ର OVER ନ୍ରିଲ୍ରିକି OHM,R=ନ୍ତ୍ର 123.45 ନ୍ତି OHM,TEMP=ନ୍ତ୍ର OVER ନ୍ତ୍ରି' C,JUDGE=HIGH ନିର୍ବିକିନ୍ଧିକ୍ଳିକ	Calculated value of TC Overrange, the measured resistance
		value 123.45Ω,
		Temperature Overrange HIGH judgment
	TC=ኽ ERR-1 ኽኽ OHM,R=ኽ 123.45 ኽ OHM,TEMP=ኽ OVER ኽ' C,JUDGE=HIGH ኽ LOW ኽም	Calculated value of TC ERR-1 , the measured resistance
		value 123.45Ω,
		Temperature Overrange HIGH LOW judgment
	When FUNCTION=RATIO,	Calculated value of ratio 120.0% Standard value 100.00 Ω
	RATIO=୍ରି 120.0%,RS=୍ରି 100.00 ର୍ଜ୍ରି OHM,RX=120.00 ର୍ଜ୍ରି OHM,JUDGE=GOOD ରିନ୍ତିର୍ଭିକିନ୍ଦ୍ରିଳ	the measured resistance value 120.00Ω GOOD judg-
		ment
	When FUNCTION=TEMP,	
	TEMP=5 100.0' C 5 F	The measured value of temperature = 100°
	TEMP=Sp OVER Sp' C Cpr	The measured value of temperature = Overrange
	TEMP=-⑮ 019.9'C 및 F	The measured value of temperature = -19.9 $^{\circ}$

Command	Response	Contents		
Read	ONLINE=REMOTE 🖫	Read the status of ONLINE		
ONLINE? CR F	1 2 3	① Read ONLINE information ② The status ONLINE ③ Delimiter		
	ONLINE=LOCAL FEF	The status of OFF LINE		
Set	ONLINE=REMOTE R	Set the status of on line.		
ONLINE=REMOTE	1 2 3	① Setting of ON LINE ② Status of ONLINE ③ Delimiter		
	The status of on line			
	REMOTE	During on line : Reading out of the measured data, setting and changing of set values can be		
LOCAL 🖻		controlled by RS-232C.		
		During off line : Setting and reading out of the measured data can be controlled by RS-232C.		

Command	Response			Contents		
Read	IDNT=TSURUGA,3585 뜱뜱뜱,0966-100,YMF00000 🖫			YMF00000		Read the product information.
IDNT? CR F	1 2	3	4	(5)	6	① Read the product information ② Manufacturer ③ Model No.
						④ The number of ROM ⑤ The serial number of the product
						6 Delimiter
						The product serial number label is pasted on the case.

Command	Response	Contents
Read	BUZZ=GOOD,05,0 🖫	Read the setting of buzzer.
BUZZ? 🖫	1 2 3	① Buzzer setting ② Setting contents(condition, volume, action) ③ Delimiter
	BUZZ=OFF 🗟,01,1 🖫 🖙	No buzzervolume:1Ringing time: 1 sec.%No buzzer rings regardless of volume of buzzer.
	BUZZ=NG 툴툴,09,2 际F	Buzzer during NG judgment volume:9 Ringing time: 5sec.
	BUZZ=HI ☜☜,05,0 ☜厅	Buzzer during HI judgment volume:5 Ringing time: continuous
	BUZZ=LO ,03,1 ლ	Buzzer during LO judgment volume: 3 Ringing time: 1 sec.
	BUZZ=GOOD,07,0 🖫	Buzzer during GOOD judgment volume:7 Ringing time: continuous
Set	BUZZ=GOOD,05,0 🖫 🖅	Set the buzzer
BUZZ=GOOD,05,0 달달	1 2 3 4 5	① Setting of buzzer ② Condition of action ③ Volume ④ Action ⑤ Delimiter
	Condition	
	GOOD	Ringing during GOOD judgment
	NG	Ringing during NG (HI or LO) judgment
	HI	Ringing during HI judgment
	LO	Ringing during LO judgment
	OFF	No buzzer
	Volume	
	01-09	Volume 1 (Min.) to 9 (Max.) 9 steps When the condition is OFF, the ringing is ignored but the setting must be
		done.
	Time	
	0	Judgment output Ringing
	1	At the time of judgment Ringing for 1 sec.
	2	At the time of judgment Ringing for 5 sec.

Command		Resp	oonse		Contents	
Read	COMP=H 🖫	35.000mOHM	l, L 🖫 01.000m		Read the comparator setting of displayed memory No.	
COMP? E	1	2	3	4	① Comparator setting ② HIGH setting ③ LOW setting	
					④ Delimiter	
	COMP=H 🖺	30.000mOHM	l,L 🖫 10.000m	OHM 🖫 🖅	H=30.000mΩ, L=10.000mΩ	
	COMP=H 🖫	300.00mOHM	l,L 🖫 100.00m	OHM 🖫 🖅	H=300.00mΩ, L=100.00mΩ	
	COMP=H 🖫	2.5000 🗟 OHI	M,L 🖫 0.1000 🗄	DHM 🖫	H=2.5000Ω, L=0.1000Ω	
	COMP=H 🖫	30.000 🖫 OHI	M,L 🖫 10.000 🗄	DHM 🖫 🗐	H=30.000Ω, L=10.000Ω	
	COMP=H 🖫	300.00 🖫 OHI	M,L 🖫 123.45 🗄	DHM 🖫	H=300.00Ω, L=123.45Ω	
	COMP=H 🖫 2.0000kOHM, L 🖫 1.0000kOHM 🖫 🖫				H=2.0000 k Ω, L=1.0000 k Ω	
	COMP=H 🖏 30.000kOHM, L 🖏 20.000kOHM ᅜᆴᅜᆕ				H=30.000 k Ω, L=20.000 k Ω	
	COMP=H 🖫	100.00kOHM,	L 🖫 012.00kO	HM Cref	H=100.00 k Ω, L=012.00 k Ω	
Set	COMP=H 🖺	2.0000kOHM,	L 🖫 1.0000kO	HM ^C R ^L F	Set the comparator	
COMP=H 🖺 2.0000kOHM, L 🖺 1.0000kOHM 대파	1	2	3	4	① Setting of comparator ② HIGH setting ③ LOW setting	
					④ Delimiter	
	Condition					
	HIGH set	> = LOW s	et			
	Range					
	-19999 to	35000, Decin	nal point		Decimal point is set at the same point of HIGH setting and LOW settin	
	Unit				When decimal points are different from each other, setting error is	
	mOHM				shown.	
	🖫 OHM					
	kOHM				Comparator rage is set based on decimal point and unit character.	
	FUNC					

Command	Response	Contents		
Read	FUNCTION=OHM 활활활활활활	Read the displayed function setting.		
FUNC? E	1 2 3	① Reading out of the function ② Function setting ③ Delimiter		
	FUNCTION=OHM 🖗 🏷 🖗	Resistance measurement OHM+6 sets of 🖫		
	FUNCTION=OHM-RATIO 🖫 🔄	Resistance measurement Ratio display		
	FUNCTION=TC ๖๖๖๖๖๖๖๖	Temperature correction TC+7 sets of 🖫		
	FUNCTION=TC-RATIO	Temperature correction Ratio display TC-RATIO+1 of 🖫		
	FUNCTION=TEMP 🖗 🖗	Temperature measurement TEMP+5 sets of 🖫		
Setting	FUNCTION=OHM DDDDDDDDD	Set the measurement function		
FUNCTION=OHM DDDDDDDD	1 2 3	① Function setting ② Measurement function ③ Delimiter		
	Function setting			
	ohm BBBBB	Resistance measurement		
	OHM-RATIO	Resistance measurement Ratio display		
	TC 35555555	Temperature correction		
	TC-RATIO 🖫	Temperature correction Ratio display		
	TEMP SSSS	Temperature measurement		

Command	Response	Contents
Read	RANGE=300mOHM 🖫 🗐	Read the displayed measurement range.
RANGE? ि	1 2 3	① Read the range ② Measurement range ③ Delimiter
	RANGE=ଜ୍ରି 30mOHM ଜ୍ରାଜ	30mΩ range
	RANGE=300mOHM 🖫 🖙	300mΩ range
	RANGE= 🖺 🛱 3 🛱 OHM 🖫 🖫	3Ω range
	RANGE=际 30 际 OHM 대한	30Ω range
	RANGE=300 ର୍ଜ୍ଧି OHM ଲ୍ଲାଳ୍ଟ	300Ω range
	RANGE=ଜ୍ମିଜି 3kOHM ଜ୍ମାଳ	3kΩ range
	RANGE=ାର୍ଚ୍ଚି 30kOHM ଲ୍ଲାଳ	30kΩ range
	RANGE=300kOHM 🖫 🖅	300kΩ range
	RANGE=ଞ୍ଚିଲ୍ରିଜ୍ AUTO ଜ୍ରାଳ	Auto range
Setting	RANGE=300mOHM 🖫 🖙	Set the measurement range
RANGE=300mOHM ဩ৮	1 2 3	① Range setting ② Measurement range ③ Delimiter
	Measurement range	
	툴 30mOHM ଭિ	Set to 30mΩ range
	300mOHM ଭਿਾ	Set to 300mΩ range
	555 3 5 OHM 55	Set to 3 Ω range
	툴 30 툴 OHM ଭિਸ਼	Set to 30Ω range
	300 际 OHM ଢિr	Set to 300Ω range
	ଲ୍ଲାଲ୍ 3kOHM ଲ୍ଲାଳ୍	Set to 3kΩ range
	툴 30kOHM 및 특	Set to $30k\Omega$ range
	300kOHM 🖫 🖅	Set to $300k\Omega$ range
	통통 AUTO 및 F	Set to auto range

Command	Response	Contents
Read out	MEM=01 Cal	Read the displayed memory No.
MEM? CR EF	1 2 3	① Read the memory No. ② Memory No. ③ Delimiter
		Memory No. 01
	MEM=15 Cal	Memory No. 15
Setting	MEM=CALL01 CRE	Read the specified memory.
MEM=CALL01 CR	1 2 3	① Specify memory No. ② Memory no. ③ Delimiter
	Memory no.	
	CALL01	Memory no. 01
	CALL15	Memory no. 15
	01-15	

Comma	nd		Response			Contents
Read		MEM=01,OHM 🖺 🖓 🏷 300	(OHM,H 🖺 300.00k	OHM,L 🖺 100.0	Okohm 🖫 🖅	Read the setting of the specified memory No.
MEM01?	-	1 2 3) (5)	6	\bigcirc	Read contents: Function, Range, Setting of comparator
		MEM=01,OHM-RATIO, 🖫 🖫 3kO	HM,S 🖫 3.0000 🖫 C)HM,D 🖫 🖫 10	.0%5p5p5pCrF	① Read memory ② Memory No. ③ Function ④ Measurement
		123) (8)	9	\overline{O}	range (5) HIGH setting (6) LOW setting (7) Delimiter
						(8) Standard resistance (9) Ratio
Set						Set Function, Range, comparator of the specified memory No.
MEM=01,OF	HM SpSpS	들,300kOHM,H 🖫 300.00kOl	IM,L 🖫 100.00kOHI			① Memory setting ② Memory No. ③ Function ④ Measurement
1 2	3	④⑤	6	\bigcirc		range (5) HIGH setting (6) LOW setting (7) Delimiter
MEM=01,OF	HM-RAT	D,탉탉 3kOHM,S 탉 3.0000 탉 OHN	1,D 🖫 🖫 10.0% 🖫	Sp Sp C _R L _F		(8) Standard resistance (9) Ratio
1 2	3	4 8	9	\bigcirc		
		Memory No.				
		01 to 15				
		Function				
		OHM [화화화화 OHM-RATI	O TC BBBBBB	TC-RATIO	S. TEMP S. S.	
		Range (When TEMP is set, fill	. ,			
		30mOHM 300mOHM		30 🖫 OHM		
			_	300 k OHM		
		HIGH and LOW settings for OHN		ents. (When TE	MP is set, fill w	ith space.)
		-19999 to 35000, Decimal po				
		Standard resistance for OHM-RA -19999 to 35000, Decimal po				
		Ratio for OHM-RATIO and TC-R	, 5			
		[월동] 000.0-100.0% [월동] [월 - 100.0% []]]				

Command	Response	Contents
Read	TCSET=25.0'C, 🖺 3930ppm 🖫	Read setting of temperature correction.
TCSET? ि	1 2 3 4	① Read the temperature correction setting ② Setting of the standard temperature
		③ Temperature coefficient ④ Delimiter
	TCSET=25.0'C, 🖺 3930ppm দ্বিদি	Standard temperature 25.0°C Temperature coefficient 3930ppm
Set	TCSET=25.0' C, 🖻 3930ppm 🖫 🕝	Set temperature correction
TCSET=25.0'C, 3930ppm 🖫 🖅	1 2 3 4	① Setting of temperature correction ② Setting of standard temperature
		③ Temperature coefficient ④Delimiter
	Standard temperature	
	00.0℃ to 99.9℃	
	Temperature coefficient	
	01000ppm to 19999ppm	

Command	Response			Contents	
Read out	RATIOSTD=딸 100.00mOHM,100.0%탈탈탈단		S _P S _P S _P C _R L _F	Read out the setting of ratio.	
RATIOSTD E	1	2	3	4	① Read setting ratio ② Standard resistance value
					③ Deviation ④ Delimiter
	RATIOSTD=	🖫 020.00 🖺 C	DHM,010.0%	65555CRF	Standard resistance 20.0Ω Deviation 10.0%
Setting	RATIOSTD=	🖫 100.00kOH	IM,010.0%	PSPSPC _R L _F	Set ratio
RATIOSTD=ኽ 100.00kOHM,100.0%ኽኽኽጬ	1)	2	3	4	① Setting of ratio ② Standard resistance value
					③ Deviation ④ Delimiter
	Standard re	sistance value			
	00.000m	OHM to 350.00)kOHM		
	Deviation				
	0.0 to 10	0.0%			

Command	Response	Contents	
Read	ZEROADJ=등 35.000mOHM 대한	Read the zero adjustment value.	
ZEROADJ?፹	1 2 3	① Read zero adjustment setting value ② Value of adjustment ③ Delimiter	
	ZEROADJ=际 1.2345 际 OHM 대파	Zero adjustment value 1.2345Ω	
Set	ZEROADJ=월 35.000mOHM 뎵厅	Set zero adjustment value	
ZEROADJ=딹 35.000mOHM 대파	1 2 3	① Setting zero adjustment value ② Value of adjustment ③ Delimiter	
	Setting value		
	🖫 30.000mOHM 🛛 🖺 300.00mOHM	30mΩ 300mΩ	
	3.0000 등 OHM 5 30.000 등 OHM	3Ω 30Ω	
	300.00 등 OHM 중 3.0000kOHM	300Ω 3kΩ	
	⑤ 30.000kOHM ⑤ 300.00kOHM	30kΩ 300 k Ω	
Set	ZEROADJ=SUCCESS 🖫 🗐	Set the displayed value to zero adjustment value.	
ZEROADJ 🖫 🗄	1 2 3	① Zero adjustment ② Response(success) ③ Delimiter	

Command	Response	Contents
Read	ADJUST=OFF 🖫 🖅	Read setting of zero adjustment.
ADJUST?ଭြြ	1 2 3	① Setting the zero adjustment ② ON or OFF ③ Delimiter
	ADJUST=ON ទីទី	Zero adjustment is effective
	ADJUST=OFF 🖫	Zero adjustment is invalid
Set	ADJUST=OFF C	Set the zero adjustment.
ADJUST=OFF Celt	1 2 3	① Setting the zero adjustment ② Set ③ Delimiter
	Set	
	NO BE	Enable zero adjustment
	OFF E	Disable zero adjustment

Command	Response	Contents
Read	AVERAGE=100 🖫 🖙	Reads the average number setting.
AVRAGE? CREF	2 2 3	① Read the value of averaging number ② Average No. ③ Delimiter
	AVERAGE= 5 10 GF	Average No. 10 times
	AVERAGE=55 1 SF	Average No. 1 time (No averaging)
Set	AVERAGE=100 🖫 🗐	Set the average No.
AVERAGE=100 CREF	2 2 3	① Setting the number of average ② Average number ③ Delimiter
	Range of the number	
	1 to 100	

Command	Response	Contents
Read	SAMPLING=MEDIUM 🖫 🖅	Read the setting of sampling.
SAMPLING?际厅	1 2 3	① Read the sampling type ② Sampling ③ Delimiter
	SAMPLING=SLOW	SLOW sampling
	SAMPLING=FAST Prove	FAST sampling
Set	SAMPLING=MEDIUM 🖫	Set the sampling.
SAMPLING=MEDIUM 🖫 🖅	1 2 3	① Setting of sampling ② Sampling ③ Delimiter
	Sampling	
	SLOW B	SLOW sampling
	MEDIUM	MEDIUM sampling
	FAST 🖫 🛱	FAST sampling

Command	Response		Contents
Set	WRITEMEMORY E SUCCESS	Save the setting value to memory.	
	1 2 3	(%Using this command, the setting	ng is saved in the memory, eventhough the power
		is shut down.)	
		① Write the memory ② Result	3 Delimiter
	Result		
	SUCCESS	Success on saving	
	ERROR 🖫 🛱	Fail on saving	
	ERR 5555	No online status	
		Saving contents	
		Measurement function	FUNCTION
		Measurement range	RANGE
		Comparator	HIGH LOW
		Zero adjustment operation	ADJUST
		Zero adjustment value	ZEROADJ
		Ratio setting	RARIOSTD
		Temperature correction setting	тс
		Sampling setting	SAMPLING
		Average No. setting	AVERAGE
		Buzzer setting	BUZZ
		Memory No. setting	MEM=CALL

Command	Response	Contents
Read	HOLD=ON SPERE	Read the status of sampling hold.
HOLD? CR EF	1 2 3	① Read response of hold ② Status of hold ③ Delimiter
	HOLD=ON FRF	HOLD ON (Sampling interrupted)
	HOLD=OFF	HOLD OFF (Sampling functions)
Set	HOLD=ON Ser	Set the status of sampling hold.
HOLD=ON EF	1 2 3	① Read response of HOLD ② Status of HOLD ③ Delimiter
	Setting	
	ON 🖫	HOLD ON (Sampling interrupted, then measured data is output.)
	OFF	HOLD OFF (Sampling status)

Command	Response	Contents
Read	RST=ON SpCRF	Read the status of reset.
RST? E	1 2 3	① Read the reset ② Status of reset ③ Delimiter
	RST=ON BE	RESET ON (Judgment output and display are OFF)
	RST=OFF 🖫 🖅	RESET OFF
Set	RST=ON BE	Set the status of judgment reset.
RST=ON Pr	1 2 3	① Read response of reset ② Status of reset ③ Delimiter
	Setting	
	OFF	RESET OFF
	ON 🖫	RESET ON (Judgment output and display are OFF)
		During HOLD ON, when RESET ON is transmitted, ONE SAMPLING HOLD works.

Command	Response	Contents	
Set	Equivalent to "DATA?" Command	During HOLD is ON, when READ is transmitted, one time sampling is done and	
READ SF		measured data is transmitted. Communication command RST=ON 🖫 is set in orde	
		to control the output of comparator during one time sampling.	

7. Analog output (Option)

The measured data of 3585 can be obtained by analog data output.

7.1 Output specifications

Output	Full scale 3V Load resistance more than $2k\Omega$						
	Output is obtained corresponding to resistance display or corrected resistance value						
	(interlocking with zero adjustment)						
Output voltage range	0.0 to 3.5V						
	When minus display: 0.0V						
	When over display: During OHM and OHM-RATIO: 3.5V						
	During TC and TC-RATIO: Maximum 4.0V (Over value)						
Conversion method	D/A conversion method (Resolution is approx. 0.3mV)						
Accuracy	One year accuracy $\pm 0.2\%$ F.S. (Defined by the range of 0V-3V)						
Output data	During OHM, OHM-RATIO and TEMP: Output resistance measurement value						
	During TC and TC-RATIO: Output correction value (Display value)						
Output cycle	Renewed with display cycle						
Response time	Time for the output to enter within the accuracy after renewed of the display:						
	Less than 3msec.						
Resolution	1/3000						

Range	Display	Analog output	Range	Display	Analog output
	0.000 mΩ	0.0000 V		0.00 mΩ	0.0000 V
22.0	10.000 mΩ	1.0000 V		100.00 mΩ	1.0000 V
30mΩ	24.999 mΩ	2.4999 V	300mΩ	249.99 mΩ	2.4999 V
30kΩ	30.000 mΩ	3.0000 V	300Ω 300kΩ	300.00 mΩ	3.0000 V
	35.000 mΩ	3.5000 V	300K32	350.00 mΩ	3.5000 V
	OVER	3.5000 V]	OVER	3.5000 V
	0.0000 Ω	0.0000 V			
	1.0000 Ω	1.0000 V]		
3Ω	2.4999 Ω	2.4999 V]		
3kΩ	3.0000 Ω	3.0000 V]		
	3.5000 Ω	3.5000 V]		
	OVER	3.5000 V]		

When the display is under 0 due to the zero adjustment function etc., the output of 0.0000V is obtained. In case of temperature correction, the corrected resistance value exceeds 35000 and is calculated till maximum 39999. In this case analog output with maximum 4.000V together with the display is obtained.

	Measurement	function	and	output data
--	-------------	----------	-----	-------------

FUNCTION Analog output	
TRMP	Resistance measurement value (OHM)
ОНМ	Resistance measurement value (OHM)
OHM-RATIO	Resistance measurement value (OHM)
T.C	Corrected resistance value (T.C)
TC-RATIO	Corrected resistance value (T.C)

8. BCD output (Option)


The measured data of 3585 can be obtained by BCD data output.

8.1 Output specifications

8.1.1 TTL output (-03)

The output of BCD data can be obtained with TTL level. Output method: BCD parallel code Positive logic


Output "L" level with logic "0". Output "H" level with logic "1".



8.1.2 Open collector output (-04)

The output BCD data can be obtained with open collector. Output method: BCD parallel code

Output "OFF" with logic "0", output "ON" with logic "1".



8.2 Connector pin array

Signal name	N	о.		Signal name	
0		1	26	4	
	1	2	27	5	
UNIT	2	3	28	6	UNIT
	3	4	29	7	
	1	5	30	1	
×10 ⁰	2	6	31	2	$\times 10^{1}$
*10	4	7	32	4	*10
	8	8	33	8	
	1	9	34	1	
×10 ²	2	10	35	2	×10 ³
×10-	4	11	36	4	~10
	8	12	37	8	
×10 ⁴ 1		13	38	POL	
OUTPUT ENA	BLE	14	39	OVER	
nHOLD		15	40		nSTROBE
DP1		16	41	1	
DP2		17	42	2	SEL
DP3		18	43	4	
DP4		19	44	2	×10 ⁴
	1	20	45	1	
FUNCTION	2	21	46	2	RANGE
FUNCTION	4	22	47	4	KANGE
	8	23	48	8	
INT. / nEXT	•	24	49	NC	(+V COM) ※
DATA COM		25	50		DATA COM

Connector in use: Amphenol 50 pin

% Pin No. 49 is allocated for +V COM in case of BCD option of PNP type (3585-04P).

8.3 Description of input and output signals

8.3.1 Output signal

Measured data output: 1,2,4,8 ($\times 10^{0}$ - $\times 10^{4}$)

The output of the measured data is obtained with parallel BCD codes. Note) During F sampling, 10^0 outputs.

Decimal point output

The output of decimal point is obtained corresponding with the measurement range as shown below.

Display	DP4	DP3	DP2	DP1
3.5000	0	1	1	1
35.000	1	0	1	1
350.00	1	1	0	1
100.0	1	1	1	0

Unit output

Unit is shown by the code as below.

Unit				Co	de			
onic	7	6	5	4	3	2	1	0
mΩ	1	0	0	1	1	0	0	0
Ω	1	1	1	1	1	1	1	0
kΩ	0	1	1	0	0	1	0	1
°C	1	0	1	1	0	0	0	1
%	1	1	1	0	0	0	0	0

Polarity output

τί σατράτ					
Polarity	POL				
Plus (+)	1				
Minus (-)	0				

Over output

Measurement	OVER
OVER	1
Not over	0
Error 1	1

Strobe output (STROBE)

When data is renewed, the output of "L" pulse is obtained.

Pulse width During S, M sample, 10ms

During F sample, 1 msec.

8.3.2 Input signal

Enable (OUTPUT ENABLE)

In case of "L" level, all the outputs except STROBE become "High Impedance".

Selecting output signals

The data output on BCD is selected by SEL1, SEL2 and SEL4.

Output data (SEL1, SEL2, SEL4)

During selecting data, make it sure that 3585 is in HOLD status.

SEL code	0	1	2	3	4	5	6	7
ОНМ	онм	ОНМ	ОНМ	онм	ОНМ	ОНМ	ОНМ	ОНМ
тс	Err3	Rt	t	Err3	Err3	Err3	Err3	RT
RATIO (OHM)	Err3	Rs	Rx	Err3	Err3	Err3	Err3	Х
RATIO (TC)	Err3	Rs	RT	Rt	t	Err3	Err3	Х
TEMP	TEMP	TEMP	TEMP	TEMP	TEMP	TEMP	TEMP	TEMP

Rt : Resistance at certain ambient temperature

RT : Corrected resistance (Calculated)

Rx : Resistance value

t : Ambient temperature

Rs : Standard resistance value

X : Ratio

Range input (RANGE)

When the input of the range code is done, make sure that the INT./nEXT. is at "L" level.

Range		Code						
Range	8	4	2	1				
AUTO	0	0	0	0				
30mΩ	1	0	0	0				
300mΩ	0	0	0	1				
3Ω	0	0	1	0				
30Ω	0	0	1	1				
300Ω	0	1	0	0				
3kΩ	0	1	0	1				
30kΩ	0	1	1	0				
300kΩ	0	1	1	1				

Function input (FUNC)

When the input of the function code is done, make sure that of INT./nEXT. is at "L" level.


Function	Code				
	8	4	2	1	
Resistance measurement	1	0	0	1	
Temperature measurement	1	0	0	0	
Temperature correction	0	1	0	0	
Ratio (OHM)	0	1	1	1	
Ratio (TC)	0	1	0	1	

HOLD input (nHOLD)


Sampling is performed at "H" level and the output of the measuring data is obtained sequentially. Sampling is stopped at "L" level and the BCD data, displayed value are retained.

External control input (INT./nEXT.)


The selection of function and range can be done at "L" level. But the control can't be done during HOLD mode. If MEM. CTRL is set as REMOTE, priority is given for the REMOTE operation.



Average No. = 1 time




Data select timing chart



If the select code is changed during sampling, the data after the end of the sampling is affected. If select code is changed during HOLD, output also change corresponding to the change of the code.

FUNCTION switching timing chart




9. Error display

Display	Name	Description
OVER	Over	The measurement is over range.
UNDER	Under	The measurement is under range.
ERR-CC or ERR-C	Source open	When SOURCE of the resistance measurement input is open or the resistance is large with the respect to the measurement value.
ERR1 or ERR-1	Error of temperature sensor	Confirm the connection of temperature sensor.
ERR-2	Calculation error	BCD option Exceeds the range of ratio calculation.
ERR-3	Select error	BCD option There is error in display select code.

Internal error code

If the hardware malfunction (ERR-HD) is detected, internal error code [ERR != ABCD] is shown on the display (OLED).


If the error is not solved even restart is done, the possibility of malfunction is high. Contact the distributor or the nearest office of TSURUGA ELECTRIC CORPORATION with the displayed error code for inspection or repairing.



Digit	Bit	Description
А	8,4,2,1	Reserved
В	8 4 2 1	Reserved Reserved Option function abnormal communication (ERR-HD) Abnormal internal communication (ERR-HD)
С	8 4 2 1	Abnormal ADC communication for resistance measurement (ERR-HD) Abnormal ADC communication for temperature sensor (ERR-HD) Protection action against over-voltage input Source open (ERR-CC)
D	8 4 2 1	Data select error of BCD (ERR-3) Calculation error (ERR-2) Temperature over (ERR-1) Measurement over (ERR-0)

10. Use in panel-mount


10.1 Assembly drawing




When the tester is used by panel-mounting, use the optional panel-mount bracket.

- 1 Remove the feet (4 parts) at the bottom of the tester.
- 2 Fix the panel-mount bracket to both side of the tester (M4×15flat head screw)
- ③ Insert the tester from the front of the panel and fix it to the panel with the fixing metal.
- Note: In case that the tester is installed to the chassis, utilizing the bottom screw taps of the testers, keep the length of screw at 6mm + thickness of chassis (mm).

10.2 External dimensions when fitted with panel-mount bracket





11. Maintenance

Cleaning

When the front panel or the case becomes dirty, wipe it with soft cloth. For heavy dirt, wipe it lightly with the soft cloth wetted with the water thinned by neutral cleaner. Do not use cleaners containing thinner, benzene, alcohol, acetone, ketone, ether or petroleum based detergent as they may deform or discolor the case.

Calibration

The regular calibration is needed to obtain correct measurement result within the range of specified accuracy.

The cycle of calibration depends on actual usage condition and environment of customers. We recommend for regular calibration at TSURUGA ELECTRIC CORPORATION depending on the condition of tester used by customers.

Transportation

During transportation of this tester, be careful of not to damage it by using proper packing box. The damage on transportation cannot be guaranteed. During repair request, attach the detail of trouble information.

12. Failure symptom

When the tester is supposed to be faulty, please check the following points before requesting the repair of it.

Symptom	Check points			
Although the power is turned	Is power supply connected to socket properly?			
ON, display does not light up.				
Kow is not operable	• Isn't the LOCK lamp lit up?			
Key is not operable.	Cancel the key lock referring to the section 3.5.			

Among error displays, internal error code might mean the malfunction.
 For repair, contact the nearest office of TSURUGA ELECTRIC CORPORATION.

13. Specifications

13.1 Model name

Model name	Description
3585- X	Without BCD data output, with RS-232C
3585-03	With BCD data output (TTL output) , with RS-232C
3585-04P	With BCD data output (Open collector PNP), with RS-232C
3585-04N	With BCD data output (Open collector NPN), with RS-232C
3585-07	With analog output (Voltage output 1 point), with RS-232C

13.2 Measuring range and accuracy

Resistance measurement

During SLOW, MEDIUM sampling

	1 5							
Range	30mΩ	300mΩ	3Ω	30Ω	300Ω	3 k Ω	30 k Ω	300 k Ω
Resolution	1μΩ	10μΩ	100μΩ	1mΩ	10mΩ	100mΩ	1Ω	10Ω
Current	DC300mA	DC100mA DC10mA DC1		C1mA DC10		L0μA		
Max. applied voltage	9mV	30mV	30mV 300mV		3V	300mV	3V	
Accuracy	Note 1	±(0.08% of rdg. +3digit)						
Temperature coefficient	Note 2	±(0.01% of rdg. +0.5digit) / ℃						
Open terminal voltage		DC6V max.						

Note 1) \pm (0.2% of rdg. +10digit) Note 2) \pm (0.02% of rdg. +1digit) Accuracy: One-year accuracy Defined at 23°C±5°C, 45 to 75%RH. Sampling During MEDIUM, 3 digits are added to the accuracy. Measurement resolution 1/30000

During FAST sampling

Range	30mΩ	300mΩ	3Ω	30Ω	300Ω	3kΩ	30kΩ	300kΩ
Resolution	10μΩ	100μΩ	$1 m\Omega$	$10 \text{m}\Omega$	$100 \text{m}\Omega$	1Ω	10Ω	100Ω
Current	DC300mA	DC100mA DC10mA DC1mA		1mA	DC1	0uA		
Max. applied voltage	9mV	30mV 300mV 3V			3V	300mV	3V	
Accuracy	Note 3		±(0.2% of rdg. +5digit)					e 5
Temperature coefficient	Note 4	±(0.01% of rdg.+ 0.1digit) / ℃				Not	e 6	
Open terminal voltage	DC6V max.							

Note 3) $\pm(0.3\%$ of rdg. ±15 digit) Note 4) $\pm(0.03\%$ of rdg. ±2 digit) Note 5) $\pm(0.5\%$ of rdg. ±20 digit) Note 6) $\pm(0.05\%$ of rdg. ±2 digit) Accuracy : One- year accuracy Defined at $23\%\pm5\%$, 45 to 75%RH. Measurement resolution 1/3000

Temperature measurement

Range	–19.9 to 199.9 ℃
Resolution	0.1 °C
Accuracy	±(0.2% of rdg. +0.2℃)
Temperature coefficient	±(0.02% of rdg. +0.02℃) / ℃
Sensor	Pt100 Ω 3 leads method (Resistance of lead: Less than5 Ω)
Current	1 mA

Accuracy : One-year accuracy Defined at 23°±5°C, 45 to 75%RH.

13.3 General specifications

Measurement method	4 terminal method (Front / Rear)							
Maximum allowable	Whole range 100V DC							
applied voltage Measurement cable resistance	SOURCE wires $30m\Omega$ range Less than 2Ω Others Less than 5Ω							
Display	OLED display							
	Display range							
	Function Display range							
	Resistance measurement-19999 to 35000, OVER, UNDER (-1999 to 3500 at FAST.)							
	TC calculation -39999 to 39999, OVER, UNDER							
	RATIO calculation -199.9 to 199.9, OVER, UNDER							
	Temperature measure- ment -19.9 to 199.9, OVER, UNDER							
Measurement range	30mΩ, 300mΩ, 3Ω, 30Ω, 300Ω, 3kΩ, 30kΩ, 300kΩ, AUTO							
	AUTO range Range up More than 35000 (FAST sampling More than 3500) Range down Less than 3000 (FAST sampling Less than 300)							
Over display	OVER UNDER							
Error display	ERR-1 When FUNCTION are TC, TC-RATIO and temperature measurement is over.							
ERR-CC display	When SOURCE of resistance measurement input is open, or SOURCE is larger than the measurement range. If FUNCTION is in TEMP mode, this error is not displayed.							
Internal error display	[ERR != ABCD] Error code is displayed in ABCD part, when internal error of the hardware is detected.							
Unit display	mΩ, Ω, kΩ, %, ℃							
Sampling rate	Resistance measurementSLOW5 times / sec.MEDUUM20 times / sec.FAST90 times / sec.							
	Temperature measurement 5 times / sec.							
Response speed 1	The required time to measure accurately (fixed range) from the input open to specimen connection.							
	Resistance measurementSLOWApprox. 400msMEDIUMApprox. 100msFASTApprox. 25ms							
	Temperature measurement Approx. 500ms							
Response speed 2	During the connection with the specimen and HOLD state, the time required from the measurement start to judgment output (fixed range).							
	Resistance measurement SLOW Approx. 210ms MEDIUM Approx. 57ms FAST Approx. 20ms							
	Temperature measurement							
	Approx. 500ms							

Noise rejection ratio	Normal mode More than 60dB (Max. applied voltage conversion) During sampling SLOW Common mode More than 100dB (Max. applied voltage conversion) During sampling SLOW
Parameter retention	Retained in the non-volatile memory Rewritable approx100,000 times Retention period approx. 10 years
Insulation resistance	Power supply terminal / Outer case More than DC500V 100M Ω Measuring terminals / Control terminals, RS-232C, Data output More than DC500V 10M Ω
Withstand voltage	Measuring terminals, Control terminals, RS-232C, Data output / Outer case 500V AC for 1 minute
	Power supply terminal / Outer case 1500V AC for 1 minute
Power supply voltage	AC100 to 240V 50 to 60Hz
Power supply voltage tolerance range	AC90 to 250V
Power consumption	17VA max.
Temperature	0 to 40℃
Humidity	Less than 80% RH (No condensation)
Storage temperature	-20 to 70°C, Less than 70%RH (No condensation)
Use environmental conditions	Indoor use Altitude: Less than 2000 m Overvoltage category: OVC II Pollution degree: 2 Allowable transient overvoltage of main supply: 1000V (1µs)
Protection grade	IP20 equivalent
Dimension	205(W) × 64(H) × 169(D) mm
Weight	Approx. 1kg
Accessories	Power supply cord for AC 100V1 pieceOperation manual1 copyUtility software (With RS-232C cable)1 sheet of CD
Option	Kelvin clip(Standard type: Model 5811-21C)Kelvin clip(Dual axis pin type: Model 5811-41)Kelvin clip(Coaxial pin type: Model 5811-42)Temperature sensor(Model 5803-11)Panel-mount bracket(Model 5811-31)Power supply cord for AC 200V(Model 5880-23-030)

```
This product is in conformity with the following standards ;
```

EN61010-1 2010

Pollution degree 2

Overvoltage category OVC II

Measurement category CAT 0

EN61326-1 :2013 Table2 *1

```
EN55011:2009+A1:2010
```

EN61000-4-2:2009

EN61000-4-3:2006+A1:2008+A2:2010

EN61000-4-4:2012

EN61000-4-5:2014

EN61000-4-6:2014

EN61000-4-8:2010

EN61000-4-11:2004

EN50581:2012

*1 In Industrial Locations

Influence	
Resistance measurement function	±(0.3% of rdg. +15digit)
Analog output function	±(0.3% of F.S.)

Configuration


Kelvin clip : 5811-21C BCD data output: BCD cable shielded type

13.5 Initial setting list (at the factory shipment)

	Item	Setting range	Initial setting ^{Note} (factory setting)	Memory (1 to 15)
Key lock		ON/OFF	OFF	_
Sampling		SLOW / MEDIUM / FAST	SLOW	_
Zero adjustment		ON/OFF	OFF	0
Zero adjustment value		0 to 35000	0	0
Buzzer setting		OFF / GO / HI / LO / NG	OFF	_
Buzzer volume		1 to 9	3	—
Buzzer ringing time		Continuous / 1 sec. / 5 sec.	Continuous	_
RS-232C	Communication speed	9600 / 19200 / 38400 (bps)	9600 (bps)	_
	Parity	None / Even / Odd	None	—
TC temperature coefficient		1000 to 19999 (ppm)	3930 (ppm)	0
TC standard temperature		0.0 to 99.9 (℃)	20.0 (°C)	0
Averaging function		1 to 100	1	—
Control of measurement current		ON/OFF	OFF	—
Memory No.		01 to 15	01	—
Function		OHM / TEMP / TC / OHM-RATIO / TC-RATIO	ОНМ	0
Range		30mΩ / 300mΩ / 3Ω / 30Ω / 300Ω / 3kΩ / 30kΩ / 300kΩ / AUTO	3Ω	Ο
Comparator H		-19999 to 35000	30000	0
Comparator L		-19999 to 35000	10000	0
Comparator range		30mΩ / 300mΩ / 3Ω / 30Ω / 300Ω / 3kΩ / 30kΩ / 300kΩ	3Ω	0
RATIO deviation		0.0 to 100.0	10.0	0
RATIO range		30mΩ / 300mΩ / 3Ω / 30Ω / 300Ω / 3kΩ / 30kΩ / 300kΩ	3Ω	0
RATIO standard resistance		0 to 35000	30000	0

Note: The setting can be reset to initial value by pressing both [F2] and [F3] simultaneously for more than 5 seconds.

13.6 External dimensions



Tsuruga Electric Corporation

Osaka Headquarters

1-3-23, Minamisumiyoshi, Sumiyoshi-ku, Osaka, Japan 〒558-0041 TEL 81-6 -6692-6700, FAX 81-6 -6609- 8115 E-mail: ft.info@tsuruga.co.jp

Yokohama Office

1-29-15, Shinyokohama, Kohoku-ku, Yokohama, Kanagawa, Japan \mp 222-0033

Tokyo Office

5-25-16, Higashigotanda, Shinagawa-ku, Tokyo, Japan 〒141-0022

Nagoya Office

Sun Park Higashi Betsuin Bld. 2F 5-19, Oicho, Naka-ku, Nagoya, Aichi, Japan 〒460-0015

Osaka Plant 1-3-23, Minami Sumiyoshi, Sumiyoshi-ku, Osaka, Japan 〒558-0041

Shiga Plant 122, Kawasaki-Cho, Nagahama, Shiga, Japan 〒526-0846

www.tsuruga.co.jp