

# LARGE STROKE ELECTRONIC INDICATORS

DATA  
OUTPUT


2117-100PE/1001PE




- Button function: on/off, zero, mm/inch, data preset, tolerance, change measuring direction, max./min./TIR measurement, absolute/incremental measurement
- Keep preset data and tolerance data in memory after restart
- CR2032 battery, automatic power off
- Maximum measuring force: .719lbf
- Data output
- Optional accessory: data output cable (part no. **7315-50M**, **7302-40M**, **7305-40M**), backs (page 74), contact points (page 73)



2117-100E



2117-100PE




Resolution .0005"/0.01mm

| Part No.   | Range    | Accuracy | Hysteresis | Remark                   |
|------------|----------|----------|------------|--------------------------|
| 2117-100E  | 4"/100mm | ±.0015"  | .0005"     | lug back                 |
| 2117-100PE | 4"/100mm | ±.0015"  | .0005"     | flat back, with lift cap |

Resolution .00005"/0.001mm

| Part No.    | Range    | Accuracy | Hysteresis | Remark                   |
|-------------|----------|----------|------------|--------------------------|
| 2117-1001E  | 4"/100mm | ±.00030" | .0001"     | lug back                 |
| 2117-1001PE | 4"/100mm | ±.00030" | .0001"     | flat back, with lift cap |



spindle lift knob is included

