

PCE Americas Inc.
 711 Commerce Way
 Suite 8
 Jupiter
 FL-33458
 USA
 From outside US: +1
 Tel: (561) 320-9162
 Fax: (561) 320-9176
info@pce-americas.com

PCE Instruments UK Ltd.
 Units 12/13
 Southpoint Business Park
 Ensign way
 Hampshire / Southampton
 United Kingdom, SO31 4RF
 From outside UK: +44
 Tel: (0) 2380 98703 0
 Fax: (0) 2380 98703 9
info@pce-instruments.com

www.pce-instruments.com/english
www.pce-instruments.com

Technical Specification Air Humidity Meter PCE-THB 38

Measurement ranges

-Temperature	0 to 50°C
-Relative air humidity	10 to 95% r.h.
-Barometric pressure	10 to 1100 hPa (mbar)
-Dew point temperature	-25 to 49°C

Resolution

-Temperature	0.1°C
-Relative air humidity	0.1% r.h.
-Barometric pressure	0.1 hPa to 1000 hPa (but 1 hPa)
-Dew point temperature	0.01°C

Accuracy

-Temperature	±0.8°C
-Relative air humidity	±3% of reading or ±1% (<70% r.h., but ±3% r.h.)
-Barometric pressure	±1,5 hPa to 1000 hPa, but ±2 hPa
Operating temperature	0 to 50°C

Power	4 AAA batteries
Dimensions	120 x 40mm
Weight (with batteries)	160g