


GRAIN MOISTURE METER (Model : GMK-303)

1. The names of each part



2. Before Measurement

- Open the lid in the bottom of the Instrument and place 1.5V batteries 4EA into battery compartment.
- [303] sign displays on LCD for 2~3 sec. and then disappears.

3. Measurement

- Fill Sample Tray with a Sample by using Spoon (with Tweezers).
- Put Sample Tray into the instrument.
- After turning Grinding Handle right to the end, choose the same Grain Select Button as a Sample.
- Press Measure Button, and then the number of times & moisture content display on LCD.

[Notice]

- The Instrument turns off automatically approx. 1 min. later when there is no other operation.
- When [] displays, please change batteries.
- When the moisture content in a Sample is out of Measuring Ranges, [Er H] or [Er L] displays.

4. Average Data

- Average data (up to 9 times) is available by pressing Average Button.

[Notice]

- When you want to get average data, please press Average Button before measurement to erase the previous data.
- The instrument turns off automatically when pressing Average Button two times continuously.

5. Keeping

- Keep the Instrument in a cool place.
- Clean the Instrument after measurement.

6. Battery



In case of no use for a while, please remove batteries.

7. Warranty

- The manufacturer grants a total replacement of warranty of 12 months from the date of purchase.
- In case of wrong use, abuse or misuse, warranty is not granted.

ACCESSORIES



Sample Tray



Spoon with Tweezers



Brush



Carrying Case

