


FLOUR MOISTURE METER

MODEL GMK-308



■ BEFORE MEASUREMENT

- 1) Open the cap of 'Test Cell' and make sure that it is clean and empty.
※ Do not touch insert pin with hands.
- 2) With a spoon, fill the 'Test Cell' tightly with testing sample.
- 3) Close the cap of 'Test Cell' by turning it left.
- 4) Watching insert holes carefully, place the 'Test Cell' on the instrument.

■ MEASUREMENT

- 1) Press 'Measure Button', and measurement result appears on LCD soon
- 2) Average data is available by pressing 'Average Button' (up to 9 times).
- 3) Power is off by pressing 'Average Button' twice.

■ IMPORTANT

- 1) Before every measurement, clean test cell with cleaning brush.
- 2) When the sample is out of measuring range, 'Err' sign appears.
- 3) Do not store the instrument at damp place.
- 4) In case of no use for a while, make sure to remove batteries.
- 5) The manufacturer grants a total replacement warranty of 12 months from the date of purchase.
- 6) Warranty will not be granted in case of wrong use, abuse or misuse.

G-WON HITECH CO., LTD.

WOOLIM E-BIZ. CENTER 310
#170-5, GURO-DONG, GURO-GU,
SEOUL, KOREA(152-769)
Tel : 82-2-2108-1646(DIR.)
Fax : 82-2-2108-1649
E-Mail : g-won@g-won.co.kr

Other Instruments

- | | |
|-------------------------|------------------------|
| ■ Digital Refractometer | ■ Grain Moisture Meter |
| ■ Wood Moisture Meter | ■ Digital Salt Meter |
| ■ Coffee Moisture Meter | ■ Soil Moisture Meter |
| ■ Tea Moisture Meter | ■ Fruit Acidity Meter |

