

SEAWATER SPECIFIC GRAVIMETER (MODEL: GMK-500AC)

DESCRIPTION OF THE INSTRUMENT



BEFORE MEASUREMENT

- 1) WITH BATTERY REMOVER, OPEN THE LID OF BATTERY COMPARTMENT (BACK SIDE).
- 2) WATCHING +/- POLES CAREFULLY, PLACE BATTERY 9V 1EA IN IT.
- 3) IF 'CAL' SIGN APPEARS ON LCD AND DISAPPEARS, THE UNIT IS READY TO MEASURE IN NORMAL CONDITION.(AUTOMATIC CALIBRATION).
- 4) WIPE 'SAMPLE WELL' WITH CLEAN WATER & TISSUE.

MEASUREMENT

- 1) PLACE SOME TEST SAMPLES ENOUGH TO FILL 'SAMPLE WELL'.
- 2) PLACE 'LIGHT COVER' ON THE SAMPLE WELL.
- 3) PRESS 'MEASURE' BUTTON, AND SPECIFIC GRAVITY OF SEAWATER APPEARS ON LCD FOR ABOUT 2 MINUTES. (# WHEN THE TEST SAMPLE IS OUT OF MEASURING RANGE, 'Er H' SIGN APPEARS).

IMPORTANT

- 1) BEFORE EVERY MEASUREMENT, CLEAN THE SAMPLE WELL WITH WATER & TISSUE.
- 2) WHEN LOW BATTERY SIGN APPEARS, REPLACE THE BATTERY SHORTLY.
- 3) DON'T STORE THE UNIT AT DAMP PLACE.
- 4) IN CASE OF NO USE FOR A LONG TIME, MAKE SURE TO REMOVE THE BATTERY.
- 5) WARRANTY PERIOD IS 12 MONTHS AFTER THE DATE OF PURCHASE.
- 6) IN CASE OF WRONG USE, ABUSE OR MISUSE, WARRANTY WILL NOT BE GRANTED.

G-WON HITECH CO., LTD.

WOOLIM E-BIZ. CENTER 310
#170-5, GURO-DONG, GURO-GU,
SEOUL, KOREA(152-769)
Tel : 82-2-2108-1646(DIR.)
Fax : 82-2-2108-1649
E-Mail : g-won@g-won.co.kr

Other Instruments

- | | |
|------------------------|-------------------------|
| ■ GRAIN MOISTURE METER | ■ COFFEE MOISTURE METER |
| ■ DIGITAL SALT METER | ■ TEA MOISTURE METER |
| ■ FLOUR MOISTURE METER | ■ FRUIT ACIDITY METER |
| ■ SOIL MOISTURE METER | ■ WOOD MOISTURE METER |

