

DT-3808

Light Meter with PC Interface DT-3808 light meter provide accurate display light level in terms of Foot Candles (FC) or LUX over wide range. Just turning the Function Switch to select the "lux" scale and setting the range to desired range, then removing the photo detector to light source in a horizontal position and reading the illuminance norminal from the LCD display. When the measurement is completed, replace the photo detector fro



completed, replace the photo detector from the light source.

| Features |
|--|
| 4000 Counts LCD dual display with timer function |
| Auto Ranging |
| Max./Min. and Data Hold |
| Auto Power Off |
| Low battery indication |
| User selectable FC/Lux |
| USB interface |
| Capacity for data logging (99 readings) |
| Total accuracy: for C.I.E standard illuminate A(2856K) |

| Specifications | |
|----------------|----------------------|
| Max Range | 400,000Lux |
| Accuracy | ±5%±10d(<10,000Lux) |
| | ±10%±10d(>10,000Lux) |
| Max Resolution | 0.1Lux/0.01Fc |
| Measuring rate | 1.5 times/second |
| Photo Detector | 115mm x 60mm x 27mm |



Light Meter with PC Interface

DT-3808 light meter provide accurate display light level in terms of Foot Candles (FC) or LUX over wide range. Just turning the Function Switch to select the "lux" scale and setting the range to desired range, then removing the photo detector to light source in a horizontal position and reading the illuminance norminal from the LCD display. When the measurement is completed, replace the photo detector from the light source.



Size(HxWxD): 160mm x 58mm x 27mm Weight: 280g

FC

Accessories : 9V battery, Photo Detector and USB cable, software, Carrying case and Gift box.