## **DIGITAL HIGH PRECISION HEIGHT GAGES**






power supplied by charge pal

data transmitted to Excel without software

- High stability, high precision, high response speed (5000mm/s)
- High brightness LED display
- Ceramic base flatness: 1µm



| Code     | Range  | Resolution  | Accuracy<br>(20°C) | Measuring<br>force | Output | Power<br>suppy                      |
|----------|--------|---|--------------------|--------------------|--------|-------------------------------------|
| 1155-505 | 0~50mm | 0.5µm/0.00002"<br>(can switch to:<br>1µm/0.00005")  | 1.5µm              | 1.0~1.5N           | USB    | 5V/1A<br>(adapter or<br>charge pal) |
| 1155-510 | 0~50mm | 0.1µm/0.000005"<br>(can switch to:<br>1µm/0.00005") | 1μm                | 1.0~1.5N           | USB    | 5V/1A<br>(adapter or<br>charge pal) |

## STANDARD DELIVERY

| Main unit | 1 pc |
|-----------|------|
|-----------|------|

## **OPTIONAL ACCESSORY**

| Contact point                              | code <b>6282</b> |  |
|--|------------------|--|
| Charge pal                                 | 1155-5-POB       |  |
| Data output cables (including foot switch) | 1155-5-FOS       |  |