

Cat.No.1018-00

Thermohygrometer

Model Clean Meter



Indicates temperature and humidity with two pointers. You can monitor the outbreak points for influenza viruses, ticks, mold, and food poisoning from where the pointers cross on the Dial. A useful item for a clean and pleasant environment.

Specifications

Measuring range	Temperature -10 to 40°C Humidity 20 to 100%RH
Accuracy	Temperature $\pm 2^{\circ}\text{C}$ Humidity $\pm 5\%\text{RH}$ (15 to 25°C, 40 to 70%)
Dimensions and weight	(W)180 x (H)180 x (D)35 mm approx. 260g
Box contains	10 x 4 carton(s)